

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

USNRC REGION II  
ATLANTA, GEORGIA

September 4, 1980

SEP 8 AIO: 12

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-19 - RII:JPO 50-327,  
-328, -390, -391, -438, -439, 566, -567 SEQUOYAH, WATTS BAR, BELLEFONTE,  
AND YELLOW CREEK NUCLEAR PLANTS

In response to your letter dated July 31, 1980, which transmitted IE  
Bulletin 80-19 on mercury wetted relays, we have completed the review  
required by the bulletin. We have determined that mercury wetted relays  
are not used in the reactor protection systems at Sequoyah, Watts Bar,  
Bellefonte, or Yellow Creek Nuclear Plants.

As requested in your letter dated July 31, 1980, we estimate that TVA  
employees expended 40 manhours in conducting the review and preparing the  
correspondence required to comply with this bulletin.

If you have any questions, please get in touch with D. L. Lambert at  
FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*L. M. Mills*

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Division of Reactor Operations Inspection  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

8009120679