

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

February 26, 1981

TELEPHONE AREA 704
373-4083

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. B. J. Youngblood, Chief
Licensing Projects Branch No. 1


Re: McGuire Nuclear Station
Docket Nos. 50-369, 50-370

Dear Mr. Denton:

My letter of October 14, 1980 outlined the results of Duke Power Company's review of the McGuire design related to resetting of plant equipment upon reset of the Engineered Safety Features (ESF) actuation signal. In that letter in Item 6, we identified four areas where modifications would be made, two to be made prior to fuel loading and two to be made after startup.

Please be advised that all modifications identified in my October 14, 1980 letter have been completed. If you have further questions regarding this matter, please advise.

Very truly yours,



William O. Parker, Jr.

GAC:pw

cc: T. J. Donat
Senior Resident Inspector
McGuire Nuclear Station

*Boo
S/O
ADD: C E
R. Stevens 10*

P

8703030751