

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

84 JUN 25 12:42 June 21, 1984  
WBRD-50-391/82-04

U.S. Nuclear Regulatory Commission  
Region II  
Attn: Mr. James P. O'Reilly, Regional Administrator  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNIT 2 - FOAM SEALS IN MECHANICAL PIPE  
SLEEVES - WBRD-50-391/82-04 - NINTH INTERIM REPORT FOR UNIT 2

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on December 4, 1981 in accordance with 10 CFR 50.55(e) as NCR WBN CEB 8118. Interim reports were submitted on January 8, and March 1, 1982. Our final report on this item was submitted on April 14, 1982. As discussed with Inspector Crlenjak on June 4 and Inspector D. Quick on August 12, 1982, TVA's final report contained information which, in subsequent investigations by TVA, was found to be inaccurate. Additional interim reports were submitted on August 18, 1982 and February 8, June 21, and September 26, 1983. Our final report for unit 1 and eighth interim report for unit 2 was submitted on January 3, 1984. This constitutes our ninth interim report for unit 2. We expect to submit our next report for unit 2 on or about November 1, 1985.

Due to concentrated work efforts on unit 1, the measurement of the pipe movements at all unit 2 sleeves has not been completed. TVA will provide more information in our final report for unit 2.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

8407020379 840621  
PDR ADOCK 05000391  
S PDR

*L. M. Mills*  
L. M. Mills, Manager  
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339