

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA TENNESSEE 37401

400 Chestnut Street Tower II

2 11 89 August 19 1982

WBRD-50-390/82-18

WBRD-50-391/82-17

U.S. Nuclear Regulatory Commission

Region II

Attn: Mr. James P. O'Reilly, Regional Administrator

101 Marietta Street, Suite 3100

Atlanta, Georgia 30303

Dear Mr. O'Reilly:

**WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - HVAC REGISTER DAMAGE
- WBRD-50-390/82-18, WBRD-50-391/82-17 - THIRD INTERIM REPORT**

The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on January 25, 1982 in accordance with 10 CFR 50.55(e) as NCR 3884R. Interim reports were submitted on February 25 and May 11, 1982. Enclosed is our third interim report.


TVA has determined that the procurement specifications were adequate and will install field-fabricated balancing devices to replace the inoperable registers.

TVA is continuing to investigate actions to prevent recurrence. We expect to provide our next report by September 8, 1982.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

1027