

TENNESSEE VALLEY AUTHORITY

USNRC REGION II
ATLANTA, GEORGIA
CHATTANOOGA, TENNESSEE 37401

1630 Chestnut Street Tower II

84 DEC 19 P 1:27

December 14, 1984

WBRD-50-391/82-02
WBRD-50-391/82-54
WBRD-50-391/82-56
WBRD-50-391/82-68
WBRD-50-391/82-69
WBRD-50-391/82-74
WBRD-50-391/83-18
WBRD-50-391/83-19
WBRD-50-391/83-20

U.S. Nuclear Regulatory Commission
Region II

Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNIT 2 - PROGRAM DEFICIENCY: ALTERNATELY
ANALYZED PIPING - FOURTH COMBINED INTERIM REPORT FOR UNIT 2

Our submittal dated November 24, 1982 on the subject alternate analysis program deficiency combined, for reporting purposes, the following 10 CFR 50.55(e) items: NCR WBN SWP 8160 (WBRD-50-390/82-02, -391/82-02), NCR WBN SWP 8220 (WBRD-50-390/82-57, -391/82-54), NCR WBN CEB 8218 (WBRD-50-390/82-59, -391/82-56), NCR 4164R (WBRD-50-390/82-73, -391/82-68), NCR WBN SWP 8231 (WBRD-50-390/82-74, -391/82-69), and NCR WBN SWP 8238 (WBRD-50-390/82-78, -391/82-74).

Subsequent to the November 24, 1982 submittal, three related nonconformances were identified and determined to be reportable under 10 CFR 50.55(e). These NCRs were initially reported to NRC-OIE Region II as NCRs WBN SWP 8264 (WBRD-50-390/83-19, -391/83-18), WBN SWP 8306 (WBRD-50-390/83-20, -391/83-19), and WBN SWP 8311 (WBRD-50-390/83-21, -391/83-20). NRC-OIE Region II was notified that these NCRs would be reported as part of the program deficiency and thus were addressed in the April 27, 1983 submittal on the program deficiency.

A final report for unit 1 and third combined interim report for unit 2 was submitted on October 14, 1983. This report constitutes our fourth combined interim report for unit 2. We expect to submit our next report for unit 2 on or about February 1, 1985.

8501150408 841214
PDR ADOCK 05000391
S PDR

An Equal Opportunity Employer

OFFICIAL COPY

110 TE 27

U.S. Nuclear Regulatory Commission

December 14, 1984

TVA is still in the process of investigating the subject deficiencies in order to determine to what extent they apply to WBN unit 2. More information will be provided for this item in the next report.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. A. Dornier

for J. W. Hufham, Manager
Licensing and Regulations

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339