August 12, 2008 (11:00am)

Cornerstone Rollup
Program: Flow Accelerated Corrosion
Plant: VERMONT YANKEE
Quarter: 3rd

Last Update:

10/03/2006

Monitored Parameter	Criteria	Color	Total Quality Points		Comments	8	
Overall Program	Green: 110 – 120 White: 85 – <110 Yellow: 75 – <85 Red: <75	Clear Clear	110				
Program Personnel Cornerstone	This cornerstone provides an indication of whether or not we have the right personnel with the right skills in the right positions to manage the program.	PasGrenn in	26				
Program Infrastructure Cornerstone	This cornerstone provides an indication of the quality of the infrastructure in place to support the program. Infrastructure includes necessary equipment, program procedures, etc.	White	21	Corrective Action CA tasks develop 02699)			LO-
Program Implementation Cornerstone	This cornerstone provides an indication of how well we execute programmatic requirements.	ProGrammer	33				
Equipment / Related Plant Performance Cornerstone	This cornerstone provides an indication of the health of the components (or other performance indicators impacting plant performance) monitored by the program.	S G(Bc)	30				

Rev. 0

Date: 04-25-06

Witness/Panel REJECTED

Program: Flow Accelerate	d Corrasion		İ		
		VERMONT	YANKEE		
	Quarter:			· · · · · · · · · · · · · · · · · · ·	
	Last Update:				
					
	Cornerstone Rollup			Selec	t Cornerstone Trending
	Green: 26-30 cornerstone quality points	Gleen		1	Up
	White: 20-25 cornerstone quality points			1	Siaple: 1977
	Yellow: 15-19 cornerstone quality points		,	↓	Down
	Red: <15 cornerstone quality points				
Monitored Parameter	Criteria	.Result	Relative Value	Quality Points	Comments
Staff Qualification and	Green - Incumbent fully qualified with 3 years or	Acheen II	3	9	Current FAC Program Owner
Experience	more experience within the program.				(JCF) and backup (TO'C) have
	White - Incumbent fully qualified.				more than 3 years of FAC
•	Yellow - Incumbent in partially qualified (> or =				experience. Also, new enginee
	25% complete with qualification card.)			٠.,	in Code Programs (R.Lane).
•	Red - No incumbent or unqualified incumbent <				
	25% complete with qualification card.				
Bench strength	Green - Backup fully qualified with 3 years or	Green	1.	3	Backup is fully qualified with
	more experience within the program.				more than 3 years of FAC
	White - Backup fully qualified.				experience.
	Yellow - Backup in partially qualified (> or =			<u> </u>	
	25% complete with qualification card.)			·	
	Red – No backup or unqualified backup < 25%			}	
TI-I (CLICOMODICS	complete with qualification card. Green: Completed CHECWORKS FAC BASIC		1	-3	Program owner and backup ha
Training (CHECWORKS BASIC and ADVANCED	and ADVANCED Training.		1	3	completed CHECWORKS
Training)	White - Completed CHECWORKS FAC BASIC			1	training prior to split to Basic &
raumg)	Training and Qualification Card.			İ	Advanced. Both individuals have
	Yellow - Incumbent is partially qualified (≥ 25%			1	more than 12 years experience
	complete with CHECWORKS Training and				using CHECWORKS.
	Qualification Card)				doing of Lott of Ito.
	Red - Unqualified		-		
Industry Participation	Green - Committee membership, other voting	. Green	1	3	Participation in EPRI CHUG

Monitored Parameter	Criteria	Hesult	Relative Value	Quality Points	Comments
(Includes any within the ENS region)	White – Active participation within industry within the past year with active sharing across sites.				(Voting and Advisory Committee access through single Entergy contact R.Jackson/RBS) Program
	Yellow – No active involvement over the past year but active involvement within the past two years.				owner member of CHUG Long Term Planning Group
<u> </u>	Red - Inactive participation.			l	

4
Ţ
\mathcal{C}
$\overline{}$
u
ά
4
ĸ
N

Monitored Parameter	Criteria	нesult	Relative Value	Quality Points	Comments
Program Human .	Green - No HPEs over the past 12 months.	- Green	1	3	No FAC Program related human
Performance (Does not	White - 1 HPE over the past 12 months .		2.		performance error clock resets
include errors in	Yellow - 2-3 HPE over the past 12 months				in the past 12 months.
implementation)	Red – 4 or more HPE over the past 12 months				
Owner Availability	Green - Supervisor determines sufficient time is	Yellow	- 2	2	Problems identified with timely update of
	available for proactive program improvements				CHECWORKS models (CR-2006- 2699). CHECWORKS models and wear
	White - Supervisor determines sufficient time			Ĭ	rata analyses updated with all previous
	allotted for necessary program up keep.				inspection data in 3rd QTR 2006.
	Yellow - Supervisor determines insufficient time				Corrective Action Plan to prevent similar issues with remaining FAC program
	allotted for long term program up keep.				tasks developed 10/2/06.
	Red – Supervisor determines insufficient time allotted for immediate program needs.				
Peer Interaction (Does not	Green – 2 or more peer	Green	1	3	Entergy FAC Program fleet call
include PI worksheet	White - 1 peer meeting/teleconference quarterly				held on 7/26/06.
development)			•		EPRI CHUG Long Term
·	Yellow - less than full regional participation for			· ·	Planning Group Telcons.
·	the meeting/teleconference within the quarter.			1	
1	Red - Did not participate in peer				· 1

Program: Flow Accelerated Cor	rosion				
		VERMONT Y	ANKEE		
	Quarter;				
	Last Update:				
					<u> </u>
	Cornerstone Rollup			Sele	ect Cornerstone Trending
	Green: 26-30 cornerstone quality points	White	٠.	A 100 A 100	Up
	White: 20-25 cornerstone quality points				Station State
	Yellow: 15-19 cornerstone quality points			1	Down
	Red: <15 cornerstone quality points	<u> </u>		, , , , , , , , , , , , , , , , , , ,	
Monitored Parameter	Criteria	Result	Relative Value	Quality Points	Comments
Program Infrastructure CRs	Green - (identified within the last two	Green4	. 2	. 6	No program infrastructure related
(Internal) and External Findings.	quarters)			1	CRs this operating cycle. For 3rd
(External findings are defined as	No A or B level CR AND				Otr. participated in development
conditions found by independent	No external findings AND				of new EN standard FAC
oversight agencies resulting in A	< 4 C level CRs			1	program procedure EN-DC-315.
or B level CRs. Oversight	White - (identified within the last two quarters)			ì	EN-AD-101 RAF forms complete
agencies include QA [audits],					Minimal impact to VY program to
INPO, and NRC.)	No A level CR; AND				adoption of EN-DC-315.
	No external findings; AND			1.0	
·	< 3 B level CRs; and AND				
•	< 6 total B and C level CRs				
	Yellow - (identified within the last two		• • •		
	quarters)				
	No A level CRs AND		1	1	
	Any of the following			}	
	3-4 B level CRs OR		1	·	
·	5-15 total B or C level CRs OR		·		
	1 external finding.			İ	
	Red - (Any of the following within the last two				
•	quarters)			1	
	Any A level CR OR				·
	5 or more B level CRs OR			1	
	15 or more total B or C level CRs OR				
•	2 or more external findings OR			1	· .
15	Any NRC violation.			1	j

Monitored Parameter	Criteria	Result	Relative Value	Quality Points	Comments
Long Range Plan (plan for items requiring significant resources such as outage support	Green – Long range plan in place covering the next 5 years, updated within the last year and with budgetary items IDd in the long range	White	1.	2	Completed transition to ENN standard FAC program this cycle. No formal long range plans have
equirements, scheduled	budget.	٠,٠		,	been developed for ENN FAC programs to date. However, VY ha
assessments, program updates,	White - Long range plan in place covering the				just implemented 120% power
ritical infra-structure upgrades,	next 3 years, updated within the last year and				uprate. To assess effects on piping
and scheduled component	with budgetary items IDd in the long range				the number of inspection locations
eplacements.)	budget. Yellow - Foreseeable issues requiring				will be increased approx 50% over
	significant resources within the 1 to 3 years				previous outages for the next 3 refueling outages. Additional
	not included in the long range plan.	٠.			planning for small bore piping with
	Red - Foreseeable issues requiring significant	,		,	respect to recommended
	resources within the next 12 months not	'	į		replacements will be performed up
:	included in the long range plan.	٠.	ļ		completion of VY-RPT-05-00013.
•	Yellow or Red can be upgraded once		·		
•	adequate plans are in place including funding in budget.				
Open Action Items (Includes ALL	Green - No due date extensions and no items	Yellow	1	1	LO-VTYLO-2003-00327-CA2
CR-CAs, ER post-action items	greater than 6 months old.		1	.	LO-VTYLO-2003-00327-CA4
and LO-CAs.)	White - No action items greater than 1 year old.				LO-VTYLO-2003-00327-CA6 LO-VTYLO-2004-00004-CA4
	Yellow - Any action item greater than 1 year old.				LO-VTYLO-2004-00399-CA1 LO-VTYLO-2005-00215-CA1
	Red – 2 or more CR-CAs and/or ER post-				(Listed LO-CAs are tracked under
	action items (excluding LOs action items)		! .		Corrective Action Plan for CR-200
	greater than 1 year old.				02699)
Document / Database Health	Green - No outstanding changes to the	White	3	6	CHECWORKS models and we
	program documents (or databases) which			1	rata analyses updated with all
•	impact program performance (e.g. missed		1	l	previous inspection data in 3rd
	commitment, surveillance past due); no outstanding changes for enhancements		1		QTR 2006. (CR-2006-2699)
	greater than two quarters old; and use of best-		1	1	
	in-practice database or tracking software.	· .	ļ		
	In-practice database of fracking software.	} :			
	White - No outstanding changes to the			Ì	
	program documents (or databases) which		}		
	potentially impact program performance.	1	1	l	
	Yellow - Database compatibility issues OR		1	!	
	any outstanding issues with the potential to			1	1 -
•	impact program performance.				
	Red - Any procedural or database issue				
	which directly impacted program performance			1.	
S	within the past quarter.				<u> </u>

Monitored Parameter	Criteria	Result	Relative Value	Quality Points	Comments
Test Equipment	Green - Best-in-practice, functional and	Green -	2	4	Test Equipment (Parametrics
•	properly calibrated equipment in the proper				UT/Data loggers) used during
	numbers to get the job done efficiently.		·	·	refueling outages is the same as
· .	White - Equipment functional and properly calibrated in the proper numbers to get the job		·		used in the ISI Program.
	done efficiently.				Equipment is tested and calibrated per NDE procedures
	Yellow - Test Equipment Obsolescence		:		prior to each refueling outage.
• .	Issues OR Test equipment failure (which did				prior to each referring outage.
	not impact scheduled or required program				
	implementation activity) within the last quarter				
	OR Insufficient equipment available				
•	(functional and properly calibrated) for				· ` ·
	efficient program implementation.) .	
	Red - Equipment unavailable to support				
	scheduled or required program			.	· ·
Benchmarks/Self-Assessments	Implementation activity. Green: Benchmark or Self-Assessment	White		<u> </u>	Non CA sebaduladás
	within the last 2 years.	Avrille		2	Next SA scheduled for completion 12/08/06 (LO-VTYLO-
	White: Benchmark or Self-Assessment within	} .			2003-00327-CA2)
	the last 3 years.			· .	2000-00021-0A2)
·	Yellow: Benchmark or Self-Assessment	1			
	within the last 4 years.				
	Red: No Benchmark or Self-Assessment				
	within the last 4 years.		<u> </u>		
		ļ	 		
	<u> </u>		Totals	21	<u> </u>

Implementation Perfor	rosion	<u> </u>	 		
Program, Flow Accelerated Cor		VERMONT	VANKEE	······································	
	Quarter:		MAKEE		
	Last Update:		 		
	Zuot opatio.	10/00/2000			
					
	Cornerstone Rollup	1		Select	Cornerstone Trending
	Green: 26-30 cornerstone quality points	S. All Services			Up _a
	White: 20-25 cornerstone quality points				Line in spicials with the
•	Yellow: 15-19 cornerstone quality points			1.	Down
	Red: <15 cornerstone quality points		·		
Monitored Parameter	Criteria	Result	Relative Value	Quality Points	Comments
Program Implementation CRs	Green - (identified within the last two quarters)	Green	1	3	CR-2006-2699 8/30/06
(Internal) and External Findings.			,		Level C, Identified
(External findings are defined as	No A or B level CR AND				CHECWORKS models
conditions found by independent	No external findings AND		ľ		were not updated in a
oversight agencies resulting in A-	< 4 C level CRs				timely manner. Problems
or B level CRs. Oversight	White - (identified within the last two quarters)				identified with timely
agencies include QA [audits],	100 110		·		update of CHECWORKS
INPO, and NRC.)	No A level CR; AND				models (CR-2006-2699)
	No external findings; AND < 3 B level CRs; AND				CHECWORKS models
. ,	< 6 total B and C level CRs				and wear rata analyses
	Yellow – (identified within the last two quarters)				updated with all previous
	1 ellow = (identified within the last two quarters)				inspection data in 3rd QTR 2006. Corrective
	No A level CRs AND			•	Action Plan to prevent
	Any of the following				similar issues with
	1 ANT OLD DIOMETHIC	DESCRIPTION OF THE PROPERTY OF THE PERSON OF	a . I		. I
•					remaining FAC program
•	3-4 B level CRs OR 5-15 total B or C level CRs OR				remaining FAC program tasks developed 10/2/06.

4	c	ı
t	1	į
(_)
ς	_)
ζ	J	٤
٠(×)
	С	١
į		j
•	•	٦

		•			
			٠		
Monitored Parameter	Criteria	Result	Relative Value	Quality Points	Comments
	Red – (Any of the following within the last two quarters)				
	Any A level CR OR 5 or more B level CRs OR				-
	15 or more total B or C level CRs OR				
	2 or more external findings OR Any NRC violation.				
nternally Identified mplementation Issues - Other	Green: None White: Identified issue with action resolved.	a green	1	3	None (Issues addressed in Corrective Action Plan
han CRs (Self revealing issues,	Yellow: Identified issue less than 1 year old.				for CR-2006-2699 above
	Red: Any identified issue greater than 1 year				
Outage Performance Note:	Green: Met original scope and goals (duration,	V.Skrien	1	3	No Outage this Qtr.
ndicator should remain the color until corrective actions are taken	White: Less than 100% greater than 90% Yellow: Less than 90% greater than 80%			•	Outage planning milestones have been
	Red: Less than 80%				met.

Monitored Parameter	Criteria	Result	Relative Value	Quality Points	Comments
On-line Performance	Green: Met original scope and goals (duration,	STEEL STEEL	1	. 3	No on-line FAC Related
	White: Less than 100% greater than 90%		1		goals
	Yellow: Less than 90% greater than 80%				
	Red: Less than 80%				
PM's/Surveillance Tasks	Green: No deferrals for the quarter	Green	1	3	No PMs under FAC
(window stays the color until the	White: Greater than 95% complete for the				program. Surveillances
deferred PM's are completed)	quarter			• • •	scheduled for RFO 26.
, , ,	Yellow: Greater than 90% complete for the				
·	quarter				
	Red: Less than 90% complete for the quarter			•	
Other Identified Concerns or	Green: No concerns / issues		1 .	3	None. Internally identified
Issues (Only captures program	White: Any non-significant concern/issue with			Ū	implementation issues
concerns that do not fall under	action plan				above addressed under
other Pls)	Yellow: Any significant concern or issue with				(CR-2006-2699)
00101110)	action plan or any non significant issue without		37.5		Corrective Action Plan
· ·	action plan			•	developed 10/2/06.
				•	developed 10/2/00.
	Red: Any significant issue/concern without				1.
	action plan				
Implementation resources (i.e.	Green: No identified resource concern	Green	1	3	Currently 2 Program
number of qualified personnel)	White: Identified concern with action plan				Engineers are qualified
	Yellow: Identified concern without action plan			•	per ENN-TK-ESPG042
,	Red: Significant concern without action plan				Training for new program
	linea. Digrillicant concern without action plan				engineer is process.
				•	
Piping Replacements (Unplanned	Green: 0 unplanned pipe or component	The Constant of	2	6	No outage this gtr. No
during cycle or outage)	replacements due to current outage findings.		_		unplanned piping
	White: 1 unplanned pipe or component				replacements during this
	replacement due to current outage finding.				operating cycle. Possible
	Yellow: > 1 < 2 unplanned pipe or component				FAC related small-bore
•	replacements due to current outage finding			,	replacement required in
•				-	RFO26, (WO 06-6880) 1"
	Red - > 2 unplanned pipe or component				
· .					
	Red - > 2 unplanned pipe or component replacements due to current outage finding.				SSH low pt.drain is planning for RFO26

	Monitored Parameter	Criteria	Result	Relative Value	Quality Points	Comments
		(Note: Color can be up-graded once corrective actions to piping are completed and Program has been corrected to prevent recurrence; i.e., additional exams or exam frequency specified)				
	Operating Experience	Green: 1 OR less items generated by plant OE department that has not been reviewed. White: 2 items generated by plant OE department that has not been reviewed. Yellow: 3 items generated by plant OE department that has not been reviewed. Red: > 4 items generated by plant OE department that has not been reviewed.	Green	1	3	No unreviewed OE generated by plant OE department.
NEC038429	Outage Scope Increase (Unplanned) (PWRs include online inspections in current cycle)	Green: < 10% increase in inspection scope due to inspection findings. White: 10% to < 12% increase in inspection scope due to inspection findings. Yellow: ≥ 13% increase in inspection scope due to inspection findings. Red: > 15% increase in inspection scope due to inspection findings.		1	3	No unplanned outage scope increase to date.
	3			,		
				Total	33	

	t Performance Cornerston				
Program: Flow Accelerated Corrosi					<u> </u>
		VERMONT YA	NKEE		
	Quarter:				
<u> </u>	Last Update:	10/03/2006		·	
			·		
	Cornerstone Rollup			Select Cornerstone Trendin	
	Green: 26-30 cornerstone quality points	e Green		1	Up
	White: 20-25 cornerstone quality points		· ·		Signal F
	Yellow: 15-19 cornerstone quality points			\downarrow	Down
	Red: <15 cornerstone quality points				
		• •			
			· .		,
Monitored Parameter	Criteria	Result	Relative Value	Quality Points	Comments
Seneration Health	Green - No Transients or power	S Green P	2	6	No transients or power
	reduction resulting from a program issue				reuctions resulting for
·	White - No Transients or power reduction		•		program activities of
	resulting from a program issue or		,		FAC related leaks so fa
	component on a quarterly basis				this operating cycle.
	Yellow - A " near miss", transient or a				
•	power reduction < 1000 mwhr/qt as a				
	result of a program issue or component				·
•					
•	Red - A plant trip or significant power		•		
	reduction > 1000 mwhr/qtr as a result of				
	a program issue of component		٠.		
arge Bore Failures (Based on Cycle	Green; No Large Bore failures in load	Par Veneral	. 4	12	No large bore failures
of operation)	Red; ≥ 1 Large Bore failure resulting in			,_	this operating cycle
	load reduction or safety issues.		ė		, s, g -,
	Note: color can be up-graded once		•		
•	corrective actions to piping are				
	completed and the Program has been				
5	corrected to prevent recurrence; i.e.,				
	additional exams or exam frequency				
	, promise in the state of the s	THE REPORT OF THE PERSON OF TH		1	1
	specified)				

			• • •		
Monitored Parameter	Criteria	Result	Relative Value	Quality Points	Comments
Small Bore Failures (Based on Cycle	Green: ≤ 1 Small Bore FAC related	#Green	2	6	1 smallbore leak .
of operation)	failure resulting in a load reduction				identified this operating
	White: < 3 Small Bore FAC related				cycle possibly due to
	failures resulting in a load reduction or				FAC. Location is on
	safety issue.				elbow of 1" low pt. drain
	Red: > 3 Small Bore FAC related failures				on SSH (WO 06-6880)
	resulting in a load reduction or safety				,
•	issue.				
	(Note: color can be up-graded once				·
	corrective actions to piping are				
•	completed and the Program has been				
	corrected to prevent recurrence; i.e.,				
the second second second	additional exams or exam frequency				
,	specified)		• ,		
Stress Analysis (Cycle of operation	Green: 1 to 3 detailed stress analysis	A Gleen Li	. 2	. 6	No stress analyses
including outage)	required.				required this operating
••	White: 3 to 5 detailed stress analysis				cycle
·	required.				
·	Red: ≥ 6 detailed stress analysis				·
	required.				
			Totals	30	
	· · · · · · · · · · · · · · · · · · ·				
					
				 	
		 			
				,	
					
				ļ	
		·			
			ļ		
		•			

Flow-Accelerated Corrosion (FAC) Program

Ownér: Jim Fitzpatrick

Phone:

802.451.3086

Controlling Document: PP 7028; ENN-DC-315

Supervisor:

Scott Goodwin

Date:

06-Apr-06

Quarter:

First Quarter, 2006

Program Color: Trend:

<u>White</u> Steady

2004 04 2005-Q1 2005-Q2 2005-Q4

Current Status Basis:

The FAC Program has just completed the 1st Qtr.: 2006. (1/01 to 3/31)

Program is white, based on 20 Green, 3 White, and 1 Yellow indicators.

There are no outstanding issues which are not already addressed that may impact the program.

Current Activities:

1st Qtr. 2006 (1/01 to 3/31)

RFO25 FAC Outage Inspection Report

RFO26 Outage Program Scope Milestone 2/19/06. RFO26 FAC Scope Memo, VYM-C-2006-001 issued 2/16/06.

auoption of ENN Standard FAC Program Procedure ENN-DC-315 Rev.1 on 3/15/06.

Attended EPRI Checworks Users Group Meeting on:1/9 & 1/10. OE at meeting from LaSalle, Peach Bottom 3, and Surry on partial line replacements resulted in addition of three Inspection locations for RF026.

ENN FAC Working Group Meeting 1/26 at PNPS.

Participation in IPEC FAC Program Focused Self Assessment 2/6 to 2/10.

Significant Accomplishments:

Adoption of ENN-DC-315 Rev.1

Met RFO26 Outage Planning Milestone

Actions To Return To Green:

Current Program engineers still involved with EPU related tasks (Nulcear Change and Power Accension). Code Programs attempts at hiring a new Program Engineer have not yielded results to date.

Completion of identified tasks listed in the "Open LO-CAs" in this Program Health Peport will bring Program status back to en. To ensure that ongoing program s are re-scheduled and performed for remainder of 2006, the action plan per ENN-MS-S-008 will be revised and activities

input to EWC by 4/15/06.

Exceptions To Grading Criteria:

REGULATORY:

No FAC Program Related LERs this

NPO Findings:

No NRC Findings No INPO Findings or AFIs.

GL 91-18 and Op Det

No GL 91-18 issues or operability evaluations related to the FAC Program

Regulatory Compliance:

The FAC Program currently meets all regulatory requirements.

New ARs and Code Cases:

New ENN Engineering Standard for Pipe Wall Thinning Evaluation, ENN-CS-S-008, incorporates ASME Code Case N-597. C.C. N-597 was incorporated into R.G. 1.147 Rev.13 with new caveats for use. NRC approval is required to implement code case as written

ADMINISTRATIVE:

Procedure, Program Compliance issues:

No Program Compliance issues with current Regulations of Codes.

With adoption of ENN-DC-315 Rev.1, VY Procedures PP7028 and DP0072 will be canceled per AP0096.

Budget, Resources:

FAC Program personnel (resources) were utilized on EPU related tasks. Currently no Program activities are scheduled into EWC. Activities will be input to EWC once scheduling of RFO26 design change work is complete.

Ownwership of FAC Program to be transferred to Programs & Components Engineering. Currently interviewing for new FAC program Engineer position in Code Programs.

Audis

No audits this quarter.

Open Action Items:

LO-VTYLO-2003-00327 CA 2 due 12/10/06 (three due date extensions) LO-VTYLO-2003-00327 CA 6 due 5/30/06 (two due date extensions) LO-VTYLO-2004-00399 CA 1 due 5/17/06 (two due date extensions) LO-VTYLO-2003-00327 CA 4 due 8/30/06 (two due date extensions) LO-VTYLO-2003-00327 CA 5 due 8/01/06 (two due date extensions)

BenchMarking. SeffAssessment:

Focused Self Assessment October 2003. Ongoing work for Corrective Actions generated from assessment. See LO-CAs (2003-0327) under Open Action Items

EWC Milestones, New Englissues

Continued difficulty in meeting re-projected schedules due to emegent work, EPU, & other unscheduled tasks. There is currently no EWC schedule in place for any Program. Program activities will be included in EWC after RFO26 design. changes are scheduled.

A formal action plan per ENN-MS-S-008 to adress issues to get program to Green status and ENN standardization was developed in 2nd. Otr. 2005. Status has 4 of 11 tasks as not complete. A revision to the Action Plan and EWC scheduling will be performed when EWC is up and functioning.

Program Concerns:

Continued difficulties in completeing scheduled FAC program activities due to resources spent on EPU related work. Concern from previous quarters. A formal Action Plan per ENN-MS S-008 was developed to get program to Green status.

Lack of progress in hiring a new FAC Program Engineer for Code Programs is a

CORRECTIVE ACTIONS

Significant CRs:

No significant CR's (Category A or B) were written against the FAC program for this quarter.

Open CR CAs:

No open CRs as of 3/31/06

EQUIPMENT:

Open Eng Reg:

Page 1 of 2

06-Apr-06

Flow-Accelerated Corrosion (FAC) Program

. AC

Owner: Jim Fitzpatrick

Phone:

802.451.3086

Controlling Document: PP 7028; ENN-DC-315

.

Supervisor:

Scott Goodwin

ER 04-1315 for Evaluation of Temporary Steam Leak Repair on L.P. Turbine Steam Seal Ploing

ER 05-0767 for Converting FAC Component Location Sketches Located into Appendix A of PP7028 into Controlled VY Drawings

ER 05-1004 for Upadating FAC Program Checworks Models for RFO26.

Operator Work Arounds:

N/A - There are no operator works arounds related to the FAC program.

Prog Related LCOs.

There are no LCOs related to the FAC program this qtr.

PMs Within Due Date:

N/A - There are no PMs associated with the FAC program.

Repetitive Failures:

are are no repetitive equipment related issues for the FAC program this quarter.

Unanticipated Failures:

SSH pin hole leaks identified in CR VTY-2004-02985. Terimporary leak enclosure installed. Additional inspections of similar piping incorporated into scope of RFO25. However, inspections were deferred until RFO26 due to schedule for LP turbine work.

No new Unanticipated Failures since October 2004.

Trending Results

No components projected to wear to wall thickness below code minimum within two cycles from RFO26.

Open Work Requests

N/A - There are no work requests over 2 yrs old.

Surveillances Within

Due Date:

N/A No Technical Specification Surveillances under the FAC program this gutarter.

Significant Parts Issues:

. - There are no parts issues associated with the FAC program this quarter

Identified Concerns:

No other identified equipment concerns.

*ORGANIZATION:*Statt Qual and T*r*ng:

The program owner and Backup engineer are qualified to perform FAC Program tasks.

3rd Engineer obtained basic FAC training and CHECWORKS SFA training, June 6-8.

Bench Strength:

The program owner and backup (T. O'Connor) are FAC qualified personnel. An additional engineer in Civil/Structural (R. Omer) has FAC related experience and has completed updated FAC training.

Program Ownership:

Site personnel are aware of the Program.

Owner based results from last SA.

FAC Program Ownership to be transferred to Code Programs Group per ENN model. Interviews for a new FAC Program Engineer to reside in Code Programs started in October 2005.

HUETOE

There were no human performance errors (HPE) as a result of Program implementation activities for this quarter.

AP0098 Expectations:

Continued difficulties in completeing program activities on schedule. EPU work is still affecting FAC Program activities in 1st quarter of 2006.

A formal action plan per ENN-MS S-008 to get program Green status and adddress ENN standardization issues was developed. The ENN standization efforts are complete as of 3/15/06 with the exception of cancelling PP7028 & DP0072 per AP0096. All other tasks required are being tracked in PCRS. Completion of identified tasks listed in the "Open LO-CAs" in this Program Health Report will bring Program status back to Green.

Status: Progress needs to be monitored. Keep status as White

Operating Experience:

See RFO26 (2007) Scoping Worksheets for a detailed list of FAC related OE and disposition for VY.

Page 2 of 2

ECIS: None

Outage Health:

<u>Outage Perfe</u>

No refueling outage in 1st QTR 2006.

RFO26 program scoping Milestone of 2/19/06 met (Memo VYM-FAC-2006-001 dated 2/16/06).

Outage Preparation:

RFO26 Outage planning milestones met.

Generation Healths Generation Health:

There were no transients or power reductions as a result of a FAC Program issue in 1st quarter of 2006.

Flow-Accelerated Corrosion (FAC) Program

<u> FAC</u>

Owner: Jim Fitzpatrick

Phone:

802.451.3086

Controlling Document: PP 7028; ENN-DC-315

Supervisor:

Scott Goodwin

Date:

15-Mar-06

Quarter:

Fourth Quarter, 2005

Program Color:

White Steady

Trend:

2005-Q1 | 2005-Q2

Current Status Basis:

2004-Q3 2004-Q4

This report covers 3rd & 4th quarters of 2005

Program is White, based on 17 Green, 6 White, and 1 Yellow indicators.

There are no outstanding issues which are not already addressed that may impact the program

Current Activities:

3rd & 4th Otr. 2005 (7/1/05 to 12/31/05)

RFO25 Outage Planning & Preparation

NRC FAC Program Inspection week of July 25

C Suseptibility Evaluation updated for EPU and other piping design changes (VY-RPT-05-00012, Rev.0)

Transition efforts to adopt ENN Standard FAC Program Procedure ENN-DC-315 Rev.0:

- Gap Analysis with PP7028 Completed 9/14/05
- 2. ENN-LI-100 Att.9.1, ENN-LI-101 Att.9.1 and EN-AD-101 Att9.1 with VY comments sent to WPO on 9/22/05.
- Engineering Standard & Approval form for ENN-CE-S-008 Pipe Wall Thinning Structural Evaluation, Rev.0 for VY completed 9/22/05.
- Engineering Standard & Approval form for ENN-EP-S-005 FAC Component Scanning & Gridding Standard, Rev.0 for VY completed 9/22/05.
- J. Fitzpatrick and T. O'Connor completed documentation for ENN standard FAC Qual Card ENN-TKESPG-042 on 10/5/05

RFO25 outage support, data evaluations and trending of inspection results.

Provided support for Management Presentations at ACRS Power Uprate Subgroup on Power Uprates Meeting in Bethdesda, MD on 11/30 & 31.

gnificant Accomplishments:

NRC FAC Inspection Complete. No findings of significance were identified. (NRC Inspection Report for VY 2005-004

dated October 19,2005).

Support of RFO25 inspection efforts

Actions To Return To Green:

Ensure that ongoing program tasks which were re-scheduled for remainder of 2005 per ENN-DC-183 Program Scope Memo are in fact performed on or near to schedule. This requires adquate time & personnel be alloted to perform program tasks. A formal action plan per ENN-MS-S-008 to get program Green status and address ENN standardization issues was developed in May 2005. Status 8 of 9 items complete in 2005.

Exceptions To Grading Criteria:

NONE

REGULATORY:

43:55

No FAC Program Related LERs these quarters.

INPO Findings.

No NRC Findings No INPO Findings or AFIs.

GL 91-18 and Op Det

No GL 91-18 issues or operability evaluations related to the FAC Program these quarters.

Regulatory Compliance:

The FAC Program currently meets all regulatory requirements.

New RRs and

New ENN Erigineering Standard for Pipe Wall Thinning Evaluation, ENN-CS-S-008, effective date 9/28/05, incorporates ASME Code Case N-597. C.C. N597 was incorporated into R.G 1.147 Rev.13 with new caveats for use. NRC appoval is required to implement the code case as written.

ADMINISTRATIVE:

Procedure Program

No Program Compliance Issues with current Regulations of Codes.

PP7028 and DP0072 to be cancelled once ENN-DC-315 is made effective at VY.

Budget, Resources:

2004 and 2005 scheduling of FAC

Page 1 of 2

Program per ENN-DC-183 Program Scoping Memo. FAC Program personnel (resources) were utilized on EPU related design changes and calculations. EWC schedule has Program resources pushed back to 2nd half of 2005.

Ownership of FAC Program to be transfered to Program & Components Engineering . Currently interviewing for new FAC Program Engineer position in Code Programs.

Archie

An NRC Inspection of the FAC Program for addressing EPU changes to piping and operating conditions was conducted the week of July 25;2005. No findings of significance were identified. (NRC Inspection Report for VY 2005-004 dated October 19,2005).

Open Action Hems

LO-VTYLO-2003-00327 CA 2 due 1/13/06 (two due date extensions)
LO-VTYLO-2003-00327 CA 6 due 5/30/06 (two due date extensions)
LO-VTYLO-2004-00399 CA 1 due 5/17/06 (two due date extensions)
LO-VTYLO-2003-00327 CA 4 due 2/10/06 (one due date extension)
LO-VTYLO-2003-00327 CA 5 due 1/15/06 (one due date extension)

SenenMarkinon Sauk sa

Focused Self Assessment October 2003.

Ongoing work for Corrective Actions
generated from assessment See LO-CAs
(2003-0327) under Open Action Items

EWC Milestones, New Englissues:

Ongoing program tasks were rescheduled for remainder of 2005 per ENN-DC-183 Program Scope Memo. Continued difficulty in meeting re-projected schedules due to emegent work, EPU, & other unscheduled tasks. A formal action plan per ENN-MS-S-008 was developed in 2nd, Qtr. 2005.

Action Plan addresses issues to get program to Green status and ENN standardization. All items on action plan completed in 2005 except incorporation of Small Bore Databse into VY-RPT-05-00013. This work is inprocess.

Program Concerns:

Scheduled FAC program activities were started late in 3rd quarter due to resources spent on EPU related work. Concern from previous qtr. A formal Action Plan per ENN-MS-S-008 was developed to get program status Green and adddress ENN

15-Mar-06

Flow-Accelerated Corrosion (FAC) Program

FAC

Owner: Jim Fitzpatrick

Phone:

802.451.3086

Controlling Document: PP 7028; ENN-DC-315

Supervisor:

Scott Goodwin

standardization issues.

Progess was made on action plan items. However, the root cause for not completing EWC schduled work has not been addressed.

CORRECTIVE ACTIONS:

Significant CRs:

No significant CR's (Category A or B) were written against the FAC program for these quarters.

Open CR CAS:

No Open CRs as of 12/31/05. CR-VTY-2005-02239 was closed out to ER 05-1004 on 12/19/05.

EQUIPMENT:

Open Eng Req:

ER 04-0964 for replacement of small bore piping on Turbine Bypass Valve 1st Seal Leakoff lines with FAC resistant materials was implemented during RFO25.

. 04-1315 for Evaluation of Temporary Steam Leak Repair on L.P.Turbine Steam Seal Piping. Removal of Temp Mod, and additional inspections to determine extent of condition were not performed in RFO25 due to schedule conflicts with LP turbine work. Deferred until RFO26. (Ref. VYPPF 7102.01-for W.O. 04-004983-000/010, dated 11/1/05)

Operator Work Arounds:

N/A - There are no operator work arounds related to the FAC program.

Progredated Loos

There are no LCOs related to the FAC program theses quarters.

PMs Within Due Date:

N/A - There are no PMs associated with the FAC program.

Repetitive Failures:

There are no repetitive equipment related Issues for the FAC program these quarters.

Unanticipated Failures:

SSH pin hole leaks identified in CR VTY-14-02985. Temporary leak enclosure alted. Additional inspections of similar piping incorporated into scope of RFO 25. However deferred until RFO26 due to schedule for LP turbine work.

Trending Results

N/A with respect to equipment.

Open Work Requests:

N/A - There are no work requests over 2 vrs old

Surveillances Within Due Date:

N/A No Technical Specification Surveillances under the FAC program were perfored in RFO25.

Significant Parts Issues:

N/A - There are no parts issues associated with the FAC program this quarter

Identified Concerns

No other identified equipment concerns.

ORGANIZATION:

Staff Qual and Tring:

The program owner and backup engineer are qualified to perform FAC Program tasks.

3rd Engineer obtained basic FAC training and CHECWORKS SFA training, 2nd Qtr. 2005.

Program owner and backup qualified to ENN Standard FAC Qual Card. ENN-TKESPG042 10/5/05

Bench Strength:

The program owner and backup (T. O'Connor) are FAC qualified personnel. An additional engineer in C/S (R. Orner) has FAC related experience and has updated training 2nd Qtr. 2005.

Program Ownership:

Site personnel are aware of the Program Owner based results from last SA.

FAC Program ownership to be transfered to Code Programs Group per ENN model. Interveiws for new FAC Program Engineer to reside in Code Programs Group started in October 05.

HU Errors:

There was one 1 human performance error (HPE) as a result of Program implementation activities for the third quarter of 2005 (CR-VTY-2005-02239 on procedure complance)

Page 2 of 2

AP0098 Expectations:

Continued difficulties in completing program activities on schedule. EPU work is winding down in second qtr. of 2005. FAC Program engineering work has been begun with update of the piping FAC susceptibility review and ENN procedure transition activities. A formal action plan per ENN-MS-S-008 to get program status to Green and address ENN standardization issues was developed and work has begun. Status: 8 of 9 items completed in 2005. Remaining task is in progress. Keep status as White.

Operating Experience:

See 2005 RFO Scoping Worksheets for a list of FAC related OE.

ECIs.

None

Outage Health:

Outage Perf:

RFO25 in October/November 2005. All planned inspections performed except Nos. 2004-24 to 2005-35. These are located on LP Turbine SSH and SPE lines to determine extent of condition for CR-VTY-2004-02925. These inspections were to be coordinated with removal of Temp Mod 2004-031. Restoration of the Temp Mod was deleted from the outage scope on 10/24/05 as documeted on YPPF 7102.01. Access to this piping could not be obtained due to critical path work on the LP turbines. Inspections were deferred to RFO26.

Outage Preparation:

RFO25 Outage planning milestones met.

Generation Health:

There were no transients or power reductions as a result of a FAC Program issue in Q3 & Q4 2005.

15-Mar-06

Flow-Accelerated Corrosion Program (FAC)

\C

Owner: Jim Fitzpatrick

Phone:

802.451.3086

Untrolling Document: PP 7028

Supervisor:

Scott Goodwin

06-Sep-05

Second Quarter, 2005

Program Color:

White **White**

Trend:

No INPO Findings or AFIs.

GL 91-18 and Op Det

quarter.

INPO Findings

No NRC Findings

No GL 91-18 issues or operability evaluations related to the FAC Program this quarter.

Regulatory Compliance:

The FAC Program currently meets all regulatory requirements.

New RRs and Code Cases:

ASME Code Case N-597 was incorporated into R.G 1.147 Rev.13 with new caveats for use. This will affect DP-0072 and transition to ENN-DC-133. WPO has decided to replace ENN-DC-133 with a new engineering Guide ENN-CE-G-001. VY Comments on draft sent to WPO on 5/24/05.

ADMINISTRATIVE

Procedure, Program:

No Program Compliance issues with current Regulations of Codes.

Budget, Resources:

2004 and 2005 scheduling of FAC Program per ENN-DC-183 Program Scoping Memo.

FAC Program personnel (resources) were utilized on EPU related design changes and calculations. EWC schedule has Program resources back onto FAC work in 2nd Qtr. 2005.

WANO inspection April 2005.

An NRC Inspection of of the FAC Program for addressing EPU changes to piping and operating conditions is scheduled for July 25,2005.

Open Action Items

LO-VTYLO-2003-00327 CA 2 due 1/13/06 (two due date extensions) LO-VTYLO-2003-00327 CA 6 due 10/03/05 (one due date extension) LO-VTYLO-2004-00399 CA 1 due 12/31/05 (one due date extension) LO-VTYLO-2003-00327 CA 4 due 2/10/06 (one due date extension) LO-VTYLO-2003-00327 CA 5 due 1/15/06 (one due date extension)

Page 1 of 2

LO-VTYLO-2005-00030 CA11 due 10/03/05 (one due date extension)

BenchMarking,

SelfAssessment

Focused Self Assessment October 2003. Ongoing work for Corrective Actions generated from assessment See LO-CAs (2003-0327) under Open Action Items

EWC Milestones, New Eng Issu

Ongoing program tasks were rescheduled for remainder of 2005 per ENN-DC-183 Program Scope Memo. Continued difficulty in meeting re-projected schedules due to emegent work, EPU, & other unscheduled tasks. A formal action plan per ENN-MS-S-008 was developed in 2nd. Qtr. 2005. Action Plan addresses issues to get program to Green status and ENN standardization.

Program Concerns:

Scheduled FAC program activities were started late in quarter due to resources spent on EPU related work. Concern from previous qtr. A formal Action Plan per ENN-MS S-008 was develoed to get program Green status and adddress ENN standardization issues

CORRECTIVE ACTIONS

Significant CRs:

No significant CR's (Category A) were written against the FAC program for this quarter.

Open CR CAs:

None for 2nd Qtr. 2005

EQUIPMENT

Open Eng Reg

ER 04-0964 for replacement of small bore piping on Turbine Bypass Valve 1st Seal Leakoff lines with FAC Resitant materials. Aprroved in EWC. Replacement to be implemented in RFO 25

ER 04-1315 for Evaluation of Temporary Steam Leak Repair on L.P. Turbine Steam Seal Piping

Operator Work Arounds

N/A - There are no operator works arounds related to the FAC program.

Prog Related LCOs

There are no LCOs related to the FAC

06-Sep-05

Date:

Quarter:

Steady

2004-Q1 2004-Q3 2004-Q4 2005-Q1

Current Status Bas

The FAC Program has just completed 2nd Qtr. 2005.

Program is white , based on 22 Green, 3 White, and 1 Yellow indicators.

There are no outstanding issues which are not already addressed that may impact the program.

Current Activities

2nd. Qtr. 2005 (4/1/05 to 6/30/05)

WANO Inspection, April 2005

RFO25 Outage Planning & Preparation

RFO25 Outage Scope Challenge Meeting 5/4/05

program and ENN procedure uansition acticities were rescheduled into EWC to start 2nd Qtr. 2005. Activities were started but not completerd due to EPU related design changes. This a continued trend from the previous quarter program health reports.

Preparation for July NRC FAC Inspection.

Significant Accomplishments

WANO Inspection Complete - No AFIs for FAC Program

Actions To Return To Green.

Ensure that ongoing program tasks which were re-scheduled for remainder of 2005 per ENN-DC-183 Program Scope Memo are in fact performed on or near to schedule. This requires adquate time & personnel be alloted to perform program tasks. A formal action plan per ENN-MS S-008 to get program Green status and adddress ENN standardization issues was developed in May 2005.

Exceptions To Grading Criteria

NONE

REGULATORY

NO FAC Program Related LERs this

Flow-Accelerated Corrosion Program (FAC)

1C

Owner: Jim Fitzpatrick

Phone:

802.451.3086

ontrolling Document: PP 7028 ر

Supervisor:

Scott Goodwin

program this qtr.

PMs Within Due Date:

N/A - There are no PMs associated with the FAC program.

Repetitive Failures:

There are no repetitive equipment related issues for the FAC program this quarter.

Unanticipated Failures:

SSH pin hole leaks identified in CR VTY-2004-02985. Tenmporary leak enclosure installed. Additional inspections of similar piping incorporated into scope of RFO 25

Trending Results:

N/A with respect to equipment

Open Work Requests:

N/A - There are no work requests over 2 yrs old.

Surveillances Within Due Date:

nspections scheduled in the RFO 2004 pection scope were completed during RFO 24. No surveillances scheduled for 2nd Qtr. 2005

Significant Parts Issues:

N/A - There are no parts issues associated with the FAC program this quarter

Identified Concerns:

No other identified equipment concerns.

ORGANIZATION

Staff Qual and Trng:

The program owner and Backup engineer are qualified to perform FAC Program tasks.

3rd Engineer obtained basic FAC training and CHECWORKS SFA training, June 6-8.

Bench Strength:

The program owner for and backup (T. O'Connor) are FAC qualified personnel. An additional engineer in M/S (R. Orner) has FAC related experience and has updated training (June 6-8).

Program Ownership:

personnel are aware of the Program owner based results from last SA.

HU Errors:

There were no human performance errors (HPE) as a result of Program implementation activities for this quarter.

AP0098 Expectations:

Continued difficulties in completeing program activities on schedule. EPU work is winding down in second qtr. of 2005. FAC Program engineering work has been begun with update iof the piping FAC susceptibility review and ENN procedure transition activities. A formal action plan per ENN-MS S-008 to get program Green status and adddress ENN standardization issues was devlopred and work has begun. Status: Progress needs to be monitored. Keep status as White:

Operating Experience:

See 2005 RFO Scoping Worksheets for a list of FAC related OE.

CPIs:

None

Ontage Health:

Outage Perf:

No outage in 2nd QTR 2005

Outage Preparation:

RFO-25 Outage planning milestones met.

Generation Health

Generation Health:

There were no transients or power reductions as a result of a FAC Program issue in Q2.

Page 2 of 2

06-Sep-05

Flow-Accelerated Corrosion Program (FAC)

Owner: Jim Fitzpatrick

Phone: 802.451.3086

Controlling Document: PP 7028

Supervisor: Scott Goodwin

Date:

10-May-05

Quarter

First Quarter, 2005

Program Color:

White:

Trend:

Improving

2003-Q4 2004-Q1 2004-Q3 2004-Q4

Current Status Basis:

The FAC Program has just completed 1st

Program is white, based on 21 Green, 3 White, and 1 Yellow indicators.

There are no outstanding issues which are not already addressed that may impact the program.

Current Activities:

1st Qtr 2005 (1/1/05 to 3/31/05)

ER 04-0964 for replacement of small bore piping on Turbine Bypass Valve 1st Seal: Leakoff lines with FAC resistant materials. Replacement to be implemented in RFO 25

34-1315 for Evaluation of Temporary steam Leak Repair on L.P. Turbine Steam Seal Piping. Inspection of additional components was added to the 2005 RFO scope to determine the extent of condition on the SSH plping.

Scheduled FAC Program Activities for the 1st quarter 2005 were not completerd due to EPU related design changes. This a continued trend from the previous quarter program health report. EPU work scheduled to end early 2nd qtr. 2005. FAC program acticities were rescheduled into EWC to start 2nd Qtr. 2005,

Significant Accomplishments:

Completed Corrective Actions from CR-VTY-2004-3061 and CR-VTY-2004-3062.

Met Outage Milestones for sub-work order genetation.

Actions To Return To Green:

Ensure that ongoing program tasks which were re-scheduled for remainder of 2005 per ENN-DC-183 Program Scope Memo are in fact performed on or near to schedule. This requires adquate time & personnel be alloted to perform program tasks. A formal action plan per ENN-MS Sto get program Green status and

'ress ENN standardization issues will delvelopred in the 2nd Qtr. 2005.

Exceptions To Grading Criteria:

NONE

REGULATORY:

LERS

No FAC Program Related LERs this quarter.

INPO Findings:

No NRC Findings No INPO Findings or AFIs

GL 91-18 and Op Det

No GL 91-18 issues or operability evaluations related to the FAC Program this quarter.

Regulatory Compliance:

The FAC Program currently meets all regulatory requirements.

Code Cases:

ASME Code Case N-597 was incorporated into R.G.1.147 Rev.13 with new caveats for use. This will affect DP-0072 and transition to ENN-DC-133. WPO has decided to replace ENN-DC-133 with a new enginineering Guide ENN-CE-G-xxx. Draft of guide sent out for comment on 3/09/05. Scheduled to have review complete by June 2005.

ADMINISTRATIVE:

Procedure, Program Compliance Issues:

No Program Compliance issues with current Regulations of Codes.

Budget, Resources:

2004 and 2005 scheduling of FAC Program per ENN-DC-183 Program Scoping Memo.

FAC Program personnel (resources) were utilized on EPU related design changes and calculations. EWC schedule has Program resources back onto FAC work in 2nd Qtr. 2005.

Monster

A QA audit was performed in Sept/October 2004. The audit identified two procedure compliance issues related to program documention and timely completion of activities.

CR VTY-2004-03061 identified that the FAC Inspection Report for the 2004 RFO was not completed within 90 days of plant startup as required per PP-7028. Report

Page 1 of 2

was completed 2/15/05 and CR was closed on 2/16/05.

CR VTY-2004-03062 identified a backlog in inspection records being sent to RIMS per AP-6807. For each refuelig outage; Progam PP7028 inspection records, reports, memos, and component evaluations were packaged similar to job order files and sent to RIMS. CR was closed on 2/16/05

WANO inspection is scheduled for April

An NRC inspection of of the FAC Program for addressing EPU changes to piping and operating conditions is scheduled for July 25,2005.

Open Action Items:

LO-VTYLO-2003-00327 CA 2 due 6/1/05 (one due date extension) LO-VTYLO-2003-00327 CA 3 due 5/15/05 (one due date extension) LO-VTYLO-2003-00327 CA 6 due 6/13/05 (one due date extension) LO-VTYLO-2004-00399 CA 1 due 12/31/05 (one due date extension) LO-VTYLO-2003-00327 CA 4 due 7/1/05 LO-VTYLO-2003-00327 CA 5 due 7/1/05 LO-VTYLO-2005-00030 CA11 due 7/31/05

BenchMarking, SelfAssessment

Focused Self Assessment October 2003. Ongoing work for Corrective Actions generated from assessment See LO-CAs (2003-0327) under Open Action Items

Participated in Focused Self Assessment of PNPS FAC Program per EN-LI-104, January 24-28, 2005.

C Milestones, New Englissues

Ongoing program tasks were rescheduled for remainder of 2005 per ENN-DC-183 Program Scope Memo. Continued difficulty In meeting re-projected schedules due to emegent work, EPU, & other unscheduled tasks. A formal action plan per ENN-MS-S-008 will be developed in 2nd. Qtr. 2005. Action Plan will address issues to get . program to Green status and ENN standardization.

Program Concerns:

Scheduled FAC program activities for qtr. were not performed due to resources spent on EPU related work. (Action Plan: Activities were rescheduled in EWC Into 2nd qtr. 2005) Same concern from previous qtr. A formal Action Plan per ENN-MS S-008 will be developed to get program Green status and adddress ENN

Flow-Accelerated Corrosion Program (FAC)

-AC

Owner: Jim Fitzpatrick

Supervisor: Scott Goodwin

Controlling Document: PP 7028

standardization issues will be delvelopred in the 2nd Qtr. 2005.

CORRECTIVE ACTIONS STORY CONTROL OF THE STORY CONTR

No significant CR's (Category A) were written against the FAC program for this quarter.

Open CR CAs:

None

EQUIPMENT:

Open Eng Reg

ER 04-0964 for replacement of small bore piping on Turbine Bypass Valve 1st Seal Leakoff lines with FAC Resitant materials. Approved in EWC. Replacement to be implemented in RFO 25

ER 04-1315 for Evaluation of Temporary Steam Leak Repair on L.P.Turbine Steam Seal Piping

raiora Work Arounds

N/A - There are no operator works around related to the FAC program.

Prog Related LCOs:

There are no LCOs related to the FAC program this qtr.

PMs Within Due Date:

N/A - There are no PMs associated with the FAC program.

Repetitive Fallures

There are no repetitive equipment related issues for the FAC program this quarter.

Unanticipated Fallures:

SSH pin hole leaks identified in CR VTY-2004-02985. Tenmporary leak enclosure installed. Additional inspections of similar piping incorporated into scope of RFO 25

Trending Results:

N/A with respect to equipment.

Open Work Requests:

- There are no work requests over 2

Surveillances Within Due Date:

All inspections scheduled in the RFO 2004 inspection scope were completed during RFO 24. No surveillances scheduled for 1st Otr. 2005.

Significant Parts Issues:

N/A - There are no parts issues associated with the FAC program this quarter

identified Concerns:

No other identified equipment concerns.

ORGANIZATION:

Staff Qual and Trng:

The program owner and Backup engineer are qualified to perform FAC Program tasks.

Bench Strength

The program owner for and backup (T. O'Connor) are FAC qualified personnel. An additional engineer in WS (R. Omer) has FAC related experience.

Program Ownership:

Site personnel are aware of the Program Owner based results from last SA.

HU Errors

There were no human performance errors (HPE) as a result of Program implementation activities for this quarter.

AP0098 Expectations:

Continued difficulties in completeing program activities on schedule. EPU work is currently scheduled to end early in second qtr. of 2005. FAC Program engineering work has been rescheduled to start in 2nd qtr 2005. FAC related milestones and activities to support RFO25 have been completed per schedule. Completion of corrective actions for CR-VTY-2004-3061 and CR-VTY-2004-3062 have resulted in reducing backlog in program documetation. The situation is improving based on end of EPU work, new EWC schedule, and reduction in documetation backlog. A formal action plan per ENN-MS S-008 to get program Green status and adddress ENN standardization issues will be delvelopred in the 2nd Qtr. 2005.

Status change form Yellow to White .

Operating Experience:

See 2005 RFOscoping worksheet for a list

Page 2 of 2

of FAC related OE.

<u>Pisi</u>

Phone: 802,451,3086

None .

Outage Health:

Outage Perf:

No outage in 1st QTR 2005.

Outage Preparation:

RFO-25 Outage planning milestones met.

Generation fleathread as Generation Health:

There were no translents or power reductions as a result of a FAC Program issue in Q1.

11-May-05

Flow-Accelerated Corrosion Program (FAC)

FAC

Controlling Document: PP 7028

Owner: Jim Fitzpatrick

Phone: 802.451.3086

Supervisor: Scott Goodwin

Date: Ouarter:

18-Jan-05

Program Color:

Zyellów Declining

2006-06- 2003

2003-Q4 2004-Q1 2004-Q3

Current Status Basis:

The FAC Program has just completed 4th Qtr 20041.

Program is Yellow, based on 17 Green, 2 White, and 5 Yellow indicators.

There are no outstanding issues that may impact the program.

Current Activities:

4th Qtr 2004 (10/1/04 to 12/31/04)

Design Engineering Manager approved 2003 Focused Self Assement Report on 10/28/04. Five new LO CAs were generated to address areas for improvement indentified in the SA.

ER 04-0964 for replacement of small bore piping on Turbine Bypass Valve 1st Seal Leakoff lines with FAC resistant materials. Approved in EWC. Replacement to be implemented in RFO 25

ER 04-1315 for Evaluation of Temporary Steam Leak Repair on L.P. Turbine Steam Seal Piping. Inspection of additional components was added to the 2005 RFO scope to determine the extent of condition on the SSH piping.

Scheduled FAC Program Activities for the 4th quarter 2004 were not completerd due to emergent work and EPU related design changes. This a continued trend from the previous quarter program health report.

Significant Accomplishments:

Approval of Focused Self Assessment Report (LO-VTY-2003-0327 CA1)

Actions To Return To Green:

Ensure that ongoing program tasks which were re-scheduled for remainder of 2004 per ENN-DC-183 Program Scope Memo are in fact preformed on or near to schedule. This requires adquate time & personnell be alloted to perform program tasks.

Exceptions To Grading Criteria:

NONE

REGULATORY:

No FAC Program Related LERs this quarter.

INPO Findings

No NRC Findings No INPO Findings or AFIs.

GL 91-18 and Op Det

No GL 91-18 issues or operability evaluations related to the FAC Program this quarter

Regulatory Compliances

The FAC Program currently meets all regulatory requirements.

New RRs and

ASME Code Case N-597 was incorporated into R.G. 1.147 Rev.13 with new caveats for use. This will affect DP-0072 and transition to ENN-DC-133. WPO controls ENN-DC-133. Revisions are planned for 1st Qtr.2005.

ADMINISTRATIVE:

Procedure, Program

No Program Compliance issues with current Regulations of Codes.

Budget, Resources:

2004 and 2005 scheduling of FAC Program per ENN-DC-183 Program Scoping Memo.

FAC Program personnel (resources) were utilized on EPU related design changes and calculations.

Audits

There was one QA audit performed for this quarter. The audit was performed in Sept/October 2004. The audit identified two procedure compliance issues related to program documention and timely completion of activities.

CR VTY-2004-03061 identified that the FAC Inspection Report for the 2004 RFO was not completed within 90 days of plant startup as required per PP-7028.

CR VTY-2004-03063 identified a backlog in inspection records being sent to RIMS per AP-6807

An NRC Inspection of of the FAC Program for addressing EPU changes to piping and operating conditions is scheduled for 2005.

Page 14 of 46

Open Action tems:

LO-VTYLO-2003-00327 CA 2 due 3/1405 LO-VTYLO-2003-00327 CA 3 due 3/18/05 LO-VTYLO-2003-00327 CA 6 due 4/1/05 LO-VTYLO-2004-00399 CA 1 due 4/1/05 LO-VTYLO-2003-00327 CA 4 due 7/1/05 LO-VTYLO-2003-00327 CA 5 due 7/1/05

Sench Markin

Focussed SA recort for VY FAC Program approved by DE Manager 10/28/04. Did not meet EN-LI-104 SA completion date expectations.

Planned participation if Fcused Self Assessment of PNPS FAC Program per EN-LI-104 4rd Qtr. deferred until 1/24/05 at PNPS requestof PNPS.

Administrative Backlog:

CORRECTIVE ACTIONS:

Significant CRS

No significant CR's (Category A) were written against the FAC program for this quarter. Existing VY commitments are equivalent to LO-CAs.

Open CR CAs:

CR-VTY-2004-03061 CA2 due 2/04/05 CR-VTY-2002-02568 CA3 due 3/01/05 CR-VTY-2004-02985 CA3 due 3/11/05

EQUIPMENT:

Open Eng Reg

ER 04-0964 for replacement of small bore piping on Turbine Bypass Valve 1st Seal Leakoff lines with FAC Resitant materials. Approved in EWC. Replacement to be implemented in RFO 25

ER 04-1315 for Evaluation of Temporary Steam Leak Repair on L.P.Turbine Steam Seal Piping

N/A - There are no operator works around related to the FAC program.

Prog Related LCOs

There are no LCOs related to the FAC program this qir.

PMs Within Due Date:

10-Feb-05

Flow:Accelerated Corresion Program (FAC)

FAC

--

Owner: Jim Fitzpatrick

Phone: 802.451.3086

Controlling Document: PP 7028

Supervisor: Scott Goodwin

N/A - There are no PMs associated with the FAC program.

Repetitive Failures:

There are no repetitive equipment related issues for the FAC program this quarter.

Unanticipated Fallures:

SSH pin hole leaks identified in CR VTY-2004-02985. Temporary leak enclosure installed, Additional inspections of similar piping incorporated into scope of RFO 25.

Trending Results

N/A with respect to equipment.

Open Work Requests

N/A - There are no work requests over 2 yrs old.

Surveillances Within-Due Date

All Inspections scheduled in the RFO 2004 inspection scope were completed during RFO 24, No surveillances scheduled for 4th QTR 2004.

Significant Parts Issues:

N/A - There are no parts issues associated with the FAC program this quarter

identified Concerns.

No other identified equipment concerns.

ORGANIZATION:

Sancual and more

The program owner and Backup engineer are qualified to perform FAC Program tasks.

Bench Strength

The program owner for and backup (T. O'Connor) are FAC qualified personnel. An additional engineer in M/S (R. Orner) has FAC related experience.

Program Ownership

Site personnel are) aware of the Program Owner based results form recent SA.

HUErrors:

There were 2 reported human performance errors (HPE) as a result of Program implementation activities for this quarter.

R VTY-2004-03061 identified that the FAC inspection Report for the 2004 RFO was not completed within 90 days of plant startup as

required per PP-7028. CR VTY-2004-03063 identified a backlog in

inspection records being sent to RIMS per AP-6807.

AP0098 Expectations

Continued difficulties in completeing program activities on schedule.

Operating Experience

See 2005 RFOscoping worksheet for a list of FAC related OE.

In addition, LO-OEN-2004-00272 for the 8/04 Mihama Event was generated. CA3 assisgned to VY to review FAC Program & Inspection Efforts for applicability to VY. Inspections of piping at two restriction orfices in the Condensate System were added to the RFO 25 scope.

CPS

Outage Health:

No outage in 4th QTR 2004.

Outage Preparation:

RFO-25 Outage Milestones met. Initial outage scope memp issued 7/7/04. Scope freeze on WO generation met 10/7/04.

Generation Health:

Generation Health

There were no transients or power reductions as a result of a FAC Program issue in O4.

10-Feb-05

Page 15 of 46

Flow-Accelerated Corrosion Program (FAC)

. AC

...

Owner: Jim Fitzpatrick

Phone: 802.451.3086

Supervisor: Scott Goodwin

Controlling Document: PP 7028

Date: Quarter: 19-Nov-04

Program Color:

2004-Q3 White

Trend:

Declining

2003-Q4 2004-Q1

Current Status Basis

Program is -White , based on 16 Green; 3 White; 2 Yellow; and 0 Red

Current Activities

3rd Quarter 2004 (6/16/04 to 9/30/04)

Review and comments on new ENN Standard FAC Program Procedure, ENN-DC-315, and new Gridding Standard, ENN-EP-S-005.

Addressed NRC RAIs relating to FAC for the VY Power Uprate Submittal.

FAC Program coordinator cancelled attendance at June 28 EPRI Checworks Users Group Meeting due to VY forced 'age. Meeting information availble on JG web site.

FAC Program coordinator participated in QA Audit of FPL Corporate FAC Inspection Program at Juno Beach FL. July 12 to 16.

FAC program engineers participated in NRC Inspection for EPU affects on FAC program.

Incorporated Design Engineering Manager comments on 2003 Focussed Self Assessment. Returned report to DE Mgr. on 9/1/04.

Scheduled FAC program work activities for 3rd qtr. were deferred due to emergent work; forced outage, NRC inspection, engineering support for intervenor requests for information, and intervenor contentions.

Significant Accomplishments,

NRC Inspection

Actions To Return To Green:

Ensure that ongoing program tasks which were rescheduled for remainder of 2004 per ENN-DC-183 Program Scope Memo are in fact performed on or near to schedule. This requires adequate time & personnel be allotted to perform program ks.

atus: There was no improvement in this area for the 3rd quarter of 2004.

Exceptions To Grading Criteria

None

REGULATORY:

41:

No FAC Program Related LERs this

INPO Findings:

No NRC Findings No INPO Findings or AFIs.

GL-91-18 and Op Det:

No GL 91-18 issues or operability evaluations related to the FAC Program this quarter.

Requiatory Compliance:

No Regulatory Compliance Issues related to the FAC Program this quarter.

New RRs and

ASME Code Case N-597 was incorporated into R.G 1.147. This will affect DP-0072 and transition to ENN-DC-133. WPO controls ENN-DC-133.

ADMINISTRATIVE

Procedure, Program Compliance Issues

There are no LPCs or relief requests required for regulatory or code compliance.

Budget: Resource

2004-2005 budget and schdule for FAC Program established through EWC process using ENN-DC-183 Program Scoping Memo.

For 3rd quarter 2004, FAC Program personnel were utilized on EPU related design changes, calculations, audit support, and intervenor issues.

Audits

An NRC Inspection for EPU included questions on affects of FAC on plant piping and equipment. Final evaluation and documetation had not been performed as of the inspection date. No immdiate findings/concems were identified.

Open Action liems

LO-VTYLO-2003-00327 CA1 (2 due date extensions during period) LO-VTYLO-2004-00399 CA1 (1 due date

Page 1 of 2

extension during period).

BenchMarking SelfAssessment:

Incorporated Design Engineering Manager comments on 2003 Focussed Self Assessment. Returned report to DE Mgr. on 9/1/04.

Documetation of Benchmarking performed during FP&L QA Audit, July 12-16, has not been completed.

Planned participation in Focused Self Assessment of PNPS FAC Program per EN-LI-104 4th Qtr. (Dec.13-16,2004)

Administrative Backlog:

Procedure changes to PP 7028 (will be resolved by transition to ENN-DC-315). Data transmittal(s) to RIMS

CORRECTIVE ACTIONS
Significant CRS

Vo significant CP's word written

No significant CR's were written against the FAC program for this quarter.

open of Cas

CR-VTY-2002-02568 CA3 (due 3/1/05). CR-VTY-2004-02985 CA3 (due 3/1/05).

EQUIPMENT:

Open Eng Reg.

ER 04-0964 for replacement of small bore piping on Turbine Bypass Valve 1st Seal Leakoff lines with FAC Resitant materials Status: 9/27/04: Recommend transfer to MPRC after approval by the department manger. Project Sponsor: JH Callaghan, SD Goodwin to prepare Funding justification form. 9/30/04 approved by

Operator Work Arounds:

N/A - There are no operator works around related to the FAC program.

Prop Related LCOs:

N/A - There are no LCOs related to the FAC program this qtr.

PMs Within Due Date:

N/A - There are no PMs associated with the FAC program.

Repetitive Failures:

There are no repetitive equipment related issues for the FAC program this quarter.

Flow-Accelerated Corrosion Program (FAC)

rAC

Owner: Jim Fitzpatrick

Phone: 802.451.3086

Controlling Document: PP 7028

Supervisor: Scott Goodwin

Unanticipated Failures:

Non Maintenace Rule. Steam leak identified in LP SSH supply line on 9/24/04. See CR-VTY-2004-02985. Planning for evaluation & repair is in progress as of 9/30/04.

Trending Results:

N/A with respect to equipment

Open Work Requests:

N/A - There are no work requests over 2, yrs old.

Surveillances Within

Due Date:

All inspections scheduled in the RFO 2004 inspection scope were completed during RFO 24. None were schedulred for 3rd qtr. 2004.

Significant Parts Issues:

MA - There are no parts issues associated the FAC program this quarter

ntified Concern

Significant Concern: Scheduled FAC program activities for qtr. were not performed due to resources spent on EPU related work. (Action Plan: Activities were rescheduled in EWC into 3rd/4th qtr. 2004) Same concern from 4th qtr. 2003. This is an ongoing issue and may require realignment of program resources to insure program activities take priority. No Progress was made in the 3rd Quarter of 2004.

Transition to ENN Standard FAC program, ENN-DC-315, will require revision to ENN-DC-133. Previously sheduled working meetings for revision of ENN-DC-133 for the first quarter of 2004 were not held. WPO controls ENN-DC-133.

のおG/4M/ZAV(IO)が Staff Qual and Trng:

The program owner and Backup engineer are qualified to perform FAC Program tasks.

Bench Strength:

The program owner for and backup (T.

Connor) are FAC qualified personnel. An
itional engineer in M/S (R. Omer) has

related experience.

Program Ownership:

Based on pending results form recent SA the answer is yes.

HU Errors:

Completion of the RFO24 FAC Program Inspection Report went past the 90 days from plant start-up as required by PP 7028. Identified by CR-VTY-2004 -03061 on 10/04/04. CR and CAs will be addressed in 4th Otr program health report.

AP0098 Expectations:

RFO 24 Inspection Report was not completed within 90 days from plant start up as required by PP7028. CR VTY-2004-03061 written on 10/4/04, not "prompt" as required by Appendix A of AP0098.

Operating Experience:

See 2005 RFO FAC Program Scoping Worksheets for detailed list.

CPIs:

None

Outage Health:

Outage Perf:

Initial RFO 25 outage scope memo issued 7/7/04.

Outage Preparation:

Initial RFO 25 outage scope memo issued 7/7/04.

©enenation⊪aleatti Generation Health:

No adverse impact on generation by FAC Program issues or component failures. No transients or power reductions were reported as a result of a FAC Program issue this quarter.

Page 2 of 2

Flow-Accelerated Corrosion Program (FAC)

Jim Fitzpatrick

Phone: 802.451.3086

Controlling Document: PP 7028

Owner:

Frequency: Quarterly

Date: Quarter 22-Jun-04

Program Color:

2004-Q1 White

Trend:

Steady

2003-08 2003-Q4

Current Status Basis;

Program is White, based on 20 Green; 1 White; 1 Yellow; and 0 Red

Current Activities

Attended the EPRI Checworks Users Group Meeting, January 12-14.

Addressed NRC RAIs relating to FAC for the VY Power Uprate Submittal.

Completed writeup for 2003 Focussed Self Assessment for Design Engineering Manager review and approval on 1/30/04.

FAC Program Coordinator participated in JAF FAC Program Self Assesment at WPO 2/9 to 2/13.

viewd draft of Revision 1 changes to wom piping components.

RFO 24 Outage Support for FAC Inspections. Tasks included outage review of Work Order packages, planning, training, data evaluation, turbine crossaround piping visual inspections, and interface with management.

Developed EWC Program Scope Memo (ENN-DC-183) for remander of 2004 and for 2005.

ENN FAC Working group assigned to an expedited adoption of a new ENN Standard FAC Program. Participated in working group developing a draft of new procedure ENN-DC-315 and new Gridding Standard ENN-EP-S-005 (6/2 to 6/4)

Significant Accomplishments **RFO 24**

Actions To Return To Green:

Ensure that ongoing program tasks which wer rescheduled for remainder of 2004 per ENN-DC-183 Program Scope Memo are in fact preformed on or near to schedule. This requires adquate time & personeel alloted to perform program tasks.

xceptions To Grading Criteria:

REGULATORY:

No FAC Program Related LERs this

INPO Findings

No NRC Findings No INPO Findings or AFIs.

GL91518 and Op Dec

No GL 91-18 issues or operability evaluations related to the FAC Program this quarter.

Requiatory Compliance:

No Regulatory Compliance issues related to the FAC Program this quarter.

Code Cases:

ASME Code Case N-597 was incorporated into R.G 1.147. This will affect DP-0072 and transition to ENN-DC-133. WPO controls ENN-DC-133.

ADMINISTRATIVE:

Procedure, Program

There are no procedure/program compliance issues associated with the FAC Program.

Budget, Resources:

Rating

2003-2004 Budget per supervisor Schedule was set prior to EPU. For reaminder of 2004 and 2005 scheduling of FAC Program per ENN-DC-183 Program Scoping Memo.

FAC Program personnel were utilized on EPU related design changes and calculations.

A NRC Inspection of ISI Program Activities was performed during the beginning of RFO 24. The inspection included an interview of the FAC Program Coordinator on program issures and planned inspections. The inspection report is pending.

Open Action Items:

LO-VTYLO-2003-00327 (1 extesion during (boineq

Bench Marking,

Participated in Fcused Self Assessment of

Page 14 of 44

JAF FAC Program per ENN-LI-104 week of 2/9 to 2/13

Planned benchamarking trip to FP&L in 3rd Qtr. (July 12-16)

Planned participation if Foused Self Assessment of PNPS FAC Program per EN-LI-104 3rd Qtr. (Aug. 8-13)

Milestones, new:

Outage support for RFO 24 completed. Ongoing program tasks were rescheduled for remainder of 2004 per ENN-DC-183 Program Scope Memo.

Engineering Issues, new:

ASME Code Case N-597 was incorporated into R.G 1.147. (DP0072) this will affect transition to ENN-DC-133. Previously planned working group meetings scheduled for 1st qtr 2004 were not held. WPO has control of ENN-DC-133

Administrative Backlog:

CORRECTIVE ACTIONS

Significant CRs:

No significant CR's were written against the FAC program for this quarter. Existing VY commitments are equivalent to LO-CAs.

CR-VTY-2002-2568 (5/4/04)

Open Eng Reg:

ER 04-0964 for replacement of small bore piping on Turbine Bypass Valve 1st Seal Leakoff lines with FAC Resitant materials

Operator Work Arounds:

N/A - There are no operator works around related to the FAC program.

Prog Related LCOs:

N/A - There are no LCOs related to the FAC program this qtr.

PMs Within Due Date:

N/A - There are no PMs associated with the FAC program.

Repetitive Failures:

N/A - There are no repetitive equipment related issues for the FAC program this

Flow-Accelerated Corrosion Program (FAC)

FAC

Controlling Document: PP 7028

Owner:

Jim Fitzpatrick

Phone: 802.451.3086

Frequency: Quarterly

quarter.

Unanticipated Failures: 0

Trending Results:

Supv. Rati

Open Work Requests:

N/A - There are no work requests over 2 yrs old.

Surveillances Within 100 Due Date:

All inspections scheduled in the RFO 2004 inspection scope were completed during RFO 24.

Significant Parts Issues: N

N/A - There are no parts issues associated with the FAC program this quarter

Identified Concerns:

nificant Concern: Scheduled FAC program activities for qtr. were not performed due to resources spent on EPU related work. (Action Plan: Activities were rescheduled in EWC into 3rd/4th qtr. 2004) Same concern from 4th qtr. 2003. This is an ongoing issue and may requie realignment of porgram resouces to insure program activities take priority.

ORGANIZATION:

Staff Qual and Trng:

The program owner and Backup engineer are qualified to perform FAC Program tasks.

Bench Strength:

The program owner for and backup (T. O'Connor) are FAC qualified personnel. An additional engineer in M/S (R. Omer) has FAC related experience.

<u>Program Ownership:</u> Hati

Based on pending results form recent SA the answer is yes.

HU Errors:

There were no human performance errors sociated with the FAC program this qtr.

.30098 Expectations:

Supv. Rating

Operating Experience:

See 2004 RFO FAC Program Scoping Worksheets for detailed list.

<u>CPIsi</u> Numb

None

Outage Health: The state of

Outage Pert: Rating

Outage Preparation: Palin

RFO-24 Outage Milestones met.

Generation Health

Generation Health: Ratin

No adverse impact on generation by FAC Program issues or component failures. No transients or power reductions were reported as a result of a FAC Program issue this quarter.

Page 15 of 44

Elow-Accelerated Corrosion Program (FAC)


FAC

Controlling Document: PP 7028

Owner: Jim Fitzpatrick

Phone: 802.451-3086

Frequency: Quarterly



Current Stātus Bāsis

Current Status: Program is Green, based on 20 Green; 2 White; 1 Yellow, and 0 Red.

Current Status Basis:

Current Program Trend: Steady
Current Activities:

ENN FAC Working group formed (two meetings held). Standardization of ENN AC Programs is a focus of the group, ach plant is to have a focused self assessment performed. A significant effort was required to develop the standardized evaluation criteria to perform these SAs per new ENN procedure ENN-LI-104.

Qualitative studies & evaluations were performed in support of September EPU submittal.

Significant Accomplishments:

A Focused Self Assessment (per ENN-LI 104) of the VY FAC Program was started on 9/29/03. Results will be incorporated into the 4th Qtr Health Report.

REGULATORY

quarter.

NPO FI

LERS


No FAC Program Related LERs this

No NRC Findings No INPO Findings or AFIs.

GL-91-18 and Op Det:

No GL 91-18 Issues or operability evaluations related to the FAC Program this quarter.

Regulatory Compliance: 0



ASME Code Case N-597 was incorporated into R.G 1.147. This will affect DP-0072 and transition to ENN-DC-133. Additional ENN meetings to be scheduled for 1st QTR 2004 to evaluate.

ADMINISTRATIVE

Procedure, Program Compliance Issues:

There are no procedure/program compliance issues associated with the FAC Program.

Budget, Resources:

Rating White

2003-2004 Budget per supervisor Schedule was set prior to EPU. For 2003 scheduling of FAC Program activities has been shifted to allow for engineering support off EPU and emergent work. FAC Program personnel were utilized on EPU related design changes and calculations.

<u>lits</u> Rali Gre

There were no Audits performed for this quarter. There are no open issues.

Open Action Items

LO-VTYLO-2002-00341 LO-VTYLO-2002-00568 (1 extension during qtr.) LO-VTYLO-2003-00327

LO-VTYLO-2002-00528 (1 extension during qtr.)
Note both extensions during qtr. are due to EPU work.

<u>BenchMarking.</u> Raling <u>SelfAssessment</u> Greer

S.A. VYM SA 2002-003 on Davis Besse Issues performed in Nov.2002.

Focused Self Assessment of VY FAC Program per ENN-LI-104 week of 9/29 to 10/2. Draft report complete, final report deffered until 2004 for EPU related work (LO-VTYLO-2003-00327 CA-0001)

<u>Milestones, new:</u> N//

None This Qtr.

Engineering Issues. 1 new: N/A

ASME Code Case N-597 was incorporated into R.G 1.147. (DP0072).
Transition to ENN-DC-133. Meetings scheduled for 1st qtr 2004 to evaluate

Page 12 of 41

Standardization for ENN FAC Programs Administrative Backlog:

CORRECTIVE ACTIONS IN

No significant CR's were written against the FAC program for this quarter. Existing VY commitments are equivalent to LO-CAs.

Open CR CAS: NA

CR-VTY-2002-2568 (5/4/04)

EQUIPMENT Open Erin Reg: N/A N/A

N/A; Engineering Requests not yet implemented at Vermont Yankee.

Operator Work Arounds

N/A - There are no operator works around related to the FAC program.

Prog Related LCOs: Gree

N/A - There are no LCOs related to the FAC program this qtr.

PMs Within Due Date N/A Green

N/A - There are no PMs associated with the FAC program.

Repetitive Failures: Gree

N/A - There are no repetitive equipment related issues for the FAC program this quarter.

Unanticipated Failures:

White

Turbine Bypass Valve Steam Seal Piping. Additional inspections scheduled for 2004RFO, Also scoping to replace with FAC resistant material.

Trending Results:

NA

Open Work Requests:

N/A - There are no work requests over 2 vrs old.

<u>Surveillances Within</u> - 100% <u>Due Date:</u> Green

All inspections scheduled in previous outages were performed. RFO 2004 scope is currently being scheduled.

22-Jan-04

Flow-Accelerated-Gorrosion Program (EAS)

FAC

Controlling Document: PP 7028

Owner: Jim Fitzpatrick

Phone: 802.451-3086

Frequency: Quarterly

Significant Parts Issues:

N/A - There are no parts issues associated with the FAC program this quarter

Leak in TBV Steam Seal Leakoff plping has elevated the need to complete the update of the small bore piping database (Action Plan: Currently on EWC FAC Program schedule).

Significant Concern: Scheduled FAC program activities for qtr. were not performed due to resources spent on EPU related work. (Action Plan: Activities were rescheduled in EWC into 1st. qtr. 2004) Same concern from 3rd qtr. 2003.

Potential Issue: Based on experience to date, the transition to ENN procedures is trending toward standardization in name only. The concern is that previous efficiencies at VY will be lost when new ENN procedures modeled on large utility organizations, which require an army to nplement, are imposed on the program. Proposed Action Plan is to participate in transition working groups to control direction of transition or alert management to start hiring.)

ORGANIZATION:

Staff Qual and Trng

The program owner is qualified to perform FAC Program tasks

Bench Strength

The program owner for and backup (T. O'Connor) are FAC qualified personnel. An additional engineer in M/S (R. Omer) has FAC related experience.

Program Ownership:

Based on pending results form recent SA the answer is yes

There were no human performance errors

associated with the FAC program this qtr.

AP0098 Expectations:

Rating

Operating Experience:

ee 2004 RFO FAC Program Scoping Worksheets for detailed list.

None Outage:Health:

RFO-24 Outage Milestones met:

Generation Health:

No adverse impact on generation by FAC Program issues or component failures. No transients or power reductions were reported as a result of a FAC Program issue this quarter.

Page 13 of 41

22-Jan-04

ENTERGYNORTHEAST VERMONT YANKEE engineering program health

Accelerated Corrosion Program (FAC)

FAC

Owner: Jim FitzPatrick

Phone: 802.451-3086

Frequency: Quarterly

Controlling Document: PP 7028

Date:

Program Color: . Trend:

2003-Q3 Crean Steady Ø

18-Nov-03

2002-Q3 2002-Q4 N/A N/A 2003-Q1 2003-Q2

Current Status: Program is Green, based on 19 Green; 3 White; 0 Yellow; and 0 Red.

Current Status Basis:

Current Program Trend: Steady **Current Activitie**

ENN FAC Working group formed (two meetings held). Standardization of ENN FAC Programs is a focus of the group. Each plant is to have a focused self-assessment performed. A significant effort was required to develop the standardized evaluation criteria to perform these SAs per new ENN procedure ENN-LL-104

Qualitative studies & evaluations were performed in support of September EPU submittal

A Focused Self Assessment (per ENN-LI. 104) of the VY FAC Program was started on 9/29/03. Results will be incorporated into the 4th Qtr Health Report.

REGULATORY

No FAC Program Related LERs this quarter

No NRC Findings

NEO Empines

No INPO Findings or AFIs GL 91-18 and On Det

No GL 91-18 issues or operability evaluations related to the FAC Program this quarter. Regulatory Compliance

No Regulatory Compliance issues related to the FAC Program this quarter.

ASME Code Case N-597 was incorporated into R.G 1.147. This will affect DP-0072 and transition to ENN-DC-133. Meetings scheduled for 4th qtr. to evaluate.

ADMINISTRATIVÉ:

There are no procedure/program compliance issues associated with the FAC Program.

Budget, Resources:

Rating White.

2003-2004 Budget per supervisor Schedule was set prior to EPU. For 2003 scheduling of FAC Program activities has been shifted to allow for engineering support off EPU and emergent work. FAC Program personnel were utilized on EPU related design changes and calculations

Pin I

There were no Audits performed for this

quarter. There are no open issues

LO-VTYLO-2002-00441 (2 extensions.) LO-VTYLO-2002-00568 (1 extension) LO-VTYLO-2003-00327 (1 extension) LO-VTYLO-2002-00528 (1 extension.) Note all 5 extensions during qtr. are due to EPU work

S.A. VYM SA 2002-003 on Davis Besse Issues performed in Nov.2002.

Focused Self Assessment of VY FAC Program per ENN-LI-104 started 9/29/03. Significant effort was required to develop evaluation criteria was required by FAC Working Group.

Page 11 of 38

Ailestones, new:

None This Qtr.

Engineering Issues:

ASME Code Case N-597 was incorporated into R.G 1.147. (DP0072). Transition to ENN-DC-133. Meetings scheduled for 4th qtr. to evaluate. Standardization ENN FAC Programs

CORRECTIVE ACTIONS

Significant CR

No significant CR's were written against the FAC program for this quarter. Existing VY commitments are equivalent to LO-CAs

Open CR CAs:

CR-VTY-2002-2568 (5/4/04)

EQUIPMENT

Open Eng Req:

N/A; Engineering Requests not yet implemented at Vermont Yanke

Operator Work Around

N/A - There are no operator works around related to the FAC program.

Prog Related LCOs

N/A - There are no LCOs related to the FAC program this qtr.

PMs Within Due Date

N/A - There are no PMs associated with the FAC program:

Répetitive Fallures

N/A - There are no repetitive equipment related issues for the FAC program this quarter.

Unanticipated Fallures:

White

Turbine Bypass Valve Steam Seat Plping. Additional inspections scheduled for 2004RFO, Also scoping to replace with FAC resistant material.

Trending Results:

N/A

11-Dec-03

ENTERGY NORTHEAST VERMONT YANKEE Engineering programhealth

Flow-Accelerated Corrosion Program (FAC)

FAC

Controlling Document: PP 7028

Owner: Jim FitzPatrick

Phone: 802.451-3086

Frequency: Quarterly

Open Work Requests:

N/A - There are no work requests over 2 yrs

Surveillances Within

All inspections scheduled in previous outages were performed. RFO 2004 scope is currently being scheduled.

Significant Parts Issues:

N/A - There are no parts issues associated with the FAC program this quarter

Identified Concerns:

Rating White

Leak in TBV Steam Seat Leakoff piping has elevated the need to complete the update of the small bore piping database (Action Plan: Currently on EWC FAC Program schedule).

Scheduled FAC program activities for qtr. were not performed due to resources spent on EPU related work. (Action Plan: Activities were rescheduled in EWC into 4th qtr. 2003 % 1st qtr. 2004)

Potential Issue: Based on experience to date, the transition to ENN procedures is trending toward standardization in name only. The concern is that previous efficiencies at VY will be lost when new ENN procedures modeled on large utility organizations, which require an army to implement, are imposed on the program. (Proposed Action Plan is to participate in transition working groups to control direction of transition or alert management to start hiring.)

ORGANIZATION:

Staff Qual and Trno:

The program owner is qualified to perform FAC Program tasks.

Bench Strength:

The program owner for and backup (T. O'Connor) are FAC qualified personnel. An additional engineer in M/S (R. Omer) has FAC related experience.

Program Ownership:

Based on pending results form recent SA the answer is yes.

HUETOS

here were no human performance errors associated with the FAC program this otr.

AP0098 Expectations:

Operating Experience: N/

See 2004 RFO FAC Program Scoping Worksheets for detailed list.

CPIS: None

Outage Perf.

RFO-24 Outage Milestones met.

Generation Health? Generation Health:

No adverse impact on generation by FAC Program issues or component failures. No transients or power reductions were reported as a result of a FAC Program issue this quarter.

Page 12 of 38

11-Dec-03