

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

March 1, 1982

WBRD-50-390/82-22, -391/82-20
BLRD-50-438/82-15, -439/82-15
HTRD-50-518/82-09, -519/82-08,
-520/82-09, -521/82-08
PBRD-50-553/82-08, -554/82-08
YCRD-50-566/82-08, -567/82-08



02 MAR 5 ALL: 10

USNRC REGION II
ATLANTA, GEORGIA

U.S. Nuclear Regulatory Commission
Region II
ATTN: James P. O'Reilly, Regional Administrator
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR, BELLEFONTE, HARTSVILLE, PHIPPS BEND, AND YELLOW CREEK
NUCLEAR PLANTS - REPORTABLE DEFICIENCY - REVIEW OF PROCUREMENT
SPECIFICATIONS FOR QUALITY CONTROL REQUIREMENTS -WBRD-50-390/82-22,
-391/82-20 - BLRD-50-438/82-15, -439/82-15 -HTRD-50-518/82-09,
-519/82-08, -520/82-09, -521/82-08 -PBRD-50-553/82-08, -554/82-08 -
YCRD-50-566/82-08, -567/82-08

The subject deficiency was initially reported to NRC-OIE, Region II,
Inspector Don Quick on January 20, 1982 as NCR M80-11 Deficiency
No. 9. In compliance with paragraph 50.55(e) of 10 CFR Part 50, we
are enclosing our first interim report on the subject deficiency.
As discussed with NRC-OIE Inspector Ross Butcher on February 19,
1982, a ten-day extension was granted on the submittal of this
report. TVA anticipates transmitting the next report on or before
May 21, 1982. If you have any questions, please call Jim Domer for
BWRs at FTS 858-2725 or Ralph Shell for PWRs at FTS 858-2676.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. R. C. DeYoung, Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

8203180188 820301
PDR ADOCK 05000390
PDR
S

OFFICIAL COPY

TE 27:11