

APPENDIX A
NOTICE OF VIOLATION

Tennessee Valley Authority
Watts Bar Unit 1

Docket No. 50-390
License No. CPPR-91

As a result of the inspection conducted on September 12 - 16, 1983, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion V requires that activities affecting quality shall be accomplished in accordance with instructions, procedures, or drawings. This requirement is implemented by the licensee's approved Quality Assurance Program, TVA-TR75-1, and the Operational Quality Assurance Manual (OQAM), Part II, Section 4.1 of the Preoperational Test Program.

Contrary to the above, preoperational testing was not performed as required by OQAM, Part II, Section 4.1, in that a safety-related test change was implemented prior to review and approval by the Plant Operations Review Committee and the Plant Superintendent.

This is a Severity Level IV Violation (Supplement II). This violation applies to Unit 1 only.

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: SEP 30 1983