

TENNESSEE VALLEY AUTHORITY

5N 157B Lookout Place

APR 22  
April 14, 1988

WBRD-50-391/84-29

U.S. Nuclear Regulatory Commission  
Region II  
Attn: Dr. J. Nelson Grace, Regional Administrator  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Dear Dr. Grace:

WATTS BAR NUCLEAR PLANT UNIT 2 - ERRATIC OPERATION OF STEAM GENERATOR BLOWDOWN  
ISOLATION VALVES - WBRD-50-391/84-29 - SUPPLEMENTAL FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
P. E. Fredrickson on June 11, 1984 in accordance with 10 CFR 50.55(e) as NCR  
WBN NEB 8407. Our last report on this item was submitted on September 14,  
1984. This constitutes our supplemental final report.

As discussed with Bob Carroll on January 30, 1986, the date of October 1, 1985  
for completion of the corrective actions indicated in our final report was not  
met. The wiring modifications for the unit 2 valves were delayed because of  
the stop work order on cables. The corrective action on this matter will be  
completed by unit 2 fuel load.

If you have any questions, please get in touch with R. H. Shell at  
FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY



R. L. Gridley  
Manager of Licensing

cc: Mr. James Taylor, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Records Center  
Institute of Nuclear Power Operations  
1100 Circle 75 Parkway, Suite 1500  
Atlanta, Georgia 30339

8605050535 860414  
PDR ADOCK 05000391  
S PDR