



BW/IP International, Inc.

Byron
Jackson
Pumps
United
Centrifugal*
Pumps
Pump
Division

P.O. Box
2017
GMF

Los Angeles
California
90051

Telephone
213 587 6171
Fax
213 589 2080

10 December 1993

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

On February 12, 1993, BW/IP transmitted a Notification of Defect and Nonconformance, Number CFRN-93-01, reporting a condition affecting BW/IP 4-inch, 150# bolted bonnet swing check valves which have a disc and stud retention weld on the back surface of the disc.

This supplement transmits the location of the affected valves as required by CFR, Part 21.

Very truly yours,

D. A. Gibson
Manager Nuclear Products Operations

DAG/ah

Attach.

cc: Mr. F. Costanzo, Manager of Engineering
Mr. R. D. Ham, Manager of Quality
Mr. K. A. Huber, Technical Liaison
Mr. W. A. Klenner, Product Manager
Mr. K. B. Lemmon, Field Service Operations

9312170157 931210
PDR ADOCK 05000259
S PDR

IF19
11

ATTACHMENT A
TO
NOTIFICATION OF DEFECTS & NONCONFORMANCES
NO. CFR-93-01

LOCATION OF EQUIPMENT

1. Florida Power & Light, St. Lucie Station
2. Texas Utilities Generating Co., Comanche Peak Station
3. Washington Public Power Supply System, WNP-3 SATSOP
4. Tennessee Valley Authority, Browns Ferry Station
5. Tennessee Valley Authority, Watts Bar Station
6. Arkansas Power and Light, ANO-1
7. Arizona Public Service Co., Palo Verde Station
8. Cleveland Electric Illuminating Co., Perry Nuclear Station
9. Duke Power Company, McGuire Station
10. Duke Power Company, Catawba Station