

Jamco America Inc.
1018 80th Street SW
Everett, WA 98203, USA

tel 425.347.4735
fax 425.355.0237



Dated 8/5/08

Corrections to letter sent 6/30/08

Attn: Richard K. Struckmeyer
State Agreements & Industrial Safety Branch
Division of Materials Safety and State Agreements
Office of Federal and State Materials and Environmental Management Programs
U.S. Nuclear Regulatory Commission
301-415-5477

Hello Mr. Struckmeyer,


I have reviewed the documents listed on our application.

- A. Application dated March 24, 1986
- B. Letters dated August 18, August 26, and September 17, 1986
- C. Letter dated April 16, 1987; and
- D. Application dated July 09, 2002

With the exception of the changes that I noted on my application dated 4/23/08, there are no other changes from the application dated July 09, 2002.

I have reviewed the leak test process and it, states that each sensor will be tested at the sub contractor in Japan, prior to shipment to Jamco America. I agree that this is insufficient testing; and I will revise our procedure to test each sensor during the build cycle of each smoke detector, here at Jamco America.

Thank You Very Much:



Randy L. Moser

QC Manager, Jamco America, Inc.