

TIC



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION II  
101 MARIETTA ST., N.W., SUITE 3100  
ATLANTA, GEORGIA 30303

NOV 30 1979

In Reply Refer To:

- RIL: JPO
- 50-438, 50-439
- 50-518, 50-519
- 50-520, 50-521
- 50-553, 50-554
- 50-328, 50-391
- 50-566, 50-567

ALL

Tennessee Valley Authority  
Attn: H. G. Parris  
Manager of Power  
500A Chestnut Street Tower II  
Chattanooga, Tennessee 37401

Gentlemen:

The enclosed IE Bulletin No. 79-27, is forwarded to you for information. Although no written response is required at this time, these concerns will be addressed as part of the licensing process for your plant. If you desire additional information regarding this matter, please contact this office.

Sincerely,

  
James P. O'Reilly  
Director

Enclosures:

- 1. IE Bulletin No. 79-27
- 2. List of Recently Issued  
IE Bulletins

1790 342

7912190 478

Q

Tennessee Valley Authority

-2-

cc w/encl:

A. M. Qualls  
Plant Superintendent  
Post Office Box 2000  
Hollywood, Alabama 35752

W. R. Dahnke, Project Manager  
Post Office Box 2000  
Hollywood, Alabama 35752

J. F. Cox  
400 Commerce Street  
W10C131 C-K  
Knoxville, Tennessee 37902

D. L. Terrill  
Project Engineer  
400 Chestnut Street Tower II  
Chattanooga, Tennessee 37401

R. T. Hathcote, Project Manager  
Post Office Box 2000  
Hartsville, Tennessee 37074

J. E. Wills, Project Engineer  
400 Chestnut Street Tower II  
Chattanooga, Tennessee 37401

W. P. Kelleghan, Project Manager  
Post Office Box 2000  
Surgoinsville, Tennessee 37873

G. G. Stack, Project Manager  
Post Office Box 2000  
Daisy, Tennessee 37319

E. G. Beasley  
Tennessee Valley Authority  
309 Grant's Building  
Knoxville, Tennessee 37902

cc w/encl: (Continued on Page 3)

1790 343

NOV 30 1979

Tennessee Valley Authority

-3-

cc w/encl: (Continued from Page 2)

J. M. Ballentine  
Plant Superintendent  
Post Office Box 2000  
Daisy, Tennessee 37319

D. L. Lambert, Project Engineer  
400 Chestnut Street Tower II  
Chattanooga, Tennessee 37401

J. F. Groves, Plant Superintendent  
Post Office Box 2000  
Spring City, Tennessee 37381

T. B. Northern, Jr., Project Manager  
Post Office Box 2000  
Spring City, Tennessee 37381

M. M. Price, Project Manager  
Post Office Box 2000  
Iuka, Mississippi 38852

1790 344

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

SSINS No.: 6820  
Accession No.:  
7910250499

November 30, 1979

IE Bulletin No. 79-27

LOSS OF NON-CLASS 1E INSTRUMENTATION AND CONTROL POWER SYSTEM BUS  
DURING OPERATION

Description of Circumstances:

On November 10, 1979, an event occurred at the Oconee Power Station, Unit 3, that resulted in loss of power to a non-class 1E 120 Vac single phase power panel that supplied power to the Integrated Control System (ICS) and the Non-Nuclear Instrumentation (NNI) System. This loss of power resulted in control system malfunctions and significant loss of information to the control room operator.

Specifically, at 3:16 p.m., with Unit 3 at 100 percent power, the main condensate pumps tripped, apparently as a result of a technician performing maintenance on the hotwell level control system. This led to reduced feedwater flow to the steam generators, which resulted in a reactor trip due to high coolant system pressure and simultaneous turbine trip at 3:16:57 p.m. At 3:17:15 p.m., the non-class 1E inverter power supply feeding all power to the integrated control system (which provides proper coordination of the reactor, steam generator feedwater control, and turbine) and to one NNI channel tripped and failed to automatically transfer its loads from the DC power source to the regulated AC power source. The inverter tripped due to blown fuses. Loss of power to the NNI rendered control room indicators and recorders for the reactor coolant system (except for one wide-range RCS pressure recorder) and most of the secondary plant systems inoperable, causing loss of indication for systems used for decay heat removal and water addition to the reactor vessel and steam generators. Upon loss of power, all valves controlled by the ICS assumed their respective failure positions. The loss of power existed for approximately three minutes, until an operator could reach the equipment room and manually switch the inverter to the regulated AC source.

The above event was discussed in IE Information Notice No. 79-29, issued November 16, 1979.

NUREG 0600 "Investigation into the March 28, 1979 TMI Accident" also discusses TMI LER 78-021-03L whereby the RCS depressurized and Safety Injection occurred on loss of a vital bus due to inverter failure.

Actions to Be Taken by Licensees

For all power reactor facilities with an  
completion of construction (North Anna 2,  
Sequoyah, and Zimmer):

1790 345

DUPLICATE DOCUMENT

Entire document previously  
entered into system under:

AND

7910250499

No. of pages: 4