UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D.C. 20555

OCTOBER 28, 1983

IE INFORMATION NOTICE 83-72: ENVIRONMENTAL QUALIFICATION TESTING EXPERIENCE

Addressees:

All holders of a nuclear power reactor operating license (OL) or construction permit (CP).

Purpose:

This information notice is provided to inform the licensees of environmental : qualification test failures. These test failures are based on (1) Construction Deficiency Reports and 10 CFR Part 21 Reports submitted to the NRC, and (2) results from the NRC-sponsored environmental qualification methodology research program. This information notice also serves to inform the licensees of findings that resulted from inspections conducted by the licensee or its agent of equipment that has been environmentally qualified and is being delivered or installed at the sites.

Because of the potential safety significance and related generic implications of these test failures and inspection findings, addressees are expected to review the information for applicability to their facilities. No specific response to this information notice is required.

Description of Circumstances:

The NRC has received a number of Construction Deficiency Reports and 10 CFR Part 21 Reports from licensees and vendors of safety-related Quipment. These reports describe a number of test failures and the circumstances under which the equipment failed to function during environmental qualification testing. These reports also indicate that there are a number of instances in which " delivered equipment and components contained material that did not conform to standards for safety, thus rendering the qualified equipment and components unqualified. In addition to the monitoring and assessing of environmental qualification information received from the industry, the NRC has also sponsored a number of qualification methodology research program, which has resulted in a number of adverse test results. This information notice is published with the following objectives:

 To disseminate the information on matters related to the environmental qualification of equipment and on test results, as received from the licensees and equipment vendors.

IN 83-October , 1983 Page 2 of 2

- 1. To disseminate the information on matters related to the environmental qualification of equipment and on test results, as received from the licensees and equipment vendors.
- 2. To disseminate the results of NRC-sponsored environmental qualification tests which were recently completed.
- 3. To provide the licensees with the status of NRC inspection on quality assurance activities at the environmental testing laboratories.

The enclosed series of Qualification Notices (Attachment 1) describes the circumstances of each failure, failure mode, and qualification concerns as described in various reports and sources indicated above. Please note that for items in Qualification Notices No. 14 through 19 the vendors have issued service instructions to the affected users regarding corrective action to be taken.

Questions regarding the details of tests described in Attachment 1 should be directed either to the equipment manufacturer or the cognizant design/test agency. If you have other questions regarding this information notice, please contact the Regional Administrator of the appropriate NRC Regional Office, or this office.

> E. L. Jordan, Director Division of Emergency Preparedness and Engineering Response Office of Inspection and Enforcement

Attachments:

1. Series of Equipment Environmental Qualification Notices

2. List of Recently Issued IE Information Notices

Technical Contact: N. B. Le, IE (301) 492-9673

RCPB: OASIP: IE

RCPB:QASIP:IE* TLe/vjj 09/ /83 Tech Editor* RCPB:QASI RSanders MPeranich 09/ /83 09//3/83

RCPB: OASIP: IE

RHeishman

09

783

DD: OASIP: IE JPart low X/83

*See previous concurrence

- To disseminate the information on patters related to the environmental qualification of equipment and on test results, as received from the licensees and equipment vendors.
- To disseminate the results of NRC-sponsored environmental qualification tests which were recently completed.
- 3. To provide the licensecs with the status of NRC inspection on quality assurance activities at the environmental testing laboratories.

The enclosed series of Qualification Notices (Attachment 1) describes the circumstances of each failure, failure mode, and qualification concerns as described in various reports and sources indicated above. Please note that for items in Qualification Notices No. 14 through 19 the vendors have issued service instructions to the affected users regarding corrective action to be taken.

directed either to the equipment manufacturer or the cognizant design/test agency. If you have other questions regarding this information notice, please contact the Regional Administrator of the appropriate NRC Regional Office, or this office.

> E. L. Jordan, Director Division of Emergency Preparedness and Engineering Response Office of Inspection and Enforcement

Attachments:

1

•

.*

1. Series of Equipment Environmental Qualification Notices

2. List of Recently Issued IE Information Notices

Technical Contact: N. B. Le, IE (301) 492-9673

RCPB:QASIP:IE TLe/vjj 09/12/83	Tech Editor RSanders 09/12/83 9/19/5 3	RCPB:QASIP:IE MPeranich 09/ /83	RCPB:QASIP:1E RHeishman 09/ /83	DD:QASIP:IE JPartlow 09/ /83
	119/13			

DIR: QASIP: IE	D: DEPER: IE
JTaylor	EJordan
09/ /83	09/ /83

 To disseminate the results of NRC-sponsored environmental qualification tests which were recently completed.

The enclosed series of Qualification Notices (Attuchment 1) describes the circumstances of each failure, failure mode, and qualification concerns as described in various reports and sources indicated above. Please note that for items in Qualification Notices No. 14 through 19 the vendors have issued service instructions to the affected users regarding corrective action to be taken.

Questions regarding the details of tests described in Attachment 1 should be directed either to the equipment manufacturer or the cognitant design/test agency. If you have other questions regarding this information notice, please contact the Regional Administrator of the appropriate NRC Regional Office, or this office.

> [. L. Jordan, Director Division of Emergency Preparedness and Engineering Response Office of Inspection and Enforcement

Attachments:

- 1. Series of Equipment Environmental Qualification Notices
- 2. List of Recently Issued IE Information Notices

1

Technical Contact: N. B. Le, IE (301) 492-9673

RCPB:QASIP:IE*	Tech Editor*	RCPB:QASIP:1	E * RCPB:QASIP:IE *	DD:QASIP:IE
TLe/vjj	RSanders	MPeranich	RHeishman	JPartlow
09/ /83	09/ /83	09/ /83	09/ /83	09/ /83

DIR:QASIP:IE * D:DEFER:IE JTaylor EJordan 09/ /83 09/ /83

*See previous concurrence

Attachment 1 IN 83-72 October 28, 1983 Page 1 of 16

٠

Equipment Environmental Qualification Notice No. 12

Related Information Notices

 Information Notices relating to environmental qualification of equipment that have been published since IN 82-52, which included Equipment Environmental Qualification Notices No. 1 through No. 11, are:

IN 83-40 Need To Environmentally Qualify Epoxy Grouts and Sealers

IN 83-45 Environmental Qualification Test of General Electric Company "CR-2940" Position Selector Control Switch

 The Equipment Environmental Qualification Notices issued to date (No. 1 through No. 24) will be updated, if required, in the next periodical information notice.

•

Attachment 1 IN 83-72 October 28, 1983 Page 2 of 16

Equipment Environmental Qualification Notice No. 13

Test Summary Report No. 1

Equipment: Anaconda flexible conduit

Test Facility: Wyle Laboratories

Cognizant Design and/or Test Agency: Washington Public Power Supply System (WPPSS)

Failed Component: Anaconda flexible conduit

Type of Test: Environmental qualification testing at LOCA conditions

Description of Failure(s):

Polyethylene copolymer jacket of the flexible conduit degraded while exposed to the following LOCA conditions:

340°F and 45 psig for 3 hr. 320°F and 45 psig for 3 hr. 250°F and 25 psig for 18 hr.

Failure Node:

Polyethylene copolymer jacket melted while exposed to LOCA temperature, pressure, and steam environment.

Possible Corrective Action Considerations:

WPPSS is reviewing the failure, and will report corrective action at a later date.

Generic Implications:

Melted polyethylene jacket would allow steam and spray solution to enter otherwise watertight junction boxes, and equipment housings. This in turn will cause degradation and short-circuiting of other safety-related components or electrical circuits inside the junction boxes and equipment housings.

Attachment 1 IN 83-72 October 28, 1983 Page 3 of 16

Equipment Environmental Qualification Notice No. 14

Test Summary Report No. 1

Equipment: Rockwell International post-LOCA hydrogen recombiner

Test Facility: Wyle-Norco

Cognizant Design and/or Test Agency: Rockwell International (RI) Energy Systems Group (ESG)

Failed Component: ITT Barton pressure transducer, 4-20 ma, part number . D4R-29098

Type of Test: Typical IEEE 323 environmental qualification

Description of Failure(s):

ITT Barton pressure transducers, will not withstand radiation dose of 1×10^7 rads (and may not operate satisfactorily after radiation exposures in excess of 10^4 rads TID because of gradual drifting of readings). These pressure transducers are installed in several delivered recombiners and are used to measure recombiner inlet gas flow, total flow, and inlet gas pressure.

Failure Mode:

Pressure transducer did not operate satisfactorily after exposure to radiation dosage in excess of 10⁴ rads.

Possible Corrective Action Considerations:

ESG recommended the following corrective action to each affected customer, as a short-term corrective measure for operating plants: Temporary wiring modification in the control cabinet should be made to allow operation of the recombiner in the manual flow control mode, until the transducer can be replaced with a gualified transducer.

Generic Implications:

Rockwell International reported that recombiners with ITT-Barton transducers were shipped to the following plants: Limerick, LaSalle County, Nine Mile Point 2, E. I. Hatch 2, and Fermi 2.

Attachment 1 IN 83-72 October 28, 1983 Page 4 of 16

Equipment Environmental Qualification Notice No. 15

Test Summary Report No. 1

Equipment: Rockwell International Post-LOCA hydrogen recombiner

Test Facility: Wyle-Norco

Cognizant Design and/or Test Agency:

Rockwell International (RI) Energy Systems Group (ESG)

Failed Component: Microswitch, DPST toggle switch, rated 15A, 125-250 VAC, 1/2 hp, 125 VAC, part number 12TSI-2.

Type of Test: Typical IEEE 323 environmental qualification

Description of Failure(s):

Both poles of the microswitch failed to close when the switch was activated during the post-LOCA environmental cycling test. It was noted that during the post-seismic functional test, the switch operation appeared to be weak and not as firm as normal. Disassembly and examination of the switch revealed that the plastic slides were missing and there was considerable debris around the switch's operating handle.

Failure Mode:

ESG concluded that the plastic slides were sufficiently degraded during the thermal and radiation aging that when the switch was exposed to the vibration and shock from the seismic test, the plastic slides broke into many pieces (when the switch was operated on with snap action).

Possible Corrective Action Considerations:

Engineering Field Bulletins have been issued by RI informing users to install jumpers bypassing the switch. RI has eliminated the switch in its recent a designs.

Generic Implications:

The switch is used in the control circuits of the reversing motor starters for the hydrogen recombiner motor-operated valves. Rockwell International reported that recombiners with microswitches were shipped to the following plants: Fermi 2, Shoreham 1, Limerick, E. I. Hatch 2, Nine Mile Point 2, and LaSalle County.

Attachment 1 IN 83-72 October 28, 1983 Page 5 of 16

Equipment Environmental Qualification Notice No. 16

Test Summary Report No. 1

Equipment: Rockwell International post-LOCA hydrogen recombiner

Test Facility: Wyle-Norco

Cognizant Design and/or Test Agency: Rockwell International (RI) Energy Systems Group (ESG)

Failed Component: Square D disconnect switch, three-pole nonfusible unit, 30A, 15 hp at 480 VAC or 20 hp at 600 VAC, part number 9422-RC-1.

Type of Test: Typical IEEE 323 environmental qualification

Description of Failure(s):

Square D disconnect switch, failed to operate following the irradiation phase of the EQ test. ESG concluded that the applied radiation dose of 1.1×10^7 rads has sufficiently degraded the plastic component to initiate the failure.

Failure Mode:

The failure is attributed to a plastic component breaking when the switch was mechanically operated.

Possible Corrective Action Considerations:

ESG recommended that the users of the RI recombiner eliminate the disconnect switch from the circuit.

Generic Implications:

The switch is used as the main disconnect for the recombiner skid 480-VAC . 3-phase, power bus to the inlet gas, recirculating gas and water valve motor circuits. The switch could fail open during a seismic event following the LOCA, thus disrupting power to the recombiner skid. Rockwell International reported that recombiners with Square D disconnect switches were shipped to the following plants: Limerick, LaSalle County, Nine Mile Point 2, E. I. Hatch 2, and Fermi 2.

Attachment 1 IN 83-72 October 28, 1983 Page 6 of 16

Equipment Environmental Qualification Notice No. 17

Test Summary Report No. 1

Equipment: Rockwell International post-LOCA hydrogen recombiner

Test Facility: Wyle-Norco

<u>Cognizant Design and/or Test Agency</u>: Rockwell International (RI) Energy Systems Group (ESG)

Failed Component: Timetrol SCR power controller, three-phase, 1066Z series, part number 2053C-125K

Type of Test: Typical IEEE 323 environmental qualification

Description of Failure(s):

The Timetrol SCR power controller failed the functional testing after the unit was irradiated. The SCR controller controls the recombiner's heaters.

Failure Mode:

•

The SCR power controller failed after being exposed to radiation dose of 1.62×10^6 rads.

Possible Corrective Action Considerations:

ESG recommended that the users of the RI recombiner replace the Timetrol SCR unit with a unit compatible with ESG current design.

Generic Implications:

Rockwell International reported that recombiners with Timetrol SCR power controllers were shipped to the following plants: Fermi 2, Limerick, Beaver Valley, North Anna, Millstone 3, Three Mile Island 2, and Zion.

Attachment 1 IN 83-72 October 28, 1983 Page 7 of 16

:

Equipment Environmental Qualification Notice No. 18

Test Summary Report No. 1

Equipment: Rockwell International post-LOCA hydrogen recombiner

Test Facility: Wyle-Norco

Cognizant Design and/or Test Agency: Rockwell International (RI) Energy Systems Group (ESG)

Failed Component: Automatic Timing & Control (ATC) time delay relay, 120 VAC, 50-60 Hz, part number 319B006QIC, IEEE No. 21A.

Type of Test: Typical IEEE 323 environmental qualification

Description of Failure(s):

Automatic Timing and Control (ATC) time delay relay failed the final performance test following the post-LOCA environmental cycling test. The relay failed when the unit was subjected to an elevated temperature test with high humidity (RH greater than 90 percent). The relay coil of the timer was energized and after one cycle, it failed to hold closed.

Failure Mode:

The failure was attributed to an oxide film on the relay contacts which occurred during the EQ testing. (NOTE: The timer is not a sealed unit)

Possible Corrective Action Considerations:

Because the ATC time delay is not a sealed unit, ESG recommended the existing timer for BWR Mark 3 and PWR plants be replaced with an EQ qualified, sealed timer. However for BWR Mark 1 and 2, ESG stated that the replacement of the existing timer is not necessary, because the loss of this timer on the BWR . Mark 1 and 2 hydrogen recombiners should not result in a loss of safety function.

Generic Implications:

Rockwell International reported that recombiners with ATC time delay relays were shipped to the following plants: Beaver Valley, North Anna, Surry, Millstone 3, Three Mile Island 2, Palo Verde, Hartsville, Phipps Bend, Clinton, Byron, Cherokee, Perkins, Oconee, Marble Hill, Braidwood, and Zion.

Attachment 1 IN 83-72 October 28, 1983 Page 8 of 16

Equipment Environmental Qualification Notice No. 19

Test Summary Report No. 1

Equipment: Rockwell International post-LOCA hydrogen recombiner

Test Facility: Wyle-Norco

<u>Cognizant Design and/or Test Agency</u>: Rockwell International (RI) Energy Systems Group (ESG)

Failed Component: ITE Gould circuit breaker, 3-pole, 600 VAC, fully enclosed, thermal magnetic, part number EF3-B015, IEEE No. 79

Type of Test: Typical IEEE 323 environmental qualification

Description of Failure(s):

The ITE Gould circuit breaker opened when temperature reached 165°F (150°F design plus 15°F margin) and also opened at post-test ambient temperature during the post-LOCA phase of the EQ testing. After this failure, a new EF3-B015 circuit breaker was tested under the same test condition as in the previous test and it was observed that the circuit breaker tripped without carrying any load current when the test temperature reached 169°F at high relative humidity. Additional testing was performed and the result was that the same breaker would trip at 145°F. To establish the temporations at which the EF3-B015 circuit breaker would carry the required load w tripping, ESG performed several tests and reported that the circuit br id not trip at 140°F while carrying 3.5 amperes, and the breaker remained clused after several days at 130°F with 3.5-ampore load current. ESG also reported that discussion with ITE Gould personnel indicates this potential failure problem may be common to several lines of ITE thermal magnetic circuit breakers at temperatures greater than 120°F. These circuit breakers include type EF2-B, EF3-B, HE3-B, and JL3-B, all of which have been used in recombiner application; however, no testing has yet been performed on these models.

Failure Mode:

The ITE Gould circuit breaker opened when ambient temperature reached 165°F.

Possible Corrective Action Considerations:

The ITE Gould circuit breakers are used to provide 480 VAC to various RI recombiner components and control devices. The failure of these breakers would prevent the operation and cause the recombiner to shut down. ESG has informed the users of RI recombiners about this potential defect and recommended that as an interim fix, the circuit breaker be bypassed and as an alternative fix, the power cabinet be relocated. Supplemental cooling to reduce the cabinet temperature to less than 100°F for PWR recombiners is also recommended.

Attachment 1 IN 83-72 October 28, 1983 Page 9 of 16

:

Equipment Environmental Qualification Notice No. 19 (Cont.)

Test Summary Report No. 1 (Cont.)

Possible Corrective Action Considerations (Cont.):

ESG states that replacement of the "thermal magnetic" breakers with "magnetic only" breakers is being considered as the permanent fix on the RI recombiners.

Generic Implications:

. .

Rockwell International reported that recombiners with ITE Gould circuit breakers were shipped to the following facilities: Fermi 2, Shoreham 1, E. I. Hatch 2, Nine Mile Point 2, LaSalle County, Hartsville, Phipps Bend, Clinton, Byron, and Palo Verde.

Attachment 1 IN 83-72 October 28, 1983 Page 10 of 16

Equipment Environmental Qualification Notice No. 20

Test Summary Report No. 1

Equipment: ITT-Barton electronic transmitters

Test Facility: ITT

Cognizant Design and/or Test Agency: ITT-Barton

Failed Component: Barton transmitter, suppressed zero model 763

Type of Test: Performance test

Description of Potential Failure(s):

The potential defect exhibits itself as a negative shift in output during initial exposure to operating pressure. The amount of the shift is a function of the process pressure and the calibrated span of the instrument.

Failure Mode:

ITT-Barton reported that further testing of model 763 pressure transmitter has identified the specific cause for the reported defect. It is due to the combined creep in:

- 1. The link wire between the pressure bourdon tube and strain-sensing beam, and
- The material used to attach the link wire to the bourdon tube and to the strain-sensing beam.

Long-term testing on the 763 pressure transmitter is continuing.

Possible Corrective Action Considerations:

The failure is under review by ITT. Users of this instrument are expected to take necessary administrative control and inform their plant staff of the potential defect.

Generic Implications:

ITT-Barton reported that all suppressed zero model 763 transmitters shipped prior to June 30, 1983, may not perform to Barton's specifications.

Attachment 1 IN 83-72 October 28, 1983 Page 11 of 16

Equipment Environmental Qualification Notice No. 21

Test Summary Report No. 1

Equipment: Barksdale pressure switches

Test Facility: Sandia National Laboratories (SNL)

Cognizant Design and/or Test Agency: NRC/RES

Failed Components: Barksdale pressure switches models B2T and D2H

Type of Test: Typical IEEE 323 LOCA simulation

Description of Failure(s):

One unit of model B2T shorted out at 5 minutes into the test but recovered on the cooling side of the first temperature transient, then failed again on the next LOCA profile temperature transient. The second unit of model B2T failed at 6 hours, 43 minutes into the test. Two units of model D2H shorted out at 10 minutes into the test but recovered on the cooling side of the first LOCA profile temperature transient, then failed again on the next LOCA profile temperature. These pressure switches were unaged and were exposed to a typical IEEE 323 LOCA simulation profile in the SNL facility test chamber which used saturated steam to achieve a LOCA temperature profile. An evaluation test was also performed on new pressure switches of the same models previously tested. It was observed that at the 10 psig plateau one Barksdale model D2H was shorted out. All other D2H and B2T models failed at the 40 psig plateau.

Failure Mode:

Pressure switches experienced "blown" seals that allowed water to accumulate in the switch housing, and as a result, exhibited electrical shorts across the microswitches.

Possible Corrective Action Considerations:

NRC is planning no further testing on these models at this time. Barksdale pressure switch models B2T and D2H should be replaced with qualified models if their application is for installation in areas where high pressure and steam/spray environment are anticipated.

Generic Implications:

The failure of the pressure switch could prevent proper operation of safetyrelated functions and could lead to inappropriate operator actions.

Attachment 1 IN 83-72 October 28, 1983 Page 12 of 16

Equipment Environmental Qualification Notice No. 22

Test Summary Report No. 1

Equipment: Static-O-Ring pressure switches

Test Facility: Sandia National Laboratories (SNL)

Cognizant Design and/or Test Agency: NRC/RES

Failed Components: Static-O-Ring (SOR) model 5N and 12N

Type of Test: Typical IEEE 323 LOCA simulation

Description of Failure(s):

One unit of model 5N failed in the first 2 minutes, and other units of model 5N and model 12N failed approximately 5 minutes into the LOCA transient. Pressure switch housings were penetrated resulting in diaphragm rupture and steam blowing out through pressure lines. These pressure switches were unaged and were exposed to a typical IEEE 323 LOCA simulation profile in the SNL facility test chamber which used saturated steam to achieve a LOCA temperature profile. An evaluation test was also performed on new pressure switches of same models, and similar failures were experienced.

Failure Mode:

Upon disassembly, the pressure switches were found to have "blown in" gaskets and the elastrometric diaphragms were found to have ruptured.

Possible Corrective Action Considerations:

SOR pressure switch models 5N and 12N (and other models of similar design) should be replaced with qualified models if their installation is in areas where high pressure and steam/spray environment are anticipated. NRC is planning no further testing on these models at the present time.

Generic Implications:

These pressure switches are used in various safety-related applications. The systems affected could be the residual heat removal (RHR), nuclear boiler (NB), reactor core isolation cooling (RCIC), and reactor protection system (RPS). The failure of these pressure switches could adversely affect the safe operation of the plant.

Attachment 1 IN 83-72 October 28, 1983 Page 13 of 16

Equipment Environmental Qualification Notice No. 23

Test Summary Report No. 1

Equipment: ITT-Barton electronic transmitters

Test Facility: ITT

Cognizant Design and/or Test Agency: ITT-Barton

Failed Component: Barton transmitter models M-763 and M-764

Type of Test: Performance test

Description of Failure(s):

The potential defect exhibits itself in the form of thermal non-repeatability, and results in performance outside Barton's specification. Transmitters manufactured after September 1, 1981 are suspect. ITT-Barton reported that a total of 474 Barton transmitters (model M-763) and 628 Carton transmitters (model M-764) have been delivered to domestic locations.

Failure Mode:

A leakage current path through the shafts of the zero and span potentiometers to the mounting bracket was detected. This resulted in non-repeatability at 320°F, according to ITT-Barton.

Possible Corrective Action Considerations:

ITT-Barton recommends the installation of a fiberglass insulator between the potentiometer shafts and the mounting brackets. Field repair kits are being prepared by Barton for onsite correction of the leakage current problem. ITT-Barton has notified all of its customers of this potential defect.

Generic Implications:

The thermal non-repeatability of these transmitters could impede the intended function of a safety system that is actuated or controlled by these transmitters. In addition, due to the thermal non-repeatability the instrument indication in the control room could become inaccurate. Tests conducted on corrected transmitters have revealed that the test methodology used on all units identified as potentially defective contributed to the out-of-specification performance at normal temperature. Barton has provided its customers with the worst case performance data for their evaluation. Barton also states that some changes to the test methods were made, and presently the specified performance is being achieved in production.

Attachment 1 IN 83-72 October 28, 1983 Page 14 of 16

Equipment Environmental Qualification Notice No. 24

GENERIC OA PROBLEMS THE EQUIPMENT QUALIFICATION INDUSTRY

The NRC has performed several QA programmatic reviews of companies and laboratory facilities that perform tests to environmentally qualify safety-related electrical equipment used in the harsh environment. This effort was started in Tate August 1982 to assess the testing organization's establishment and implementation of the QA program based on 10 JFR Part 50, Appendix B criteria.

Ruring these QA programmatic reviews, several generic problems related to the testing industry were identified. They are as follows:

- 1. Organizations (architect engineers (AEs), manufacturers, suppliers, and testing laboratories) have failed to include 10 CFR Part 50, Appendix 8 or equivalent quality requirements and 10 CFR Part 21 requirements in : purchase orders or contracts. In one case a testing laboratory was performing environmental qualification testing without knowing it was testing safety-related electrical equipment, because the purchase order or contract did not include quality control or 10 CFR Part 21 requirements. NRC inspectors have identified many similar failures to pass on requirements between involved organizations. The NRC considers this to be a serious problem because testing without knowing the criticality of the equipment being tested would likely result in less caution during testing and little concern relative to deviation or defect reporting in accordance with 10 CFR Part 21.
- 2. A few testing facilities failed to establish and implement a QA program. Other testing facilities failed to properly implement 10 CFR Part 21.
- 3. The majority of the manufacturing test facilities and testing organizations inspected had QA programs that were deficient or nonconforming. The seriousness of these nonconformances ranged from no QA program to less serious nonconformances such as failing to follow procedures.
- 4. The generic problems described above have in most cases, been caused by the test organization's customers (manufacturer, AE, or licensee). That is, these upline customers have failed to pass on NRC requirements in procurement documents, failing to ensure that QA programs were established and properly implemented. It is apparent that the audit process (licensee to lowest subcontract tier) is not working properly. A recent example was identified in which three utilities and five AEs had performed audits of the vendor's QA program for manufacturing but had not audited the EQ test program to ensure proper establishment/implementation of the QA program.

Attachment 1 IN 83-72 October 28, 1983 Page 14 of 16

Equipment Environmental Qualification Notice No. 24

Equipment: Limitorque valve operators

Reference: Construction Deficiency Report - Part 50.55(e) Facilities: 50-329, -330

Description of Circumstances:

The Bechkel Associates Professional Corporation, A/E for Consumers Power Company's Midland Plant Units 1 and 2, has recently reported to the NRC the following deficiencies related to the Limitorque valve operators at the Midland plants.

- 1. The use of underrated terminal blocks in Limitorque operators
- 2. The use of terminal blocks without proper environmental qualification in Limitorque operators
- 3. Additional concerns regarding qualification of various Limitorque operator components

These concerns are detailed below.

A. Underrated Terminal Blocks

While replacing a damaged terminal block on a Limitorque operator, Bechtel determined that some of the terminal blocks used for the termination of the leads from the 460-volt motor were rated less than 460-volt. These Limitorque operators, when used on safety-related valves, must function on an emergency core cooling actuation signal (ECCAS). In addition to being a personnel safety hazard, the potential exists for short circuit/flashover, which could render the valves inoperative.

B. Environmental Qualification

During random inspection for underrated terminal blocks, it was discovered that, in some cases, terminal blocks were used from manufacturers not covered by existing qualification reports.

Limitorque provided the following information on environmental qualification of terminal blocks is its July 31, 1981, letter to Bechtel.

The Buchanan 0524 has been qualified by analysis. To supplement the qualification by analysis, Limitorque is currently running a type test on the Buchanan 0524 terminal block. The Buchanan 0824 terminal blocks are not qualified and must be replaced.

Attachment 1 IN 83-72 October 28, 1983 Page 15 of 16-

Equipment Environmental Qualification Notice No. 24 (Cont.)

Description of Circumstances (Cont.):

Some of the Limitorque operators having Buchanan 0824 type terminal blocks have been used on safety-related valves located inside containment. These operators must function on an ECCAS. The potential exists for a terminal block to fail during its interded service life because of aging and radiation effects, which works ender the valve inoperable and prevent proper operation of the same lated system.

C. Additional Qualification Concerns

During the month of June 1982, a random inspection was made of safetyrelated Limitorque valve operators supplied through various valve manufacturers and installed inside the reactor building. This inspection resulted in various potential concerns regarding qualification of these Limitorque operators. These concerns are:

- The motor nameplate ambient temperature rating on various motors installed on some Limitorque operators is 40°C. Limitorque has verbally stated that the Class B insulation motors rated for a 40°C ambient temperature have not undergone qualification testing in accordance with IEEE Std 382-1972 for the specified normal, accident, and postaccident environment. Class H insulation motors are rated for 50°C ambient temperature, but the qualification testing in accordance with IEEE Std 382-1972 for these motors is presently unknown.
- No identification was evident on certain materials internal to the Limitorque operators (e.g., wiring, insulation, etc.). It is not presently known whether these types are qualified for the service conditions.
- Various orientations of installed operators were observed. It is not presently known whether the operators are qualified for all installed orientations.
- 4. Drain plugs on operators were observed to be both in place and removed. Orientation of the operators did not always result in the drain holes being at the lowest point of the installed operator. It is not presently known whether the existence of the drain plug or the orientation of the drain hole is essential to proper operation of the operator or is in conformance with the qualification tests for the operator.
- 5. Various Limitorque operator limit switch gear frames were observed to be made of a white metal. It is not presently known whether these gear frames are qualified for the service conditions.

Attachment 1 IN 83-72 October 28, 1983 Page 16 of 16

Equipment Environmental Qualification Notice No. 24 (Cont.)

Description of Circumstances: (Cont.)

•

- 6. Information obtained from purchase order files and qualification files does not agree with the installed components.
- It is presently not known whether space heaters are qualified or required to be qualified.
- 8. Various O-rings are located throughout the actuator. It is not presently known whether these components are qualified for the service conditions.
- Unidentifiable terminal blocks (nonpower lead connectors inside the operators) were observed in other Limitorque operators. It is not presently known whether these components are qualified for the service conditions.

Attachment 2 IN 83-72 October 28, 1983

LIST OF RECENTLY ISSUED IE INFORMATION NOTICES

Information Notice No.	Subject	Date of Issue	Issued to
83-71	Defects in Load-Bearing Welds on Lifting Devices for Vessel Head and Internals	10/27/82	All nuclear power facilities holding an OL or CP
83-70	Vibration-Induced Valve Failures	10/27/83	All nuclear power facilities holding an OL or CP
83-69	Improperly Installed Fire Dampers at Nuclear Power Plants	10/21/83	All nuclear power facilities holding an OL or CP
83-68	Respirator User Warning - Defective Self-Contained Breathing Apparatus Air Cylinders	10/11/83	All nuclear power facilities holding an OL or CP; research and test reactors, fuel cycle licensees; Priority 1 material licensees
83-67	Emergency-Use Respirator Material Defect Causes Production of Noxious	10/11/83	All nuclear power facilities holding an OL or CP; research and test reactors, fuel cycle licensees; Priority 1 material licensees
83-66	Fatility at Argentine Critical Facility	10/7/83	All nuclear power facilities holding an OL or CP; non- power reactor, ' critical facility and fuel cycle licensees
83-65	Surveillance of Flow in RTD Bypass Loops Used in Westing- house Plants	10/07/83	All Westinghouse facilities holding an OL or CP
83-64	Lead Shielding Attached to Safety-Related Systems Without 10 CFR 50.59 Evaluations	09/29/83	All power reactor facilities holding an OL or CP

OL = Operating License CP = Construction Permit

	al manufacture of the second start and all	AND A REAL PROPERTY OF THE PARTY OF THE PART	and the second second second	A CARL CORPORE TO A CARL CONTRACTOR OF A CARL CONTRACTOR OF A CARL CONTRACTOR OF A CARL CONTRACTOR OF A CARL CONTRACT OF	CALIFORNIA CONTRACTOR OF THE OWNER OWNER OF THE OWNER OWN		ALC: CALLER OF A DECK	
TOURGSTOUR VILDING 6 R	NG CO	TOUSGSTONS USL DALE F. LESIS 04 BARAGES 3700 CARWOOD A TOUSGSTOUS	DING 6 ING C	o 3581				
174 10 10 57 55 1 1 10 10 57 55 1 10 10 10 57 55 1 10 10 57 55 1 10 10 10 10 10 10 10 10 10 10 10 10 1	29999 K 7410	174 10 109 1767 2889, 288 BES 2121 6 16 15T 8	SPER CORP	9	•			
102114040065 1 EFVITAS ASSOCIATES S0 STAVIPORD STREET BOSTOR	99999 A 02114	260099006542 ZION GPC OF NA CABL A SANGUT CONDINATOR-SI SION	1 9999 108 9999 08 8504 IL 6	9				
155144064622 1 3 CO L S MARQUARDT GARET DE SERV HEALTH ST PAUL	99999 CAL# 11 55144		2					100 L 2015
		ود: ویکی کی	C \$\$\$\$\$\$\$\$\$\$ 55 55 55 55 55 55 55 55 55 55			99999999999999999999999999999999999999		
.tt ^{rit} in		c cccccc ^{cc} sssss ccccc sssss	33333333 535 53 53 53 53 53 53 53 53 53	HIIIII 800000	8800 989 99999 8800 99999999999999999999			
ξξ ••		************	,1		8888888888 88888888 8888888 888888 88888	*******		
2333	13332 2	innunit i		\$\$\$\$\$\$\$\$\$\$\$\$\$\$ \$\$\$\$\$\$\$\$\$\$\$ \$\$\$\$\$\$\$\$\$\$	0000000	Etttt	ttttt	

VORCESTER POLYTECHNIC INST' BARCH BA	NOUSNAN TOBSTTNE & SANFELS' SPENCES TAN TONSE 2007 DETAN TONSE DALLAS TE 75201
135807057011 1 99999 VILE LABORATORIES FO BOI 1008 HUBTSVILLE AL 35807	191760057154 3 99999 WILE LABORATORIES DEPT 170 DIRECTOR-STRATEGIC PLANNING PO BOI 160 CA 91760
135807057010 1 99999 VILE LABOMATORIES PO BALL NUMTSVILLE AL 35807	191760091764 1 99999 WILE LABORATORIES SCIENTIFIC SVC STST GROUP LAWEINCE NOUSPEAU OA HAGEN HAGEN AVE CA 91760
135007053348 1 99999 WILE LABORATORIES DIRECTOR BUCLEAN PROGRAMS PO BOI 1008 AL 35807	162001012273 1 WTOBING DEPT OF HLTW 6 SOC SVC BADTOLOGICAL HLTW SVC THOMAS SCHELL CHIEF CHIEF 401 HATHAWAY BLDG CHEFENER WT 82001
145242091765: 1 . 99999 TOPLINE DIV DON GRAY QA MANAGEN CINCINNATI : ON 45242	227028005511 1 99999 TAORIN BIVER COMMITTER RABY A DAVIS CHAINAN ROOTSVILLE BOX 261 BC 27028
298988006817 1 99999 TARINA INDIAN NATION CONSOLIDATED TRIBES 6 DANDS BUSSELL JIN TRIBAL COUNCILNAN TRIBAL COUNCILNAN TOPPEDISN DA 98948	101701005714 1 TANET ATONIC RESCTRIC CO. LIBRAT TANET ATONIC RESCTRIC CO. LIBRAT AND TANESTRA ST RA 01701
1013500 00575 L PCTBIC CO TANKES TOMIC REPORT CC TANKES TOMIC INFS TANKES NA 01350	101367036517 1 YANKES ATOMIC BLECTBIC CO H AUTIO FLANT SUPT STAR ROUTE NA 01367
101701081394 1 99999 TANEB ATOMIC BLECTBIC CO JOHN DEVINCEBTIS J671 WORCESTER BD FRAMINGTON NA 01701	10 170 100 1046 1 99999 OPER PROJECTS & LICENSING D
101701008690 1 99999 TARKES ATORIC BLECTRIC CO 9 JOHNSON VICE PRESIDENT 1671 WORCESTER ROAD FRANINGMAN NE 01701	10 170 10660 35 1 99999 YANKER ATOMIC BLECTBIC CO LICENSING JANES A RAY SETIOR ENGINEER SETIOR CONCESTER RD FRANINGHAM RA 01701
101701065505 1 99999 JANKER ATOMIC ELECTRIC CO JANES E TRIBBLE PRESIDENT 1671 VORCESTER ROAD FRANINGNAN NA 01701	119922091766 1 99999 TARUAT CORP BOY CHEU OA MARAGER BLUE BELL PA 1992
119422053153 1 99999 TABUAT CORP A VOLGER MANAGER OUALITY SYSTEMS BLUE BELL PA 19422	117405064457 1 TORK PLECTRO PAREL CONTROL CO JANERS TORK COUNTY INDUSTRIES PARK TORK COUNTY INDUSTRIES PARK TORK PA 17"9

••

	HARTERT SLAST-SJAPSTRAL
253702006123 DISCUSIN DEPT OF JUSTICE PATRICE UN ALSU ASSISTANT ALSU DEPICOL HADISON STATE CAPITOL 1 53702	15 3707000976 HI SAPETY 6 BLDU
154241040510 ELECTIC POURS CO POINT BACCARS UI 54241	15 320 1000 061 FL STRIC POWER CO SECONDI FL STRIC POWER CO SECONDI FL STRIC POWER CO SECONDI FL STRICE PERSIDENT SILVAUKER WI SJ201
151201002931 BLECTBIC POURS CO GINECTOR 231 WIST BICHIGAN ST BILWARKER WICHIGAN ST BILWARKER	15.22.10.00502 gcphic Power CC
150241001592	153703000485 1 99999 WISCONSIN FYIROWARNTAL DECADE PTER 105500 ADISON UI 53703
253703005866 1 99999 SCOUSIN BUTIBOUNENTAL BECADE STER LEDERSON ADISON II SJ703	25 J702005365 LIC SERVICE CON CHAIN NAMES STATE OFFICE SLOG NAMES OF STATE OFFICE SLOG NAMES OF STATE OFFICE SLOG
1537020 +1839 1 SERVICE CON 15500310 PUBLIC SERVICE CON 1555 PLORES CHORAS AVE 1502 SEEDOTGAN AVE 1508 7854	15 37070 31305 1 SERVICE CON CHISCONSIN FUELIC SERVICE CON CHIST DESTREE BOL 7854 WI 53707
153707081507 1 588VICP CON 150708318 PUBLIC SERVICP CON 111118 557183 CMIEP BOI 7854 PO DOI 7854 PADISON NI 53707	153707032484 PUBLIC SERVICE CON STATENT TORK CHAINER PARES STATE OFC 819977
154216080468 1 SERVICE CORP VISCONSIN PUBLIC SERVICE CORP REVAUER UPS VLANT MANAGER REVAUER VI 54216	154305002942 1 SREVICE CONP NISCONSIN PUBLIC SREVICE CONP NOCLEAR PUBLIC SREVICE CONP C USAN PUBLIC SR
154 JOSO9 1 183 1 VISCONSIN PUBLIC SERVICE CORP REVAUERE NOC POWER PLANT DOMALD C SHIVICE? SUPERVISOR PO POI 1200	154305064763 1 99999 WISCONSIN PUBLIC SERVICE CORP J N NORRISON HUCLEAR ADDIN SUPV PO BOX 1200 GREENDAY WI 54305
239205001246 1 99999 VISE CARTER CHILD 6 CARAVAY ROBER 7 B ACCENEE ATTOMET PO BOI 651 JACKSON RS 39205	10522091762 1 99995 90000480 60200 00 CO JARS PEITCH 04 MANAGES 1000 CORAES ND PO BOX 1519 1000 CORAES ND PO BOX 1519 1000 CORAES ND CO 10522

..

ITTER BUSS SLECTAIC COAP	itititit. stittes thit
PO BOI JSS PITTSBUGG PA 15230	PO DOI 355 PITTSBORGH PA 15230
115238064865 BLECTRIC CORP BETTINGHOUSE BLECTRIC CORP 200 STTA DR PITTERNAGE PA 15230	115009091750 LLCTBIC COLP CONTROL PRODUCTS DIV CONTROL PRODUCTS DIV ALSE MANAGER OA MANGER DA DESCRAVAS RD REAVER PA 15009
115196001625 LL TRIC COAP PLANT APPARATOS DIVISION PLANT APPARATOS D	115230064758 1 HSTINGHOUSE HLECTBIC CORP BUCLSAF HERBOT RUSSELL RGE BECORPS & PILES OP PO BUI 355 PITTSHUMGE PA 15230
115230001499 1 Telc 29999 LICE SING SAPEGUARDS & SAPETY AT SAFO DIRECTOR	115230001612 12 10 99999 POULA SISTERS D SCARGA PITTSBURGH PA 15230
1152 Je091757 BLBCTPIC CORP WEST HOROUSE BLBCTPIC CORP HELECTROUSE BLBCTPIC CORP HAROLD SCHERESTEL 03 MANAGEN 200 BETA DE PA 15234	133065055288 1 CTRIC 2027 WESTINGHOUSE LLECTRIC CORP PSJ SCHNIDT NANAGES OVALITY ASSURANCE 4300 CORIL RICOR DELVEL 13045
115230002263 1 29779 WESTINGHOUSE BLECTBIC CORP WALTER 5 STEVENS PO BOX 355 PITTSAURGN PA 15230	215230001417 LICTAIC CORP PATRONOLISE STATES DIVISION PO DOI 155 PITTSMAGN PA 15230
115230092869 1 29999 # STINGHOUSS HIDCTBIC COBP DOCLAR SVC INTIGRATION DIV JANUS C IN PO BOX 2728 BLDG-701 BATTSAURGE PA 15230	199352053149 HANFORD CO BITING 10038 HANFORD CO BICHLAND WA 99352
199352077527 1 99999 WESTINGHOUSE NAMPORD CO J H MACLARE NAMPORD CO MCB-MUCLEAR QA PROGRAM OPC PO BOX 1970 V/B-110	199352055108 1 999999 908571 MGHOOSE HAMPORD CO 80867 1 884008 801 1970 907 1970 908 1970 908 1970 909 1970 909 1970 909 199352055108
IICHLAND VA 99352 199352039954 1 99999 VESTINGHOUSE NANFORD CO 0 V/D 374 0 PO BOE 1970 V/C 1970 0	160193062781 1 99999 WILLIAN A FOPE CO GARY L MARODAROT 1020 L MARONAROT SCHAURBURG IL 60193
ISCHLAND VA 99352 105210091761 1 99999 VILLIAN POWELL CO 99999 VILLIAN POWELL CO 99999 VIDSON KNOCK 2503 SPNIG GROVE AVE FOB 14006 GROVE AVE	145214029498 1 99999 WILLIAM POWELL CO PO BOX 14006 CINCINNATI H 45214
CINCINNATI ON 45214 145214040024 1 99999 NILLIAN POWELL CO EDWIN E NINTERPELDT CORPORATE ON MANAGER PO BOI 14006 CINCINNATI ON 45214	145153026371 1 99999 WILLIAM ZINMER NUCLEAR TON JOHNSON US BOUTE 52 PO BOX 201 BOSCON OH 45153

..

VESTINGROUSE BLECTBIC COMP POURE ELECTROBICS & DEIVE STS & C HOLDBROOK GEN BRAL MANAGER FO FOI 225	UESTINGHOUSE ELECTRIC WALTE RILL SITE P BOLENDECK LRR 04 HANGER P0 BOI 156	222	¥"
DUPPALO BI 14240 114240053723 1 99999 UESTINGNOUSE ELECTRIC COMP BEDIUM NOTOS & GRABING DIV D L NOOVER GENERAL MANAGER PO BOI 225 NY 14240	HADISON 115230092715 1 WESTINGHOUSE RLECTBIC OPERATING PLANTS PROJ PO BOX 2720 RED 701 PITTSNURGE	9999 COR BCT	15230
115112053150 1 99999 WESTINGHOUSE ELECTRIC CORP SWITCHGEAR DIV 7836 D B JOHES WAWAGER QUALITY ASSUBANCE 700 ARADDOCE AVE PA 15112	1378 3008 1131 1 WESTINGHOUSE ELECTRIC ANGUS KINHINS PO BOY W OAK RIDGE	202	2 9 37830
215230006522 1 99999 ESTINGOUSE ELECTRIC COMP ATORIC POWER DISTRIBUTION VILLIAN KONTINE POST OFFICE BOX 355 FITTSBURGE PA 15230	121030091759 HSTINGOUSE PLECTRIC DUCLEAR INSTRUCE CONT FOOD A MANAGES TOOD A MANAGES SONT VALLEY	999 COB BOLS	2 9 21030
215230006498 1 99999 WESTINGROUSE ELECTRIC CORP POURE STSTERS TO LEI PO DEI 355 PITTSBURGE PA 15230	215230001379 1 WESTINGHOUSE ELECTRIC V LOCE PO BOX 355 PITTSBURGE	232 PA	2 9 15230
1 1566 30 53 142 1 VESTINGHOUSE ELECTRIC CORP A ESD A ESD A BATINI DEPUTT PROD ASSUE NAMAGER PO POI 150	114240091752 1 WESTINGHOUSE ELECTRIC MED MOTOR & GRARING D B P MCKERVER DIV QA MANAGER 4454 GENESSE ST	999 200	29
115230091754 1 99999 WESTINGHOUSE ELECTRIC CORP WATER REACTOR DIV P T MCHANGS PROJECT ENGINEER PO BOX 355	132596053144 1 WESTINGMOUSE ELECTRIC WUCLEAR COMPONENTS DI PRODUCT ASSURANCE NG2 PO BOI 1313	239	99 P
115230022974 1 99999 WESTINGHOUSE ELECTRIC CORP WATER BEACTOR DIVISIONS J S NOORE GENERAL RANAGER PO NOI 355	1200 14056984 1 WESTINGHOUSE ELECTRIC LICENSING OPERATIONS ED THURPHY NAMAGER 4901 FAIRNONT AVENUE	232	200 L
185282091751 1 99999 WESTINGHOUSE ELECTRIC CORP CONBUSTION CONTROL DIV J H MURPHY OA MAKAGEE 1441 WEST ALAMEDA DB	115230079596 1 WESTINGHOUSE ELECTRIC WESTINGHOUSE ADMINISTR A J WARDI RANAGER BOX 355	999 COS AT 10	29 29 1521
TERPE AZ 05202 115024053139 1 99999 WESTINGHOUSE ELECTRIC CORP BLECTRO RECHANICAL DIVISION C E OVEN PRODUCT ASSURANCE HANAGER CHESNICK AVENUE	215230006516 1 WESTINGHOUSE ELECTRIC A T PARKER PO 901 355 PITTSBURGH	994 COI PA	99 1523
CHESWICK PA 15024 121030081454 1 99999 WESTINGHOUSE ELECTRIC COMP NUCLEAR INSTRUMENTATION & CONT W PATALON GENEBAL MANAGER 1111 SCHILLING RD NS 7422	119113091758 1 WESTINGHOUSE ELECTNIC POWER GENERATION DIV JAMES P PHILLIPS 2ND 6 SEMINOLE STS POB.9175	201	199 19
HONT VALLEY ND 21030	PHILADELPHIA	PA	1911

.

..

	And the second
ATTALE FARMERS ELEC COOP INC CEDERAL MARAGES FO BOI 629 ANADARKO OK 73005	NESTENS PIPING 6 ENGINEANING N HAVTACE OA MANAGER 1465 TOSENITE AVE SAN PRANCISO CA 94124
107662079039 1 99999 UESTEEN STRESS INC 374 PORTH HIDLAND AVE SADDLE BROOK NJ 07662	115663092299 1 99999 MESTINGWOUSE PLECTRIC CORP ADVANCED ENGY SYSTERS DIV WALTZ MILL SITE LIBRARY PO BOX 158 MADISON PA 15663
199352091760 1 99999 HESTINGHOUSE ELECTBIC COMP HAWFORD OPERATIONS FO BOI 1970 BICHLAND WA 99352	114845053148 1 99999 WESTINGHOUSE ELECTRIC CORP INDUST & GOVT TUBE DIV ULITY ASSUBANCE MANAGER BESTINGHOUSE CIRCLE NORSENEADS NY 14845
115230006610 1 99999 UESTINGHOUSE ELECTRIC CORP NOCLEAR ENERGY SYSTEMS LIDBART JAN AGEN FO BOT JSS PITTSBURGE PA 15230	115220001629 1 99999 HESTINGHOUSE ELECTRIC CORP UNI LINGARY FITTER IGN PA 15220
132576053722 1 99999 WESTINGBOUSE BLECTBIC COMP UCLEAR COMPONENTS DIVISION T C ALLEN PROJECT HANAGER BACP PO BOI 12831 PRUSACOLA PL 32576	11566309.249 1 99999 WESTINGHOUSE ELECTRIC CORP A STANNO'.D GRUNDAL JANAGER MADISON PA 15663
160099081500 1 99999 WESTINGHOUSE ELECTRIC CORP INSTRUCT & TRAINING BRACTOR C DACH NANAGER 505 SHILOR BLVD IL 60099	115230065223 1 99999 WESTINGROUSE ELECTRIC CORP W N BANFORD PO BOX 355 PITTSBURGE PA 15230
115230038027 1 99999 WESTINGNOUSE ELECTRIC CORP WECKEAR SAFETY DEPT N D BURCH LICENSING RNGIWEER PO BOX 355 PITTSNURGH PA 15230	114240053138 1 99999 WESTINGHOUSE ELECTRIC CORP LARGE MOTOR DIVISION T & CONVAY MANAGER QUALITY ASSURANCE 4454 GLUESER STREET RUPPALO BY 14240
18528205314^ 1 99999 WESTINGHOUSE ELECTRIC CORP CONPUTE E INSTRUMENTATION DIV NANCY DUGGER PO BOX 22005 1441 W ALANEDA DE TENPE AZ 85282	192665091748 1 99999 WESTINGHOUSE ELECTRIC CORP R LEURY OA MARAGER ORANGE CA 92665
215230006311 1 99999 WESTINGHOUSE ELECTRIC CORP BOB FAAS PO BOI 355 PITTSBUNGH PA 15230	115230006709 1 99999 WESTINGHOUSE ELECTRIC COMP HUCLEAR SERVICE DIVISION W H PURPARI PO BOX 2720 PITTSBURGH PA 15230
215230001222 1 99999 WESTINGHOUSE ELECTRIC CORP NUCLEAR OPERATIONS DIV W C GANGLOFF HANAGER-US WEST PROJECTS PO BOX 355 PITTSBURGH PA 15230	114845001535 1 99999 WESTINGHOUSE ELECTRIC CORP REACTROWIC COMPONENTS DIV WALLACE GILLIES WESTINGHOUSE CINCLE 111 HORSENEADS BY 14445
114240091753 1 99999 WESTINGHOUSE ELECTRIC CORP PWR ELECTRONICS 6 DRIVE STS DAVID HAWKINS OA MANAGER FO BOI 225	115230091237 1 99999 WESTINGHOUSE ELECTRIC CORP NUCLEAR SYCS INTEG DIV D N HECKNAN PO BOX 2728 BAY 201
BUFFALO NY 14240	PITTSBORGH PA 15230

٠

•

.....

DÁSHÍDGTÖÐ PUB ÞOWER JÜPL STS G E DOUPE Joog george Vasnington Vat Po boi 968 Rickland Va 99352	WASHINGTON FUB FOURE SUPL'STS G L FONES SR PROJECT OA ENGINEER PO BOI 1223 ELNA NA 98541
199352079423 1 99999 WASHINGTON PUB POWER SUPL SYS B GLASSCOCK GA DIRECTOR PO DOI 968 RICHLAND VA 99352	198541079424 1 99999 NASHINGTON PUB POWER SUPL SIS ARTHUR D KOHLER PROJECT HANAGER-UNP-3/5 FO BOX 1223 ELNA NA 98541
158501079422 1 99999 MASHINGTON PUB POWER SUPL STS R S LEDDICK PROBAN DIRECTOR - WWP 3/5 PO BOX 1223 ELMA WA 98541	198541064621 1 99999 WASHINGTON PUB POWER SUPL SIS R D HADDEN OUALITY ASSURANCE ENGINEER PO BOI 1223 ELAA KA 98541
199352081530 1 99999 WASHINGTON PUB POWER SUPL SYS B G NATLOCK PROGRAM DIRECTOR-WHP-2 PO BOI 968 BICHLAND WA 99352	199352008688 1 99999 JASHINGTON PUB POWER SUPL SYS D W HAZUR NANAGING DIRECTOR PO BOI 968 RICHLAND NA 99352
299352006468 1 99999 WASHINGTON PUB POWER SUPL STS RELSOW LICENSING HANAGER PO BOI 968 RICHLAND • WA 99352	199352081529 1 99999 WASHINGTON PUB POURE SUPL SYS R N BOOT PROGRAM DIRECTOR-WEP-1/4 PO BOX 968 BICHLAND WA 99352
199352057188 1 99999 WASHINGTON PUB POWER SUPL STS LICENSING ENGINEERING G C SORENSEN 3000 GEORGE WASHINGTON WAY PO BOX 968 BICHLAND WA 99352	199352064626 1 99999 WASHINGTON PUB POWER SUPL.SYS C L WRITCORD SENIOR ENG REC ANALYST 3000 GROEGE WASHINGTON WAY BICHLAND WA 99352
1SCOTLO91744 1 99999 WEIR PUMPS LTD CATHCART WORKS I H LUNDIE DA MANAGER BEWLAWDS ED GLASCOW G444EI SCOTLAND	199219053134 1 99999 WELK BROS HETAL PRODUCTS INC PO BOX 19099 SPORANE WA 99219
199219091745 1 99999 WELK BROS BETAL PRODUCTS INC H FAREELL FIELD QA HANAGER S 2504 HATFORD BD FOR 19099 SPOKAME NA 99219	108094091746 1 99999 MEST JEBSET NPG CO CHESTNUT & NAIN ST WILLIAMSTOWN NJ 08094
225305005701 1 99999 WEST VIRGINIA DEPT OF WEAL-W CLARK HANSBARGER STATE DIRECTOR OF BEALTH BLDG 3 ROOM 206 CHARLESTON WV 25305	225305006545 1 99999 WEST VIRGINIA DEPT OF LABOR LAWRENCE BARKER COMMISSIONER STATE CAPITOL COMPLEX-BLDG 6 BOOM 451 CMARLESTON WY 25305
125305004355 1 99999 WEST VIRGINIA OPC OF ENER SVC DIRECTOR STATE CAPITOL COMPLEX ROOM EB80 CHARLESTON VV 25305	225305005704 1 999999 WEST VINGIWIA OFFICE OF GOV CHARLESTON WY 25305
126506081876 1 99999 WEST VIRGINIA PUB INT RES GRP W VIRGINIA UNIVERSITY MOUNTAINCLAIR SON NORGANTOWN WY 26506	119103028068 1 99999 WESTEC SERVICES INC Applied Sciences IAN H SARGENT 100 North 20th Street Philadelphia pa 19103

W J WOOLLEY CO OA MANAGEN 1315 WEST 22WD ST OARBROOK IL 60521	W J WOOLLEY CO A B BU IFACIO OA BANAGEB 73 15 W 22 MD ST OAKBROOK IL 60521
144708091763 1 99999 U J NOOLLET CO NOOLLET MPG CO CHARLI O'DAY 03 NAMAGER 1545 WRIPPLE AVE SW CARTON OF 44708	120874066211 1 99999 9 L PAUTH ASSOC INC NUCLEAR INDUSTRY CONSULTANTS 14411 POPLAR NILL RD GERMANTOWN ND 20874
102173066783 1 99999 W R GRACE & CO ORGANIC CHEMICALS DIVISION JORN J EAGAN RSEADCH SPECIALIST 55 HATDEN AVE LEXINGTON NA 02173	261820001585 1 99999 WAALER EVANS & GORDON THOMAS J GORDON ESQUIRE 2503 S NEIL CHAMPAIGN IL 61820
246224006240 1 99999 WABASH VALLEY POWER ASSOC E P GARTIN GRWERAL MANAGER PO BOI 24700 INDIA AAPOLIS IN 46224	110007057894 1 99999 WALL STREET JOURNAL JOHN ERSCHWILLER 22 CORTIANDT STREET NEW YORK NY 10007
107036053131. 1 99999 BALWORTH CO ALOTCO PLANT JOHN L MANLEY BUCLEAR ENGN CONSULTANT 1400 W BLIZADETH AF BJ 07036	119481053133 1 99999 WALWORTH CO CORPORATE ENGINEERING PO NUNT OUALITY ASSURANCE NANAGER PO BOX 873 VALLEY PORGE PA 19481
176710091742 1 99999 WALWORTH CO WACO DIV CLIPP JOHNSON FUGE HABAGER 1200 TEIAS CENTRAL PRUY UACO	107036091743 1 99999 WALWORTH CO ALOTCO PLANT P TRUPPO OA DIRECTOR V400 W ELIZABETH AVE LINDEN NJ 07036
196504078325 1 99999 WASHINGTON DEPT OF SOC & BLTH RADIOACTIVE BATEBIALS WANCY P KIRNER SUPERVISOR WAIL STOP LD-11 OLIPPIA WA 98504	198504004311 1 99999 WASHINGTON DEPT OF SOC & RLTH RADIATION CONTROL SECTION TERRY STRONG NEAD AIRDUSTRIAL PARK LP-13 OLYMPIA WA 98504
198504091024 1 99999 WASHINGTON ENERGY PACIL SITE EVALUATION COUNCIL GEORGE NANSEN PT-1 OLYMPIA NA 98504	198504080853 1 99999 MASHINGTON ENERGY PACIL SITE EVALUATION COUNCIL MICHOLAS D LEWIS CHAIRMAN PT-11 OLYMPIA NA 98504
199352080581 1 99999 WASHINGTON PUB POWER SUPL SYS WASHINGTON MUCLEAR 1 PLANT MANAGER RICHLAND WA 99352	199352080580 1 99999 WASHINGTON PUB POWER SUPL SYS WASHINGTON NUCLEAR 2 PLANT NAWAGER RICHLAND WA 99352
199352080582 1 99999 WASHINGTON PUB POWER SUPL STS WASHINGTON BUCLEAR 3 PLANT NANAGER BICHLAND WA 99352	299352006466 1 99999 WASHINGTON PUB POWER SUPL SYS G D BOUCHEY DEPUTY DIRECTOR-SPTY 6 SECURTY PO BOX 968-ND 650 RICRLAND WA 99352
199352081528 1 99999 WASHINGTON PUB POWER SUPL SYS C S CARLISLE DEPUTY PROGRAM MANAGER-WNP-2 PO BOI 968 BICHLAND WA 99352	198541004554 1 99999 WASHINGTON PUB POWER SUPL SYS KENNETH W COOK PROJECT LICENSING AGR PO BOX 1223 ELMA WA 98541

VILLAGE OF BUCHANAN CARL B DALVIA VILLAGE ATTORNEY 395 SOUTH RIVERSIDE AVE CROTON ON NUDSON NY 10520	VIEGINIA ATTORNET GENENAL 1101 EAST BROAD STREET A 23219 RICHNORE VA 23219
223219007071 1 99999 VIRGIPIA ATTORNEY GENERAL ATTORNEY GENERAL 11 S 12TN STREET BOOM 308 BICEROND VA 23219	123209091591 1 99999 VIRGINIA CORP CONNISSION DIV OF ENERGY REGULATION W T LOUGH PO BOI 1197 RICHNOND VA 23209
123233081537 1 99999 VIRGINIA CORP OF BICHBOND 3605 NATLAND CT VA 23233	123261082352 1 99999 VIRCINIA ELECTRIC & POWER CO RICHAOND
1231170 80 485 1 99999 VIRGINIA ELECTRIC & POWER CO NORTH ANNA 1 NPS PLANT NANAGER NINERAL VA 23117	123117080497 1 99999 VIRGINIA ELECTRIC 5 POWER CO NORTE ANNA 2 NPS PLANT HANAGER RINERAL VA 23117
123117080496 1 99999 VIRGINIA ELECTRIC & POWER CO BORTH ANNA 3 BPS PLANT BANAGER NINBRAL VA 23117	123261005619 1 99999 VIRGINIA ELECTRIC & POWER CO NOCLEAR OPERATIONS VICE PRESIJENT PO BOX 26666 RICHNOND VA 23261
123883080596 1 99999 VISCINIA ELECTRIC & POURE CO SUREY 1 NPS PLANT MANAGER 'VA 23883 SUREY	123883080597 1 99999 VIRGINIA ELECTRIC & POWER CO SURRY 2 MPS PLANT NAWAGER SURRY VA 23883
123117080970 1 99999 VIRGINIA ELECTRIC & POWER CO WORTH ANNA MPS 1 & 2 W E CARTWRIGHT STATION HAWAGER PO BOI 402 WIREAL VA 23117	123204064594 1 999999 VIRGINIA ELECTRIC & POWER CO J C DANVLO SUPVE ADMIN & RECORDS NG PO BOX 564 RICRNOND VA 23204
223261005672 1 99999 VINGINIA ELECTRIC 6 POWER CO J H PERGUSON EXECUTIVE VICE PRESIDENT-POWER PO BOI 26666 RICHNOND VA 23261	12326100#558 1 99999 VIRGINIA ELECTRIC 6 POWER CO LI BRATY A B FLANAGAN LIBBARIAN PO BOX 26666 RICENROND VA 23261
123261080952 1 99999 VIRGINIA ELECTRIC & POWER CO SURRY & MORTH ANNA MPS 1 & 2 P G GODWIN DIBECTOR OF MUCLEAR SECURITY PO BOI 26666 FICHMOND VA 23261	123204080945 1 99999 VIRGINIA ELECTRIC & POWER CO WORTH ANNA 3 NPS E LIPRAGE PROJECT COORDINATOR PO BOX 564 RICHNOND VA 23204
123117080946 1 99999 VIRGINIA ELECTRIC 6 POWER CO WORTH ANNA 3 WPS P G PERY F VTE MANAGER BOX 38 RIWERAL VA 23117	123883079289 1 99999 VIRGINIA ELECTRIC & POWER CO SUREY MPS 1 & 2 J L WILSON STATION HANAGER PO BOX 315 SUREY VA 23883
123225091838 1 99999 VINGINIA OPC OP ENGY ENER SVC RADIOLOGICAL PLANNING BR HENRY G ALLARD CHIEP 310 TURNER BD RICHMOND VA 23225	220006006552 1 99999 VOLPE BOSKEY 6 LYONS D B MACGUINEAS 918 16TH STREET NW WASHINGTON DC 20006

.

..

.

VAPOR COMP GPE CONTROLS DIV D SCHLEITER 04 MANAGER 5511 QARTON ST NOTTH GROVE IL 60053 105495091739 1 99999 VELAN VALVE COMP E I PRANCOIS CO3P QA MANAGER NAVE BUE C GRISNOLD INDUST PKNY VILLISTON VT 05495	VELAN FIAC A K VELAN PRESIDENT 2125 WARD AVE HON-TTO NONTREAL QUEBEC CANADA 105495053130 1 99999 · VELAN VALVE CORP P J 3TR BLCZYR PLANT MANGER AVE C GRISVOLD IND PARK WILLISTON VI 05495
205602005891 1 99999 VERMONT ATTORJET GENERAL JOHN J EASTON 109 STATE STREET-PAVILION BLPG NONTFELIER VT 05602	105602053196 1 99999 VERNONT DEPT OF HEALTH DIV OF OCCUPATIONAL & BAD HLTH BATNOND N NCCANDLESS 10 BALDWIN ST FONTPELIER VT 05602
105602065591 1 99999 Y MONT PUB INTEREST BES GROUP 43	205602005895 1 99999 VERMONT PUBLIC SHRVICE 120 STATE STREET NOFFPELIER VT 05602
1056020916'2 1 99999 VERMONT PUBLIC SERVICE RICHARD SAUDRY. 120 STATE ST NORTPELIER VT 05602	205602005897 1 99999 VER NOWT TANKEE DECON ALLIANCE 43 STATE ST PO BOX 1117 NONTFELIER VT 05602
105354000590 1 PS VERMONT TANKEN TUC POWER CORP VERMONT TANKEN TUC VERMONT TANKEN TUC VERMONT TANKEN TUC VERMONT TANKEN TUC VERMONT TANKEN TUC	105301036326 1 99999 VERMONT TAMER NUC POWER CORP VILLIAM P COWAT PRESIDENT & CHIEP BIEC OPPICER RD 5 BOX 169 PERRY RD BRATTLEGORO VT 05301
201701005883 1 99999 VRROUT TANKER BUC P TR CORP LOUIS HEIDER VIC3 PRESIDENT 1671 PORCESTER RD PRANINGWAN NA 01701	105354064682 1 99999 VERONT VANKER BUC POWER CORP ADMINISTRATIVE SUPERVISOR 90 BOX 157 GOV HUNT ED VERNON VT 05354
295301005886 1 99999 VERMONT YANKEE NUC POWER CORP N P AURPHT VP 6 NANAGER OF OPERATIONS RD 5 BOX 169 FERRY RD BRATTLEBORO VT 05301	105354091016 1 99999 VERMONT VANKEE NUC POWER CORP J.P. PELLETIER P1.5NT WANAGER P0 BOX 157 VERMON VT 05354
101701005618 1 99999 VELNOWT TANKEE NUC POWER CORP J B SINCLAIR LICENSING ENGINEER 1671 NORCESTER RD PRANTIGHAN NA 01701	201701007004 1 99999 VERMONT YANKER NUC POWER CORP TANKER ATONIC ELECTRIC PWE CO J B SINCLAIR LICENSING PNGIMERE 1671 NORCESTER ND PRANINGHAR NA 01701
144 10409 1740 1 99999 VICTOREEN INC PETER CORRIGAN 04 MANAGEN 101 VOODLAND AVE CLEVELAND OH 44104	144104053725 1 99999 VICTOREEN INC R E STAFFORD MANAGER-RELIABILITY ENGR 10101 WOODLAND AVE CLEVELAND ON 44104
101950065238 1 99999 VIKEN INDUSTRIES INC OPERATIONS VAL BOUCHARD VICE PRESIDENT 12 MULLIKEN WAY	210511005686 1 99999 VILLAGE OF SUCHANAN GEORGE BEGANY MAYOF 236 TATE AVENUE BUCHANAN NY 10511

.

US NEC PEGION 111 REGIONAL ADRINISTRATOR 799 BOOSEVELT RD IL 60137 GLEN ELLTH IL 60137	US DAC REGIONALISTRATOR PEGIONAL ADMINISTRATOR DAD SEVELT BOAD IL 60137
176011012301 1 99999	176011056496 3 99999
US BEC REGION IV	US BAC BEGION IV
REGIONAL ADDINISTRATOR	EGIONAL STATE LIAISON OFFICES
611 BTAN PLAZA DE	SOITE 1000
SUITE 1000 TI 76011	ARLINGTON TX 76011
1760 120 8 1627 1 99999	1760 1208 16 28 1 99999
US BEC REGION IV	US BEC BEGION IV
STATE AGE REMENTS OFFICER	STATE AGREENENTS OFFICER
511 FTA B PLAZA DE SOLTE 1000	11 BYAR PLAZA DE SOITE 1000
ARLINGTON	ARLINGTON TI 76012
276011006384 1 99999 US HEC REGION IV BRGIONAL ADRINISTRATOR SUITE 1000 ARLINGTON FI 76011	176012003589 1 99999 US HHC BEGION 1 99999 BEACTOR PROJECT BR-1 BRANCH CHIEP 611 HIAP PLAZA DR ARLINGTON TX 74012
194596056507 7 99999	US WEC BEGION Y
US MEC BEGION V	BEGIONAL ADBINISTBATOR
BEGIONAL STATS LIAISON OPPICER	SUITE 210
1450 BARIA LANE CA 94596	VALSUT CEBER CA 94596
294596006567 1 99999	194596081626 1 99999
US UNC BEGION Y	US BC BEGION V
JANDS MARCHETT	JACK NOBPOR
PUBLIC INFORMATION OFFICER	STATE AGREENENTS OPPICES
1980 IC CALIFORNIA BLVD	1450 RABIA LANS SUITE 210
NALMOT CALER CA 94596	VALUUT CREEK
294596007126 1 99999	194596092222 1 99999
US DEC BEGION Y	05 URC REGION V
DENNIS F RIBSCE	DOT BOVAR
1450 HARIA LA SUITE 210	1450 RABIA LANE
VALUUT CREEK CA 94596	VALUOT CREEK CA 94596
10330 1093224 1 99999 US SENATE J NUMPERET BEN BOTHTON 1 PILLSBURT ST NH 03301	120510093223 1 99999 05 588478 3884708 G J BURPHRET 708 BURACK DC 20510 8458186708 DC 20510
10 16 13091729 1 99999 US STEEL COOP ABERICAS BRIDGE DIV GEORGE SURREP VORCESTER RA 01613	168102079365 1 US VETERARS ADRIBISTRATION 18001 B L TURCOTTE NOSPITAL DIRECTOR 9101 BOOLWORTH AVE 9101 BOOLWORTH AVE 000400
184103028043 1 99999	107081064448 1 99999
UTAN DEPT CATION & OCCUP NLTH	VALCON ENGINERNING CORP
DUR OF BALATION & OCCUP NLTH	GJ BORGO
DIRECTON	DINECTOR-UVALITY ASSUMANCE
150 W NORTH TEMPLE BOX 2500	2 LAWRENCE RD
150 W NORTH TEMPLE BOX 2500	SPRINGPIELD BJ 07081
200225005630 1 99999 VALONE RCALLISTER ET AL CALL VALORE RCALLISTER ET AL SISTILION ROAD PO BOI 122	JA 4563053128 1 99999 G. C. CLAPR G. C. CLAPR SPEINGE NOONTATINASSUBANCE ANGE NOONTATINASSUBANCE ANGE SPEINGVILLE

٠

..

1 17057	HARTON DC 20555
120555001463 3 99999 34C BATHJE AASHINGTON DC 20555	231513005792 1 99999 9 9 8 9 8 9 8 9 9 9 9 9 9 9 9 9 9 9 9 9
120355070790 1 99999 433 0058070AL 4430 0058070AL 9430 005 DC 20555	120555029190 1 99999 HC 8 1C 8 1C 8 1C 8 1C 8 1C 8 1C 8 1C 8 1
120555001600 1 99999 800 800 900 900 900 900 900 900 90	120555081107 1 99999 Rob Statigat A SALFALT A SALFALT DC 20555
WASHINGTON DC 20555 120555009718 1 99999 US MC 45100 PREDERICK SNOU 20555 WASHINGTON DC 20555	120555007804 1 99999 45 LAP 1748 9 98178 8458180708 DC 20555
120555020206 1 99999 US BEC OSP SUB WEISSBERG SUB WEISSBERG AF-5032	120555007803 1 99999 US BAC ASLEP SHELOON J VOLFE RUD-019 VASUINGTON DC 20355
1 19406003570 3 99999 US NEC REGIOP I REGIONAL ADRIVISTRATOR 631 PART AVUSSIA PA 19406	119406004826 1 99999 US MAC BEGION I PUBLIC AFFAIRS OFFICER AING OF PRUSSIA PA 19406
119406026175 1 99999 US WEC REGION I REGIONAL STATE LIAISON OFFICER 631 PARK AVERUE RING OF PRUSSIA PA 19406	119406081630 1 99999 US MRC ARGION I STATE AGREENENTS OFFICER 631 PARK AVE KING OF PRUSSIA PA 19406
219406006387 1 99999 US NEC REGION I REGIONAL ADRINISTRATOR 631 PARK AVENUE RING OF PRUSSIA PA 19406	130303056497 1 99999 US WRC REGION II REGIONAL STATE LIAISON OPPICER 101 HARIETTA STREET SUITE 3100 ATLANTA GA 30303
130303081629 1 99999 US MAC REGION II STATE AGREENENTS OFFICER 101 MARIETTA ST SUITE 3100 ALLANTA GA 30303	230303006346 1 99999 US MRC REGION II REGIONAL ADRIMISTRATOR 101 RABIFITA STREET SUITA JIO ATLANTA GA 30303
130303082718 1 99999 US NEC REGION II BRAD JONES 101 MARIETTA ST SUITE 3100 ATLANTA GA 30303	160137064870 1 99999 US BRC REGION III BEGIONAL STATE LIAISON OPPICER 799 ROOSEVELT RD GLEN ELLYN IL 60137

••

15 10C	US BEC 1 33334	
I PACTOR TRAINING CENTER	ACRS RLPIDIO G IGNE	
OSBORNE OFFICE CTR SUITE 200	N-1016 WASHINGTON DC 2055	5
CHATTABOOGA TH 374	111	23
120555009812 1 99999 US NAC ASLAP W REP JOHNSON	120555026886 1 99999 · US NEC ADM-DIV OF TIDC PAUL JONES	
ADMINISTRATIVE JUDGE-TECH BUN-529 WASHINGTON DC 205	NFB 042 55 VASHINGTON DC 2055	5
120555066613 1 99999	120555093290 1 99999	
US NBC ASLBP	US NEC NER-DIV SAPETY TECHNOLOGY	
CAROLE KAGAN BNN-439	GLENN KELLEY RELIABILITY & RISK ASSESS BE	
WASHINGTON DC 205	55 216 #ASHINGTON DC 2055	5
120555062544 1 99999	120555003890 1 99999	
ASLAP	OIP	
ADAINISTAATIVE JUDGE-LEGAL	EN3-403A	
WASBINGTON . DC 205	55 DC 2055	2
120555007810 1 . 99999 US MBC ASLBP	120555031467 1 99999 US NAC	
ROBERT N LASO	ASSISTANT RIECUTIVE DIRECTOR	
WASHINGTON . DC 205	55 H-1016 WASHINGTON DC 2055	5
120555007809 1 99999	120555007808 1 99999	1832
US MAC ASLAP	US BAC	
G A LINENDERGER JR	ZANETH A LUEBRE	
VASNINGTON DC 205	55 WASHINGTON DC 2055	5
120555025111 1 99999 US_BAC	120555004184 1 99999 US_BRC	
SHERTLA MASSARO	ASSISTANT BEBCUTIVE DIRECTOR	
WASHINGTON DC 205	55 H-1016	
	WASHINGTON DC 2055	5
120555030757 1 99999 US NBC ACRS	120555004171 1 99999 US BRC ASLBP	
B E ACKINLEY SUBCTAB ON WASTE HANAGEMENT	MARSHALL B MILLER BVV-439	
H-1016 WASHINGTON DC 205	55 WASHINGTON DC 2055	5
120555052087 1 99999	120555007785 1 99999	
ASLAP	ASLEP	
ADHINISTRATIVE JUDGE-LEGAL	DORIS M HORAN EWU-439	
WASHINGTON DC 205	55 WASHINGTON DC 2055	2
120555066170 1 99999	229678005805 1 99999	
ASLEP	WILLIAM T ORDERS	
EVU-439	SR RESIDENT INSPECTOR	
DC 205	SENECA SC 2967	8
120555009542 1 99999 US NRC ASLEP	220555006548 1 99999 US NRC ASLBP	
USCAR H PARIS EWU-439	USCAR H PARIS WASHINGTON DC 2055	5

..

1.00

•

19 20년 4월 20일 NARA NA 19 20일 NA	a second s
US URC TIMBER UPS SIDENT INSPECTOR US TT 52 PO BOX 2021	US WRC WRB-CLINCH BVB BR PROGRAM OFC CANDIS L ALLEN AR-5003
BOSCOW . DH 45153	WASHINGTON DC 20555
120555066453 1 99999 US MRC BES BESLEY L AU	120555009813 1 99999 . US WRC ASLBP CHARLES BECKHOEPER
NUMAN PACTORS BR SS-1130 NASHINGTON DC 20555	EUW-439 VASHINGTON DC 20555
117057091774 1 99999 US BRC BRE-THI PROGRAM OFFICE	120555064868 1 99999 US NRC ASLBP
PO BOX 311 BIDDLETOWN PA 17057	WASHINGTON DC 20555
120555052438 1 99999 US NEC ASLEP LAVRENCE BRENNER	120555003845 1 99999 US MRC ASLBP GLEMN O BRIGHT
BUN-439 DASHINGTON DC 20555	EUU-439 WASHINGTON DC 20555
220555005307. 1 99999 US MC ASLAP	120555077553 1 99999 US WRC ASLBP
JOHN H BUCK DC 20555	JAMES H CARPENTER
	VĂŠHĬVĠTOV DC 20555
120555029097 1 99999	120555007774 1 99999
ASLAP	ASLBP
JOHN CHO , C	RICHARD COLE EWW-439
RAN-529 WASHINGTON DC 20555	WASHINGTON DC 20555
120555065759 1 99999	120555082888 1 99999
US BRC A EOD	US NRC
BUS-263	EWN-359
WASHINGTOP DC 20555	WASHINGTON DC 20555
120555078951 1 99999 US MRC ASLAP GARY J EDLES	120555055103 1 99999 US NBC ASLBP John H PRYE III
ADAINISTRATIVE JUDGE-LEGAL	CHAIRMAN
WASHINGTON DC 20555	VASHINGTON DC 20555
120555078950 1 99999 US HEC	120555051908 1 99999 US BRC
REGINALD L GOTCHY	E GREAER
ADMINISTRATIVE JUDGE-TECH	PROGRAM SUPPORT BE EWW-359
WASHINGTON DC 20555	WASHINGTON DC 20555
120555038234 1 99999 DS NC ASLBF HERBENT GROSSMAN	120555078519 1 99999 US BRC ASLBP JERRY_HARBOUR
ZNN-439 NASHINGTON DC 20555	WASHINGTON DC 20555
120555056993 1 99999 US NRC	237411006528 1 99999 US NRC
JANES HARD	REACTOR TRAINING CENTER OLIVER HAVENS
BUN-439 HASHINGTON DC 20555	OSBORNE OFFICE CENTER
	CHATTANOOGA TH 37411

..

			いたい アフィックステレビ ションデーター かくちんしょう
US BRC SEABROOK MPS BESIDENT INSPECTOR		US NBC SBCY SECRETARY H-1149	,,,,,
SEABBOOK	BE 03874	WASHINGTON	DC 20555
137379051333 1 US NAC SEQUOYAN NPS RESIDENT INSPECTOR RESIDENT INSPECTOR	99999	111778051341 1 US NEC SHOREHAN WPS RESIDENT INSPECTOR	99999 .
SODDY DAIST	TH 37379	BOCKY POINT	NY 11778
1774 14051312 1 US HEC SOUTH TEXAS UPS RESIDENT INSPECTOR	99999	133457056920 1 US NC ST LOCIE NPS RESIDENT INSPECTOR	99999
BAT CITI	TI 77414	JENSEN BEACH	PL 33457
129065092300 1 US BRC SUNUE MPS RESIDENT INSPECTOR RTE 1 BOX 64	99999	123883064021 1 US MRC SURRY MPS RESIDENT INSPECTOR RTE 1 BOX 166	99999
JERKINSVILLE	SC 29065	SUREI	VA 23003
118655051344' 1 . US MRC	99999	117057077547 1 US NRC	99999
SUSQUENANNA NPS RESIDENT INSPECTOR		THEES MILE ISLAND BP SR RESIDENT INSPECTO	S-1
PO BOI 52 SHICKSHINNY	PA 18655	AIDDLETOWN	PA 17057
120555064864 1 US BRC	99999	197048051320 1 US NRC HPS	99999
DIRECTOR .	*	RESIDENT INSPECTOR	
UASHINGTON	DC 20555	AALVIER .	OR 97048
133030051316 1	99999	105354056253 1	99999
TURKET POINT NPS		VERBONT TANKEE MPS	
PO BOX 1207 HOMESTEAD	PL 33030	PO BOX 176 VERION	VT 05354
130830080044 1	99999	170066057471 1 US HC	99999
VOGTLE NPS RESIDENT INSPECTOR		RESIDENT INSPECTOR	
PO BOX 572 WAY BESBORO	GA 30830	PO BOX 822 KILLONA	LA 70066
137381053194 1 US NHC DAR NRC	99999	166839057446 1 US NBC	99999
RESIDENT INSPECTOR		PO BOX 311	
SPELIG CITT	TH 37381	BURLINGTON	KS 66839
199352051322 1	99999	199352057472 1	99999
NPPSS 1 NPS RESIDENT INSPECTOR		NPPSS 2 NPS RESIDENT INSPECTOR	
PO BOX 69 BICHLAND	WA 99352	PO BOX 69 RICHLAND	WA 99352
109601067160 1	00000	101350056252 1	49999
US NBC NPPSS 3 NPS	,,,,,	US NEC TANKEE ROVE NPS	
RESIDENT INSPECTOR		RESIDENT INSPECTOR	
ELMA	WA 98541	MONROE BRIDGE	HA 01350

	和法律的推荐的法律性的问题,并且任何的问题,我们就是自己的问题,我们就是这些问题。
US MAC OSP-STATE AGREEMENTS PROGRAM (SSISTANT DIRECTOR STRT AR-5233	US NRC OYSTER CREEK NPS RESIDENT INSPECTOR PO BOX 445 FORKED RIVER NJ 08731
149043051326 1 99999 US NEC PALISADES NPS RESIDENT_INSPECTOR	185001051310 1 99999 . US MRC PALO VERDE MPS RESIDENT INSPECTOR
COVERT AI 49043	PLOENIX AZ 85001
117314051343 1 99999 US NEC PEACE BOTTON NPS RESIDENT INSPRCTOR	144081056716 1 99999 US BEC PERRY NPS RESIDENT INSPECTOR
PO BOI 399 DELTA PA 17314	PERET OR 44081
137873091209 1 99999 US WRC PRIPPS BEND WPS RESIDENT_INSPECTOR	102360055458 1 99999 US NEC PILGEIN NPS BESIDENT INSPECTOR
SUBGIOUSVILLE TH 37873	PLIBOUTH HA 02360
154 24 10 55882· 1 . 99999 US HEC POINT BRACH MPS PRINT INSPECTOR	155089051329 1 99999 US NEC PRAIRIE ISLAND NPS Resident Inspector
THO RIVERS BI 54241	NECH BOX 500A NE 55089
161242051327 1 99999 US NBC QUAD CITIES NPS	195638051321 1 99999 US MRC RANCHO SECO MPS
22712 206TH AVE BORTH CORDOVA IL 61242	HERALD CITIES ED CA 95638
120555066490 1 99999	120555063080 1 99999 US NRC
RES-DIV OF ACCIDENT EVALUATION DIRECTOR SS-1130 ULSUINGTON DC 20555	RES-DIV OF RNGIWERRING TECH DIVISION DIRECTOR SS-1130 WASHINGTON DC 20555
120555063085 1 99999	120555066611 1 99999
RES-DIV OF ENGINEERING TECH SECTION LEADER-STRUCTURAL ENGR BECHANICAL/STRUCTURAL ENGR BR	BES-DEV OF ENGINEERING TECH BRANCH CHIEF MECHANICAL/STRUCTURAL ENGE BR
SS-1130 WASHINGTON DC 20555	WASHINGTON DC 20555
120555063568 1 99999 US WRC RES-DIV OF PACILITY OPERATIONS BRANCH CHIEF INSTRUMENTATION 6 CONTROL BR SS-1130	120555063571 1 99999 US NBC RES-DIV OF PACILITY OPERATIONS BRANCH CHIEF HURAN PACTORS BR SS-1130
UISNINGTON DC 20555	WASHINGTON DC 20555 129550057468 1 99999
US NRC RIVERBEND NPS RESIDENT INSPECTOR PO BOX 1051 ST FRANCISVILLE LA 70775	US NRC ROBINSON NPS RESIDENT INSPECTOR RTE 5 BOI 266-12 HARTSVILLE SC 29550
108038051342 1 99999 US NRC SALEA NPS BESIDENT INSPECTOR	192672051318 1 99999 US NRC SAN ONOPRE NPS RESIDENT INSPECTOR RESIDENT 199
HANCOCKS BRIDGE NJ 08038	SAN CLEMENTE CA 92672

	and a second
US HEC	NER-DIV SYSTEMS INTEGRATION
BR-DIV SISTERS INTEGRALIUM	SECTION LEADER-RAD PROTECT
INSTRU & CONTROL STS BR	PADIOLOGICAL ASSESSMENT DE
P-1030C DC 20555	WASHINGTON DC. 20555
TASHINGTON DC 10000	
120555056772 1 99999	120555056790 1 97577
US NEC CUSTONS INTEGRATION	HRB-DIV SYSTEMS INTEGRATION
SECTION LEADER-EFFLUENT TE STS	SPECIAL ASSISTANT
SETEOR & EPPLOENT TREAT STS BR	P-A02
P-750 DC 20555	WASHINGTON DC 20555
	120555063630 1 99999
120555056796 1 99999	US NAC
TRR-DIV SYSTEMS INTEGRATION	HRR-DIV SYSTEMS INTEGRATION
BRANCH CHIEF	ACCIDENT RVALUATION BE DSI
BADIOLOGICAL ASSESSMENT DE	P-8028
WASHINGTON DC 20555	WASHINGTON DC 20555
100555056740 1 99999	117057056750 1 99999
	OS HEC PROCESS OFFICE
URB-PLAN & PROG ANALISIS STAFF	DEPUTY PROGRAM DIRECTOR
TECHNICAL SUPPORT BR	THI SITE - PO BOI 311 17057
P-408	RIDDLETOWN PA 17037
WASHINGTON . DC 20555	
120555056741 2 . 99999	120555056749 1 99999
US MAC	MER-TAT PROGRAM OFFICE
SECTION LEADER	SECTION LEADER
ENVIRONBENT REVIEW	SAPETI BEVIEW
AB-5031 DC 20555	WASHINGTON DC 20555
	00000 1 00000
120555004754 1 99999	
	OCH
OFFICE DIRECTOR .	TECH ASSIST TO COM ASSELSTING
8-1159 DC 20555	WASHINGTON DC 20555
	120555038065 1 99999
	US HAC
OCH	OCH ASSIST TO COR GILINSKY
TECH ASSIST TO CON ANEANDE	H-1149
WASHINGTON DC 20555	WASHINGTON DC 20555
120555038066 1 99999	120555003969 1 99999
US NIC	OF DEPUT PRATTING & ENFORCE DIV
OCH ASSTST TO CHATE PALLADINO	DIVISION DIRECTOR
B-1159	BBBB-9604 DC 20555
WASHINGTON DC 20555	WASHINGTON DC 10000
120555003920 1 99999	120555003989 1 99999
US WEC	OIP
GENERAL COUNSEL	OFFICE DIRECTOR
H-1035 DC 20555	MASHINGTON DC 20555
APPRILATION OF TOPOT	
ADALLE 1 80000	120555003916 1 99999
120555003928 1 55555	US NRC
OPA	OPELCE DIRECTOR
OFFICE DISECTOR	H-1013
WASHINGTON DC 20555	WASHINGTON DC 20555
120555003995 1 99999	120555056728 1 99999
US WRC	OSPASTATE & LICENSEE RELATIONS
ORB CHIPP	ASSISTANT DIRECTOR
DAI	AR-5037 DC 20555
HABB-7602 DC 20555	WASHINGTON DC 20555

US MC	120555056770 1 99999 US MRC
BRANCH CHIEF	BRANCH_CHIEF
P-302	P-1022
DC 20555	WASHINGTON DC 20555
120555056724 1 99999 US MRC	120555056799 1 99999 ' US_WEC
DEPUTY DIRECTOR	BRANCH CHIEF
WASHINGTON DC 20555	LICENSING BR-2 328
	WASHINGTON DC 20555
120555056810 1 99999 US URC	120555056811 1 99999 US WRC
BRANCH CHIEF	BRANCH CHIEF
440	OPERATING REACTOR DR-2 4168
TASHINGTON DC 20555	WASHINGTON DC 20555
US URC	120555056814 1 99999 US NRC
BRANCH CHIEF	BRANCH CHIEF
	308
	WASHINGTON DC 20555
	US NRC
BRANCH CHIEF	BRANCH CHIEP
	124
US NC	US NEC
DRANCH CHIEF	BRANCH CHIEF
	540
US MEC DE LICENSING	US NEC
STAN & SPECIAL PROJECTS AR	DIRECTOR
JAO NASHINGTON DC 20555	WASHINGTON DC 20555
120555066420 1 99999	120555056753 1 99999
US NRC NRR-DIV OF LICENSING	US WEC WER-DIV SAFETY TECHNOLOGY
BRANCH CHIEF ORB-4	278
WASHINGTON DC 20555	WASHINGTON DC 20555
120555056782 1 99999	120555056784 1 99999
WER-DIV SAPETI TECHNOLOGY	NRR-DIV SAPETY TECHNOLOGY
P-278	ASSISTANT DIRECTOR Generic Projects
TASAINGICE DC 20555	WASHINGTON DC 20555
120555056788 1 99999	120555056791 1 99999
BR-DIV SAPETY TECHNOLOGY	NRB-DIV SAPETY TECHNOLOGY
LICENSING GUIDANCE BR	TECHNOLOGY
WASHINGTON DC 20555	WASHINGTON DC 20555
120555056792 1 99999	120555056794 2 99999
HER-DIV SAPETY TECHNOLOGY	NRR-DIV SAFETY TECHNOLOGY
SAPETY PROG EVALUATION BR	RELIABILITY & HISK ASSESS BR
WASHINGTON DC 20555	WASHINGTON DC 20555

••

US NAC NONTICELLO NPS BESIDENT INSPECTOR NONTICELLO IN 55362	US MAC HIME WILE POINT NPS RESIDENT INSPECTOR PO BOI 126 LICONING NY 13093
113093080043 1 99999 US BEC DINE HILE POINT NPS DESIDENT INSPECTOR PO BOX 99 LICONING NY 13093	120555004023 1 99999 US NEC WASS OFFICE DIRECTOR SS-958 WASHINGTON DC 20355
120555004773 1 99999 US HEC BUSS-DIY PUEL CYCLE HATL SPTY DIRECTOR SS-396 HASHINGTON DC 20555	120555024900 1 99999 US DAC HRSS-DIV FUEL CYCLE HATL SPTY SECTION LEADER TECH ASSESS EVALUATION SECTION S5-396 VASHINGTON DC 20555
120555035625 1 99999 US HEC HESS-DIV OF SAFEGUARDS BRANCH CHIEF LICENSING POLICY & PROGRAMS BR SS-081 WASHINGTON - DC 20555	120555055502 1 99999 US MAC HASS-DIV OF SAFEGUARDS DIVISION DIRECTOR SS-081 WASHINGTON DC 20555
120555029836 1 99999 US MC VASTE NAWAGEMENT DIVISION DIBECTOR SS-623 USSNINGTON DC 20555	123117051334 1 99999 US NEC HORTH ANNA HPS BESIDENT INSPECTOR RTE BOX 784 SIMERAL VA 23117
120555056805 1 99999 US NBC UBR-DIV HUHAN FACTORS SAFETY BRANCO CHIEF OPERATOR LICENSING BR AR-5221 WASHINGTON DC 20555	120555056815 1 99999 D. NRC- NRR-DIV HUNAN PACTORS SAFETY DIRECTOR P-242 WASHINGTON DC 20555
120555056729 1 99999 US HBC HER-DIV OF FIGINEERING BRANCE CHIEF EQUIPHENT QUALIFICATION BR P-234 WASHINGTON DC 20555	120555056730 1 99999 US NRC WRR-DIV OF ENGINEERING SECTION LEADER-CORROSION ENGR CHEA ENG BR P-1000 WASHINGTON DC 20555
120555056731 1 99999 US WRC WER-DIV OF ENGINEERING ASSISTANT DIRECTOR MATLS & QUALIF ENGINEERING P-302 WASHINGTON DC 20555	120555056736 1 99999 US MRC WRR-DIV OF ENGINEERING SECTION LEADER-B STRUCTURAL ENG BE P-1022 WASHINGTON DC 20555
120555056739 1 99999 US NRC NRE-DIV OF ENGINEERING SECTION LEADER-SDQ ROUIP QUALIF BR 38 WASHINGTON DC 20555	120555056743 1 99999 US MRC WR P-DIV OF ENGINEERING SECTIOF LEADER-CHEMICAL TECH CHEMICAL ENGR BR P-802 WASHINGTON DC 20555
120555056745 1 99999 US NRC URR-DIV OF ENGINEERING BRANCH CHIEF MATERIALS ENGR BR P-328 WASHINGTON DC 20555	120555056746 1 99999 US NEC WRE-DIV OF ENGINEERING ASSISTANT DIRECTOR CONFONENTS 6 STRUCTURE RNG P-530 WASHINGTON DC 20555
120555056747 1 99999 US NRC NKR-DIV OF ENGINEERING DIRECTOR P-202 WASHINGTON DC 20555	120555056755 1 99999 US NEC MER-DIV OF ENGINEERING SECTION LEADER-ENVIR QUALITY EQUIP QUALIF BR

and a second and a second as	
TR-DIV BREN PREP & RUGE RESPON	IE-DIV RAFE PREP & RIGR RESPON
SECTION CHIEF	SECTION CHIEF
ENGE & GEN COUNTY DE SECT B	ENGE & GES CORNUS BE SECT A
BASHINGTON DC 20555	WASHINGTON DC 20555
120555078987 1 99999	120555063635 1 99999
TR-DIT RARE PREP & RUGE - 45PON	IE-DIV QUAL ASSUR SPGDS 6 INSP
SECTION CHIEF	DIVISION DIRECTOR
INCIDENT RESPONSE BE SECTION B	EWS-360
WASHINGTON DC 20555	
120555063643 1 99999	120555063644 1 99999
TR-DIT OUAL ASSUR STODS & THEP	IE-DIV QUAL ASSUR SPEDS & INSP
BRANCH CHIEF	BRANCH CHIEF
SPGDS & MATLS PROGRAMS BR	OPERATING REACTOR PROGRAMS BR
WASHINGTON DC 20555	WASHINGTON DC 20555
120555063645 2 99999	120555078894 1 99999
TR-DIT OUAL ASSUR SPEDS & THSP	TR-DIV QUAL ASSUR SPGDS & THSP
BRANCE CETEF	PAANCH CHIEP
REACTOR CONSTRUCTION PROGAS BR	QUALITY ASSURANCE BE
HASHINGTON DC 20555	WASHINGTON DC 20555
120555082518. 1 99999	137411078989 1 99999
IE-DIV ORAL ASSOR SPGDS & INSP	IE-TECHNICAL TRAINING CENTER
DEPUTT DIVISION DIRECTOR	CENTER DIRECTOR
EWS-360	TTC
WASHINGTON , DC 20555	CHAITABOUGA IN STOLL
110511051346 1 99999	110511080042 1 99999
THOTAN POTHE 2 HPS	THOTAN POINT 3 MPS
RESIDENT INSPECTOR, 4	RESIDENT INSPECTOR
PO BOT 38	PO BOX 66
BUCHANAN NI 10311	DUCBARAN BE INJII
154216055881 1 99999	154632055886 1 99999
KEWAUNER NPS	LA CROSSE MPS
BESIDENT INSPECTOR	RESIDENT INSPECTOR
BTE 1 BOX 999 HT 54216	GRNOA BOL 2/6 NT 54632
REFRUIES IN JALIS	CAPACITY CAPACITY
161341051325 1 99999	11940403J340 1 39999
LASALLE TPS	LINERICK NPS
RESIDENT INSPECTOR	RESIDENT_INSPECTOR
TE 1 BOI 224	SAMATOGA PA 19468
100570055056 1 00000	147147057577 1 40000
104578055456 1 99999	US NRC 99999
BAINE TANKEE MPS	HARBLE HILL MPS
RESIDENT INSPECTOR	BESIDENT INSPECTOR
PC BOL E AF 04578	WARR TH A7147
139079057870 1 80000	148640051318 1 00000
US MRC	US NRC 99999
HCGUIRE MPS	HIDLAND NPS
BESIDENT INSPECTOR	RESIDENT INSPECTOR
HONTERSVILLE NC 28078	NTDLAND NT 48640
106 38 50 9 32 6 1 80 000	104357078858 1 00000
US MAC 77779	US NRC 77777
MILLSTONE III NPS	MILLSTONE NPS
SR RESIDENT INSPECTOR	RESIDENT INSPECTOR
WATERFORD CT DATAS	HTANTIC CT 06357

US MRC	US HIC
BESIDENT INSPECTOR	RESIDENT LUSPECTOR
TORRIS IL 60450	PALO IA 52324
120555067244 1 99999	136319065849 1 99999 .
US HRC EDO	US NRC PARLET NPS
TECHNICAL ASSISTANT	BTE 2 PO BOI 24
WASHINGTON DC 20555	COLUMNIA AL 36319
148 1660 56 259 1 99999	113093057158 1 99999
PERAL BPS RESIDENT INSPECTOR	PITEPATRICK NPS RESIDENT INSPECTOR
SASS BORTE DILLE HUY BEWPORT NI 48166	PO BOX 136 LYCOBING NY 13093
	100451051331 1 00000
168023057474 1 59559 US BC	US NEC
ESIDENT INSPECTOR	PESIDÊNT INSPECTOR
FORT CALBOUN NE 68023	PLATTEVILLE CO 80651
114519057473 1 99999	139150056255 1 99999
GINNA NPS	GRAND GULF NPS
1503 LARB RD NY 14519	TE 2 BOX 399 PORT GIRSON MS 39150
106423056254 1 99999 US MRC	127562057157 1 99999 US NBC
RADDAN BECK BPS RESIDENT INSPECTOR	BESIDENT INSPECTOR
BAST HADDAN POST OFFICE CT 06423	NEW BILL WC 27562
108038055459 1 99999	120555063603 1 99999
NOPE CREEK MPS	US NRC
PO BOI 241	EVV-359
HANCOCKS BEIDGE IJ 08038	
120555063606 1 99999	120555063634 1 99999 US BRC
BRANCH CHIEF	DEPUTY OFFICE DIRECTOR
PROGRAM SUPPORT BR EVU-359	WASHINGTON DC 20555
WASHINGTON DC 20555	120555056768 1 40040
	US NEC TREP PREP 6 ENGR HESPON
STAFF DIRECTOR	BRANCH CHIEF BATEGENCY PREPAREDNESS BR
END-359 WASHINGTON DC 20555	ENV-359 WASHINGTON DC 20555
120555063622 1 99999	120555063633 1 99999
IE-DIV ENER PREP & ENGR BESPON	IE-DIV ENER PREP 6 ENGR RESPON
ENN-359 WASHINGTON DC 20555	WASHINGTON DC 20555
120555063639 1 99999 US NRC	120555063649 1 99999 US NRC
BRANCH CHIEF	BRANCH CHIER FREP 5 ENGR RESPON
EVENIS ANALISIS DE EVS-305A WASNINGTON DC 20555	EVS-312A WASHINGTON DC 20555

US BRC ASLOP	•••••	US NAC ASLAP ASSISTANT RECOTIVE	RCRETARY
EUS-439 WASHINGTON	DC 20555	WASAINGTON	DC 20555
120555028228 1 US HAC ASLBP LIBRARY LIBRARY	99999	120555067119 1 US NEC ASLEP TECHNICAL ADVISOR	99999
ULS RIÚGTON .	DC 20555	VASBINGTON	DC 20555
115077052530 1 US HBC BEAVE VALLEY 1 HPS BESIDENT IN SPECTOR PO DOL 298	99999	115077077514 1 US NEC DEAVER VALLEY 2 NPS RESIDENT INSPECTOR PO BOX 181	99999
SEIPPINGPORT	PA 15077	SHIPPINGPORT	PA 15077
135752056922 1 95 NC BELLEFONTE NPC RESIDENT INSPECTOR PO BOI F77	99999	149720055885 1 US NAC BIG ROCK POINT NPS ESIDENT INSPECTOR REJ BOX 600	99999
TOTLYANOD	AL 33/32		
IGGAO7078948- 1 US WRC BRAIDWOOD WPS RESIDENT INSPECTOR BR 1 BOX 79 BRACEVILLE	99999 IL 60407	IS AC BPOWS FERSINS RACIDENT INSPECTOR ROUTE 2 PO BOI 3 ATHENS	11 35611
128461051337 1	99999	161010066839 1	99999
US WEC BRUNSWICK NPS BESIDENT INSPECTOR. STAR RTE 1 BOX 208 SOUTHPORT	BC 28461	US NEC BIRON NPS RESIDENT INSPECTOR 4448 NORTH GERMAN CH BIRON	"IE" Bloro
165077052529 1 US MAC CALLAWAY NPS RESIDENT INSPECTOR 1 BOT 1	99999	120657055454 1 US NRC CALVERT CLIPP NPS RESIDENT INSPECTOR PO BOL 437	99999
STREDALD	NO 65077	LUSBY	ED 20657
129745066556 1 US NEC CATAWBA WPS RESIDENT INSPECTOR ROUTE 2 BOX 1798	99999	161727055455 1 US NEC CLINTON NPS RESIDENT INSPECTOR RESIDENT INSPECTOR RESIDENT INSPECTOR	99999
TORK	SC 29745	CEINION	
176043051311 1 US NRC Comanche peak NPS Besident inspector Po box 38	99999	168321064276 US NRC COOPER STATION NPS RESIDENT INSPECTOR PO BOI 218	99999
GLEN ROSE	TI 76043	MEGABAILLE	NE 08321
132629054656 1 US NBC CRYSTAL RIVER NPS RESIDENT INSPECTOR RTE 3 BOI 717 CRYSTAL RIVER	99999 PL 32629	149127051324 US WRC D C COOK MPS RESIDENT INSPECTOR 7700 RED ARROW HWT STEVENSVILLE	99999 NI 49127
143449051326 1 US NBC DAVIS BESSE NPS BECIDENT INSPECTOR	99999	193424053477 1 US NRC DIABLO CANYON NPS RESIDENT INSPECTOR	99999
OAK HARBOR	Ó# 43449	AVILA BEACH	CA 93424

..

US ENVIA PROTECTION AGENCY REGION V EIS COORDINATOR 210 S DEARBORD ST CHICAGO IL 60604	US ENVIE PROTECTION AGENCY REGION V OPPICE-PRD ACTIV BR REGIONAL RADIATION R2P 230 S DEARBORN ST CHICAGO IL 60604
275270006534 1 99999 US ENVIR PROTECTION AGENCT REGIONAL RADIATION BEP 1201 ELE STREET DALLAS TI 75270	275231005813 1 99999 US ENVIR PROTECTION AGENCY REGION VI OFFICE 15 COORDINATCE 201 ELE ST INTERFIRST TWO BLD DALLAS TX 75231
264106005926 1 99999 US ENVIE PROTECTION AGENCY REGIONAL RADIATION REP 324 E 11 STREET RANSAS CITY NO 64106	189114082430 1 99999 US ENVIR PHOTECTION AGENCY ENVIR HONITORING SYSTERS LAB JOHN L CONNELLY PO BOI 15027 LAS VEGAS NV 89114
220472005740 1 99999 US PED ERERGENCY MGHT AGENCY GENERAL COURSEL DOCKET CLZRK 1725 I STREET NN WASHINGTON DC 20472	120426064596 1 99999 US PED ENERGY REG COM E H DAWSON ACCOUNTANT (DOE-FERC-OCA) 825 NORTH CAPITOL ST RE WASHINGTON DC 20426
220515006403 1 99999 US NOUSE OF REPRESENTATIVES TON CORCORAN DC 20515	220515001253 1 99999 US HOUSE OF REPRESENTATIVES LAWERICE COUGHLIN WASHINGTON DC 20515
120515081496 1 99999 US HOUSE OF REPRESENTATIVES ENVIE ENERGY 6 WATL RESOURSES JOHN R GALLOWAY SUBCRTE STAPP DIRECTOR RATEUR HOB ROOM P-371 DC 20515	120515081521 1 99999 US HOUSE OF REPRESENTATIVES CHTE ON INTERIOR & INSULAR APP RICHARD UDELL SUBCHTE ON OVERSIGHT & INVEST HOUSE ANNEL 1-818 DC 20515
120380079658 1 99999 US HARINE CORPS BEADQUARTERS COMMANDANT OF THE MARINE CORPS ATTN RASP LMA 3 WASHINGTON DC 20380	120590006830 1 99999 US MARITIME ADMINISTRATION OFC OF ADVANCED SHIP OPERATHS 2 LEVING MAR-930 ROOM 4100 WASHINGTON DC 20590
120555003911 1 99999 US NEC ACES EXECUTIVE DIRECTOR E-1016 WASHINGTON DC 20555	120555012329 105 99999 US MEC ADM-DIV OF RULES & RECORDS BRANCH CHIEF LOCAL FUBLIC DOCUMENT ROOM BR ANDB-7414 NASHINGTON DC 20555
120555003956 1 99999 US NRC ADR-DIV OF TIDC BRANCH CHIRF RECORDS SERVICES BR 042 WASHINGTON DC 20555	120555004281 1 99999 ADH-DIV OF TIDC BRANCH CHIEF DOCUMENT HANAGEMENT DP W-548 WASHINGTON DC 20555
120555051515 1 99999 US NBC A BOD DIR BCTOR EWS-263A WASHINGTON DC 20555	172801051532 1 99999 US NEC ARKANSAS 1 HPS RESIDENT INSPECTOR POX 200 RUSSELLVILLE AR 72801
120555003909 1 99999 US BRC ASLAP CHAIRMAN ENU-529 WASHINGTON DC 20555	120555082279 1 99999 US NAC ASLAP VICE CHAIRNAN EWW-529 WASHINGTON DC 20555

187115091948 1 99999	160439082730 1 99999
US DOE ALBUQUERQUE OPERATIONS	US DOE CHICAGO OPERATIONS
E VALENCIA	DIV OPER & ENVIRON SAPETY
PO BOX 5400	DIRECTOR
ALBUQUERQUE NH 87115	ARGONNE IL 60439
160439092866 1 99999	160439092865 1 99999
US DON CHICAGO OPERATIONS	US DOE CHICAGO OPERATIONS
PROJECT MERT & ENGINEERING DIV	TECH HANAGEMENT DI
NICHAEL FLANNIGAN	PAREEL SINS
9800 SOUTH CASS AVE	9800 South Cass ave
ARGONNE IL 60439	Argonne IL 60439
18340 10 28822 1 53999	183401005974 1 99999
US DOR IDANO OPERATIONS	US DCB IDAHO OPERATIONS
R J BEZES	B B TILLER
550 200 ST	550 SECOND STREET
IDANO PALLS ID 83401	IDAHO FALLS ID 83401
189114006949 1 99999	237830005320 1 99999
US DOE NEVADA OPERATIONS	US DOE OAK BIDGE OPPATIONS
OFFICE OF SAFETY & BEALTH	CLINCH RIVER BREEDER JEACTOR
SHED B ZLLIOTT	PLANT PROJECT OFFICE
DIRECTOR	PO BOX 0
PO BOI 14100	OAK BIDGE 37830
137830082334 1 99999	137830091930 1 99999
US DOR OAK RIDGE OPERATIONS	US DOR OAK BIDGE OPERATIONS
CLINCE BIVES BREEDER BRACTOR	SAPETT & ENVIR CONTROL DIV
P GROSS	W H TRAVIS
ASSISTANT DIRECTOR	PO BOX E
PO DUX U	OAK BIDGE TH 37830
199352027006 1 99999	199352005965 1 99999
US DOE RICHLAND OPERATIONS	US DOB RICHLAND OPRRATIONS
DIV OF WASTE HANAGEBET	J N STRAUB
BOJ & GERTON	DIRECTOR OA OPPICE
CHIEP-OPERATIONAL UST HEGT BE	PO BOI 550
PO BOX 550	RICHLAND NA 99352
BICHLAND UA 99352 194612071931 1 99999 US DOB SAM PRANCISCO P BARIREZ 1333 BROADWAY OAKLAND CA 94612	12980 109 1928 1 99999 US DOR SAVANNAH RIVIR OPER SAPETY DIV V A BERSE PO BOE A AIKEN SC 29801
140207026663 1 99999	260604006242 1 99999
US ECOLOGY INC	DS REVIE PROTECTION AGENCY
W M BIPSHER	PEDERAL ACTIVITIES BRANCH
HAWAGER CORPORATE SAFETY	REGIONAL BAD REPRESENTATIVE
PO BOX 7246	230 SOUTH DEARBORN ST
LOUISVILLE KY 40207	CHICAGO IL 60604
280203006314 1 99999	202203005405 1 99999
US ENVIR PROTECTION AGENCY	US ENVIE PROTECTION AGENCI
BADIATION PROGENS	REGION I OFFICE
REGIONAL REF. ENTATIVE	BEG BADIATION REPRESENTATIVE
1860 LINCOLN SEET	JPK FEDERAL BUILDING
DENVER CO 80203	BOSTON NA 02203
210278005326 1 99999	219106005452 1 99999
US ENVIR PROTECTION AGENCY	US ENVIR PROTECTION AGENCY
BEGION II OPPICE	REGION III OFFICE
REGIONAL RADIATION REP	REGIONAL RADIATION REP
26 PEDERAL PLAZA	6TH & WALNUT STREET CORTIS BLD
NEW YORK NY 10278	6TH FLOOR
230308005732 1 99999 US ENVIR PROTECTION AGENCY REGION IV OPPICE REGIONAL BADIATION REP 345 COURTLAND ST WE ATLANTA GA 30308	PHILADELPUIA PA 19106 294105006284 1 99999 US ENVIR PROTECTION AGENCY REGION IX OPPICE REG RADIATION REPRESENTATIVE 215 PHEENONT STREET SAN PRANCISCO CA 98105

DIRECTOR TE	ST VALLET DENO PROJECT
USALINGTON DC 20545 VE	ST VALLEY BY . 14171
120545067122 1 99999 11 US DOE TASK PORCE POR MRC COORDINATH TH BODERT W BARBER CHAIRMAN	TOSTOZE469 1 99999 DOR I SITE OFFICE BITEY
ATTINGION DC 20343 PO	DDLETONN PA 17057
111973055306 1 99999 12 US DOB BROOKNAVEW ABEA OPPACE HICHAEL A BUTLER REACTOR SAPETY SPECIALIST UPTON UPTON UPTON UPTON	O545091943 1 99999 DDE CLEAR RHERGY B CHITHOOD RHANTOWN OPPICE -43 SHINGTON DC 20545
120545091933 1 99.99 12 US DOE DEPENSE PROGRA4S US COCHEAN COCHEAN GENANTONN OFFICE DE-13 NASHINGTON - LC 20545 NA	D545091950 1 99999 DOB VIR PROT SPTY 6 ENER PREP U DEVEREUI C QUAL ASSUR 6 STAND-GTOWN -35 SNINGTON DC 2545
120545064078 1 99999 12 US DOE COORDINATION 6 SPEC PROJECTS REPORT P PRIMOTE B-107 VASHINGTON DC 20545 DE	DS45091936 1 99999 DOE PENSE PROGRAMS A FORSTINE RNANTOWN OFFICE 226 SEINGTON DC 20545
120545091935 1 99999 12 US DOE DEFENSE PROGRAMS J GALBO GERMANTOWN OFFICE DP-133 WASHINGTON DC 20545 WA	DOSA5091927 1 99999 DOE PENSE PROGRAMS J GRETTI RNANTONN OFFICE -30 SNINGTON DC 20545
197310038384 1 99999 12 US DOR SITING & REGULATION DE DOWALD W GODARD R LASON & INDUSTRIES BLDG GR BOOM 111 SALER OR 97310 WA	10545291937 1 99999 DOB PENSE PROGRAMS R HEUSSER R NANTONN OFFICE 132 SHINGTON DC 20545
183451092238 1 99999 12 US DOE US INZL-EGEG US JAITS A HUNTER S PO BOI -1625 GE TSB-B ID 83451 WA	DOSA5091944 1 99999 DOE ENERGY J LANES REANTONN OFFICE -50 NUNGTON DC 20545
120545091932 1 99999 12 US DOB OFC SAPETY 6 QUALITY ASSUBANCE EN S REALTOVICE GREATOVICE	D545091943 1 99999 DOE REGY RESEARCH-OFC PUSION ENG L OPDEWARER RHANTOWN OFFICE -532 SATURTON DC 20545
120545091938 1 39999 12 US DOB US DOB US DEPENSE PROGRAMS DE DE SCOTT DE NPM GERMANTOWN OPPICE GE DP DP US DASHINGTON DC 20545 VA	OSASO91934 1 99999 DOE PRUSE PROGRAMS D SIMPSON RMANTOWN OFFICE -131 SHINGTON DC 20545
187115055305 1 99999 18 US DOE ALBUQUERQUE OPERATIONS US DIV OPER & ENVIRON SAFETY OP PO BOX 5400 R RCSB PO ALBUQUERQUE NM 87115 AL	TISO91929 1 99999 DOE ALBUQUERQUE OPERATIONS ERATIONAL SAPETY DIV L HILLER BOI 5400 BUQUERQUE NN 87115

UNIVERSITT-PURDUP SCHOOL OF NUCLEAR ENGR ELOON & STAVSDERRY EACTOR SUPERVISOR UEST LAPATETTE IN 47907	UNIVERSITY-ST BONAVENTŰÁÉ SCHOOL OF BUSINESS S MAI ASSOC PROF OF FINANCE ST BONAVENTURE NY 14778
213210001373 1 99999 PHIVERSITT-SYRACUSE COLLEGE OF LAW BICEARD GOLDSHITH I WHITE HALL CAMPUS STRACUSE WY 13210	119140066216 1 99999 . UNIVERSITI-TRAPLE RDIATION SAPETY OFFICE JOSRPH LAU ASST RADIATION SAPETY OFFICER 3JO7 NORTH BROAD ST PHILADELPHIA PA 19140
177843080937 1 99999 UNIVERSITI-TEIAS AGH UNIVERSITI BESEARCHOPC DOWALD E FELT CHIEF ADMINISTRATIVE OFFICER COLLEGE STATION TI 77843	126505080948 1 99999 UNIVERSITI-VEST VIRGINIA COLLEGE OF ENGINEERING EXCTOR DIRECTOR HORGANTONN NV 26505
101923066627 1 99999 UES JONN A BLUNE & ASSOC ENGR BOSTON OPPICE 130 STLVAN STREET DANVERS HA 01923	194105066497 1 99999 URS JOHN A BLUME & ASSOC ENGR BAVINDRA P HISTRY PROJECT HANAGER SAN PRANCISCO CA 9410
194105091222 1 99999 UES JOHN & BLUNE & ASSOC ENGR LANDON B PHILLIPS 130 JESSIE ST SAM PRANCISCO CA 96105	220590006297 1 99999 DS COAST GUARD OFFICE OF HERCHANT HABINE SPTY BUCLEAR COORDINATOR COEDINAT GRET-4 WASHINGTON DC 20590
140226092713 1 99999 DS DEPT OF ARAY US COEPS OF ENGINEERS FELL GENEING 477 NICHIGAN AVE NCEED-T BI 48226	147111079655 1 99999 DS DEPT OF PIELD SPTY ACTIVITY JAMES D LLOYD DIRECTOR CHARLESTOWN IN 47111
220 2400 06 321 1 99999 US DEPT OF INTERIOR NATIONAL PARK SERVICE NICHARD BAICELAND ASSOC DIRECTOR-SCIENCE 6 TECH VASHINGTON DC 20240	180225079373 1 99999 US DEPT OF INTERIOR US GEOLOGICAL SURVEY D H RUSLING PRDERAL CENTER 424 BOX 25046 CO 80225
120910092711 1 99999 US DEPT OF WAYY HAVAL SURPACE WEAPONS CENTER P C HUANG COMMANDER UBITE OAK	120545025203 1 99999 US DOE DIY OF NAVAL REACTORS ASSISTANT DIRECTOR REACTOR CONP HE-GO
120585006812 4 39999 US DOE DIV OF HAVAL REACTORS ASSISTANT DIRECTOR REACTOR SAPETY 6 COMP WASHINGTON DC 20585	120545091939 1 99999 US DOB NUCLEAB ENERGY DIRECTOR-STORAGE & TREAT PROJ GENMANTOWN OFFICE NE-25 NASHTNGTON DC 20545
120545091940 1 99999 US DOB BUCLEAR ENERGY DIFECTOR-BUC REGULATION 6 SPTY GERMANTON B OFFICE WF 12 US ALLINGTON DC 20545	120545091941 1 99999 US DOE NUCLFAR ENERGY DIRECTOR-REMEDIAL ACTION PROJ GERMANTOWN OFFICE NE-24 WASHINGTON DC 20545
120345091942 1 99999 US DOR DIRECTOR-NARKETING & BUSINESS GERMANTOWN OFFICE NE-32	120545091945 1 99999 US DOE NUCLEAR ENERGY DIRECTOR-SFTY OA 6 SPGDS GERMANTOWN OPPICE NE-74
MASHINGTON DC 20545	MASHINGTON DC 20545

..

UNITERSTITION TILLS 99999 UNITERSTITION TILLS NECHANICAL ENGINEERING D. R. 22010 T. 74712 T. 74712	18-11/000 1/2 1 99999 UNIVESITY OF UTAR SALT LAKE CITY SALDUT 84112
122901001042 1 99999 GUIVESITY OF VINGINIA DIRECTOR OF REACTOR PACILITY CHARLOTTESVILLE VA 22901	198195007710 1 99995 UNIVERSITY OF WASHINGTON SCHOOL OF OCEANOGRAPHT GEORGE C ANDERSON DIR ECTOR WB-10 SEATTLE WA 98195
184602079366 1 99999 UBIVEASITT-BRIGHAN TOURG COLLEGE PRTS & MATREMATIC SCI PACILITY CHIEF PROVO DT 84602	120064079399 1 99999 DELYERSITT-CATHOLIC PARENDE SAFETT OFFICIAL PANGEOGRA HALL DASSINGTON DC 20064
114653000241 1 99999 UNIVERSITT-CORNELL VARD REACTOR LABORATORY HOW REACTOR SUPERVISOR EACTOR SUPERVISOR ITRACA NY 14853	114850079901 1 99999 UNIVERSITY-COBNELL OFFICE OF ENVIRONMENTAL HEALTH W EXEMPT DIRECTOR 116 MAPLE AVE ITMACA NY 14850
219104005313'1 99999 UNIVERSITT-DEELEL ENVIRONALITAL STUDIES GROUP FAUL PFUEDON DIRECTOR 3200 6 CRESTAUT STREETS 19104	183209079368 1 99999 UNIVERSITI-IDAKO STATE SCROOL OF ENGINEERING NYRON CONSTRUCTOR SAFETY CONNITTEE POCATELLO ID 83209
138152000193 1 99999 UNIVERSITT-ARMPHIS STATE CENTER FOR WOCLEAR STODIES D W JONES D W JONES D W JONES D W JONES TW 38152	148823081067 1 99999 UNIVERSITI-MICHIGAN STATE, COLLEGE OF ENGIPERAING JAMES CAREICF HAST LANSING RESEARCH HI 48823
139762080968 1 99999 DELYERSITT-RISSISSIPPI STATE DEPT OF RECH & BUCLEAR ENGIG C T CARLET BEAD FO DRAWER HE FO DRAWER HE	11421-080941 1 99999 UNIVERSITY-NEW YORK STATE BUFF-SUC SCI & TECH PACILITY 14214 ECTARY ROAD BY 14214
114260079414 1 99999 UMIVERSITY-BEN TORE STATE RES & GRAD STUDIES DOWALD & REBAILS VICE PRESIDENT SCI CAPEN HALL NY 14260	160115021248 1 99999 UBI TEPLITI-BORTHERN ILLINOIS BIOLOGICAL SCIENCES DEFT DECA VON BELLEN LL 60115
143210079377 t 99999 UNIVERSITI-OF & STATE RACIATION SCRATT CACRGE & KATE MEALTH SCIENCES STAPP REP RA 232-370 W 958 AVE OF A7210	197331007631 1 99999 UNIVERSITT-OBEGON STATE SCHOOL OF OCEANOGRAPHY ROBERT L NOLTON ASLEP CORVALLIS OR 97331
116802031127 1 99999 UNIVERSITY-PENNSYLVANIA STATE REALTH PHYSICS OFFICE REALTH PHYSICIST 228 ACADENIC PROJECTS BLDG	116802031124 1 99999 UNIVERSITY-PENNSYLVANIA STATE PHYSICS DEPARTMENT WILLIAN A LOCHSTET 104 DAVET LAB UNIVERSITY PARK PA 16802
108558066980 1 99999 UNIVERSITY-PRINCETON SCHOOL OF ENGIG & APPLIED SCI ROBERT C AXTHANN ACRS DET C C AND NJ 08558	147907007317 1 99999 UMIVERSITY-PURDUE DEPT OF NUCLEAS ENGINEERING PAUL LYKOUDIS WEST LAPAYETTE IN 47907

UNITED ILLUMINATING CO JOHN D PASSETT PRESIDENT 60 TEMPLE STREET BEN MAYEN CT 06506	UNITED NUCLEAR CURP NUCLEAR & IND SAPETY DEPT UILLIAN P RISK RAWAGER 67 SANDY DESERT BD UNCASVILLE CT. 06382
15533COOB693 1 99999 UNITED POWER ASSOCIATION JACOBD NORDBERG PRESIDENT ELK RIVER NN 55330	107030039638 1 UNITED STATES TESTING CO GENE BASILE 1415 PARE AVENUE BOBOKEN NJ 07030
246312005359 1 99999 DHITED STEELWORKERS OF AMERICA LOCAL 1010 MEZO ACTING PRESIDENT 3703 EUCLID AVE HAS12	1CANADOS1598 1 99999 UNIVERSITE LAVAL PUBLIC HEALTH DEPT DSC PAUL LACHANCE LE CHUL 2705 BLVD LAURIER LE CHUL GIV 4C2 SAINTE-POT QC CANADA
190024077560 1 99999 UIVERSITY OF CALIFORNIA SCHOOL OF RHGRG & APPLIED SCI DAVID OKRENT 5532 BOELTER MALL ACRS ACTINE CA 90024	132611009360 1 99999 DEPT OF BUCLEAR SCIENCES ENGR DISBCTOR 202 BUCLEAR SCIENCES CENTER 202 BUCLEAR SCIENCES CENTER 202 BUCLEAR SCIENCES CENTER 202 BUCLEAR SCIENCES CENTER 201 BUCLEAR SCIENCES CENTER
132 - 10 80950 1 99999 UIVESITY OF PLORIDA DEPT-BOCLIAR ENGIG SCIENCES A B JACOBS CAIDENAR 202 BUCLEAR SCIENCES CTR	132611082349 1 99999 UNIVESTIOF PLOBIDA NUCLEAR ENGR SCIENCES DEPT JA WTHINGTON 202 NUCLEAR SCIENCES CENTER 202 NUCLEAR SCIENCES CENTER 202 NUCLEAR SCIENCES CENTER
166044021426 1 99999 UNIVERSITY OF KAUSAS SCHOOL OF EVGINEERING BUSSELL MESLER BLACTOR SUPERVISOF 102 NUCLEAR BEACTOR CENTER 102 NUCLEAR BEACTOR CENTER	101854060944 1 99999 UNIVERSITY OF LOWELL ACTING DIRECTOR OF NUCLEAR CTR 1 UNIVERSITY AVE LOWELL NA 01854
101854006416 1 99999 URIVERSITY OF LOWELL UCLEAR CENTER T VALLACE BRACTOR SUPERVISOR 1 URIVERSITY AVE A 01854	120742079419 1 99999 DHIVESITY OF HABYLAND BELCHEL BRACTON DIRECTOR COLLEGE PARK HD 20742
265211006405 1 99999 UNIVERSITY OF MISSOURI MISSOURI/KAWSAS SEC-AM BUC SOC WILLIAM M MILLER DEPT OF BUCLEAR ENGINEERING 1026 ENGINEERING BLDG COLUMBIA	187131066750 1 99999 UNIVERSITY OF NEW ABIICO DEPT CHEMICAL & NUCLEAR ENGR J C ROBERTSON CHIEF REACTOR SUPERVISOR ALBUQUERQUE NA 87131
227514007044 1 99999 UNIVERSITY OF WORTH CAROLINA ENVIRONMENTAL LAW PROJECT GEORGE JACKSOM SCHOOL OF LAW 064-A CHAPEL WILL NC 27514	173019080062 1 99999 UNIVERSITT OF OKLAHOMA SCHOOL-CIVIL ENG & ENVIRON SCI EDWIN H KLERE CHAIRMAN BRACTOR SAPETY COMM 202 W BOYD WORNAN OK 73019
192110065279 1 99999 DETERSITION SAN DIRGO REVIEW TIAW CLINIC ICHARD J WHARTON ALLALA PARK SAN DIRGO CA 92110	178712079370 1 5)999 UNIVERSITY OF TEXAS HECHANICAL BUGG THOMAS BAUER ETC 5, 160 TAY 167 AUSTIN TX 78712
178712091837 1 99999 UNIVERSITY OF TELAS BUREAU OF BECON COLOGY WILLIAM FISSER DIRECTOR GEOLOGY BLDG BOO. 529 AUSTIN TX 78712	178712079372 1 99999 UNIVERSITY OF TEXAS COLLEGE OF ENGINEERING E F GLOYNA DEAN COCKBELL GALL 10 310 AUSTIN TX 78712

142501052887 1 99999 UNION CARBIDE CORP TROMAS WONG COORDINATOR P.O. POI 5100 GAS MILLS BT	UN ION ELECTRIC CO PLANT HANAGER PO BOX 620 BO 65251
263 166001356 1 99999 WIOS ELECTRIC CO 3 B BIR 55 ISTAT TO THE GEN COUNSEL FO BOL 192	263166006486 1 99999 UNION ELECTRIC CO NUCLEAN BIGINERSING DONALD W CAPONE NAMAGES NAMAGES
IGIIGOGAG77 1 99999 URION ELECTRIC CO J GROSS BECORDS NANAGERENT SUPVE OF DOI 149	ST LOUIS NO 63166 165251004692 1 99999 UNION BLECTRIC CO UNION BLECTRIC CO UNION BLECTRIC CO REPERBNCE RM
It Louis It couis 165251081504 1 99999 UBION ELECTRIC CO STRVE BILTENBREGER POLTON NO 65251	FULTON NO 65251 163166079475 1 99999 UNION BLECTRIC CO SUPERITURNENDENT LICENSING PO FOR 149 PO FOR 149 ALLCODE 63166
163166002916 1 99999 UNION REPOTRIC CO NOCLEAR ENGINEERING DEPT D F SCHWELL D F SCHWELL D F SCHWELL	163166079379 1 99999 UNION PLACTAIC CO UNCLEAR CONSTRUCTION A AGE AND ANY CONTAIN
PO POI 145 P/C-400 ST LOUIS NO 63166 220036005756 1 99999 UNION OF CONCENTED SCIENTISTS 1346 CONNECTICOT AVE WW SDITE 1101 DC 20036	PO DU 149 HAIL CODE CO 63166 149016091721 1 99999 99999 99999 99999 90100 99999 90100 900000 900000 90000
148184091732 1 99999 UNISTRUT CORP. BRUCE ACCLURE OC MANAGER OC MANAGER ED PO BOX 802 UNIVE NATUR ED PO BOX 802 UNIVE	146184053126 1 99999 UNISTRUT CORP PARAGER ODALITY CONTROL 4118 SOUTH WAIDE BD RI 48184
102172091771 1 99999 UNITED ELECTRIC CONTROL CO WILLIAN E CARDILLO ON HANGER 85 SCHOOL ST WATERTOWN BA 02172	130067091335 1 99999 UNITED BERRY SERVICES CORP 1640 POWRES PERET ED SE BLDG-1 ATLANTA GA 30067
119101008692 1 99999 UNITED ENGLERES & CONSTRUCTION SAPETY LIC ADVANCED ENGE DEPT NEWLY L DEBNAMIS 30 SOUTH 17TH STREET BOX 8223 POX 8233 POX 8233	219101005492 1 6 CONSTRS INC DELTED ENGINEERS 6 CONSTRS INC A BOUTE 17TH ST PO BOX 8223 30 SOUTH 17TH ST PO BOX 8223 PHILADELPHIA PA 19101
2 19 10 1001 345 1 99999 UNITED ENGINEERS & CONSTRUCT TANIL 30 SOUTH 17TH STREET PHILADELPHIA PA 19101	199352064745 1 99999 UNITED ROGINEERS & CONSTRUCT J P MCCALES SUPERVISE POCUMENT CONTROL 1019875208-DOCUMENT CONTROL 1019875208-DELVE VA 99352
1 19 10 100 1238 1 99999 UNITED ENGINEERS & CONSTRUC POWER DIV JOHN J PANISANO PO BOI 8223 POBLADENIA PA 19101	119101091733 1 99999 UNITED ENGINEERS & CONSTRUCT J B TILTERWOOD OA MANAGER JO STATE ST PHILADELPHEL PA 19101