



September 11, 2008

U.S. Nuclear Regulatory Commission
Washington, DC 20555

ATTENTION: Document Control Desk

SUBJECT: Calvert Cliffs Nuclear Power Plant
Unit No. 1; Docket No. 50-317; License No. DPR 53
Licensee Event Report 2008-002, Revision 0
Pressurizer Safety Valve Setpoint High Due to Low Torque and Misalignment

The attached report is being sent to you as required by 10 CFR 50.73. Should you have questions regarding this report, please contact Mr. Jay S. Gaines at (410) 495-5219.

Very truly yours,

A handwritten signature in blue ink, appearing to read "DRB", with a long horizontal flourish extending to the right.

Douglas R. Bauder
Plant General Manager

DRB/ALS/bjd

Attachment: As stated

cc: D. V. Pickett, NRC
S. J. Collins, NRC

Resident Inspector, NRC
S. Gray, DNR