

September 30, 2008

Mr. Steve Garchow
USNRC
Region IV
Texas Health Resources Tower
611 Ryan Plaza, Suite # 400
Arlington, TX 76011-4005


Dear Mr. Garchow:

Please find enclosed the following for the September 2008 San Onofre Written exam;

SONGS September 2008 ES-403-1, Written Examination Grading Quality Checklist
Exam Seating Chart
Exam Analysis for the September 2008 SONGS Exam
Exam Proctor Forms documenting applicant questions and clarifications
Each Applicants original answer sheet and exam coversheet
A clean copy of each answer sheet
Copies of ES-201-3 Examination Security Agreement forms

Please contact me at (949) 368-3807 or (760) 504-9071 with any questions.

Respectfully,



William Arbour
Simulator Support / Exam Supervisor
San Onofre Nuclear Generating Station

2008 NRC Written Exam Analysis

Common Question 6

This question was missed by 4 of 9 applicants.

Topic: Safety Injection and Containment Spray

The question is technically accurate, as written. Applicants did not recall the correct answer.

Common Question 34

This question was missed by 3 of 9 applicants.

Topic: Containment Purge

The question is technically accurate, as written. Applicants did not recall the correct answer.

Common Question 37

This question was missed by 5 of 9 applicants.

Topic: Condenser Air Removal

The question is technically accurate, as written.

Common Question 46

This question was missed by 5 of 9 applicants.

Topic: Pressurizer Pressure Control Malfunction

The question is technically accurate, as written.

2008 NRC Written Exam Analysis

Common Question 60

This question was missed by 3 of 9 applicants.

Topic: Loss of Source Range Nuclear Instrumentation

The question is technically accurate, as written

Common Question 64

This question was missed by 3 of 9 applicants.

Topic: High Reactor Coolant Activity

The question is technically accurate, as written.

Common Question 76

This question was missed by 3 of 3 applicants.

Topic: Inadequate Core Cooling

The question is technically accurate, as written. Applicants confused inadequate core cooling with insufficient subcooling.

A notification has been written to include the analysis and the review of questions missed in the initial license training program. Not # 200161004