

"Saving People Money So They Can Live Better"



Environmental Services

Rich Dailey, Sr. Director

Radiation Safety Officer

1300 SE 8th Street, MS 0605
Bentonville, AR 72716-0605
Phone 479.204.9914
Rich.Dailey@wal-mart.com
www.walmart.com

October 3, 2008

Dr. Charles Miller, Director
Office of Federal and State Materials
and Environmental Management Programs
U.S. Nuclear Regulatory Commission
One White Flint North
11545 Rockville Pike
Rockville, MD 20852

Subject: Report of Damaged Tritium Exit Sign

Dear Dr. Miller:

Pursuant to 10 CFR § 31.5(a), Wal-Mart Stores, Inc. ("Wal-Mart") is a general licensee of the Nuclear Regulatory Commission ("NRC") because it possesses and uses byproduct material in the form of tritium exit signs ("TES") regulated by the NRC, in the State of Connecticut. Consistent with 10 CFR § 31.5(c)(5), Wal-Mart is providing the subject report regarding one damaged TES that it discovered at store #2371, located in Wallingford, Connecticut.

Attachment A provides a brief description of the events associated with the damaged TES and corrective actions taken. Information on the damaged TES is provided below:

<u>Serial #</u>	<u>Curies</u>	<u>Damage Date</u>	<u>Store Location</u>
255379	11.5	Prior to 06/2008 (est.)	844 N. Colony Rd., Wallingford, CT

Please contact me at (479) 204-9914, if you have any questions regarding this letter or the attached report.

Sincerely,

Richard Dailey

Radiation Safety Officer
Wal-Mart Stores, Inc.

FSME - Gde 10 - Sensi Review Complete

" Publically Available "

2008/10/07

cc: Angela Washington, Wal-Mart Stores, Inc.
Thomas Poindexter, Morgan Lewis & Bockius LLP

FSMEIO

Attachment A

A. Description of Events

On September 3, 2008, Wal-Mart Stores, Inc. ("Wal-Mart") representatives and its contractor, Shaw Group, Inc. ("Shaw"), visited Wal-Mart store #2371 in Wallingford, Connecticut to inventory tritium exit signs ("TES"). Wal-Mart has retained Shaw, an environmental services contractor with extensive experience in the management of radioactive material, for its company-wide program to inventory TES. During the inventory at the Wallingford store, Shaw discovered one damaged TES with a cracked face plate and broken tritium-containing tubes. The TES was installed in the non-public break room area of the store.

B. Actions Taken

Interviews with the store managers and associates provided no information as to how the TES was damaged, although the individuals interviewed indicated that it was damaged over four months ago. Shaw removed and packaged the TES for transfer according to a protocol established by Isolite, a specific licensee authorized to receive TES for disposal. The Wal-Mart Radiation Safety Officer ("RSO") directed a Certified Health Physicist ("CHP") from Dade Moeller & Associates ("Dade Moeller") to visit the Wallingford store to conduct radiological surveys and decontaminate the areas to ALARA levels, as necessary. Dade Moeller is a contractor retained by Wal-Mart with the responsibility to assess the radiological impacts of damaged TES.

A CHP visited the Wallingford store on September 24, 2008. The CHP interviewed store managers and associates, and also conducted swipe surveys of the areas deemed likely to have become contaminated by wiping a 100 cm² area (approximately 4 X 4 inches) with a paper disk. Wal-Mart anticipates providing the NRC with a supplemental report by October 24, 2008.

C. Long-term Corrective Actions

Wal-Mart has implemented and communicated protocols to its stores for the proper handling of TES to ensure public health and safety and the protection of its employees. It is also inventorying all of the TES at its sites across the country to re-establish the accuracy of its records and to track the current locations of the TES. The intent of this program is to ensure that all TES are accounted for and are handled properly. As a part of this program, Wal-Mart has employed Shaw to inventory TES, and a team of CHPs from Dade Moeller to properly handle TES and prepare and arrange for their return to a specific licensee.

D. Shipping Details

Wal-Mart transferred the damaged TES to a specific licensee authorized to receive damaged TES on September 3, 2008. Wal-Mart will send the NRC a report of that transfer within 30 days after the date of the transfer.