## SAFEGUARDS INFORMATION

October 10, 2008

Mr. J. Randy Johnson Site Vice President Southern Nuclear Operating Company Inc. Joseph M. Farley Nuclear Plant 7388 North State Highway 95 Columbia, AL 36319

SUBJECT: FARLEY NUCLEAR PLANT UNITS 1 AND 2 SECURITY INSPECTION

05000348/2008202 AND 05000364/2008202

Dear Mr. Johnson:

On August 8, 2008, the U.S. Nuclear Regulatory Commission (NRC) completed a security baseline inspection at Joseph M. Farley Nuclear Plant, Units 1 and 2. The inspection covered one or more of the key attributes of the security cornerstone of the NRC's Reactor Oversight Process. The enclosed inspection report documents the inspection results, which were discussed on September 17, 2008, with you and other members of your staff.

The inspection examined activities conducted under your license as they relate to security and compliance with the Commission's rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel.

This report documents one finding of very low safety significance (Green). The deficiency was corrected, and the plant was in compliance with applicable physical protection and security requirements within the scope of the inspection before the inspectors left the site. However, because of the very low safety significance and because it is entered into your corrective action program, the NRC is treating this deficiency as a non-cited violation (NCV) consistent with Section IV.A.1 of the NRC Enforcement Policy. If you contest the NCV in this report, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the Nuclear Regulatory Commission, ATTN.: Document Control Desk, Washington DC 20555-0001; with copies to the Director, Office of Nuclear Security and Incident Response, United States Nuclear Regulatory Commission, Washington DC 20555-001; the Regional Administrator Region II; the Director, Office of Enforcement, United States Nuclear Regulatory Commission, Washington, DC 20555-001; and the NRC Resident Inspector at the Sequoyah Nuclear Plant.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system ADAMS. ADAMS is

Enclosure Contains Safeguards Information. Upon separation, this page is decontrolled.

J. Johnson -2-

accessible from the NRC Web site at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a> (The Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosures will not be available for public inspection. Should you have any questions concerning this letter, please contact us. Your cooperation is appreciated.

Sincerely,

/RA/

Ronald J. Albert, Chief Security Performance Evaluation Branch Security Oversight Division of Security Operations Office of Nuclear Security and Incident Response

Docket Nos.: 50-348, 50-364 License Nos.: NPF-2, NPF-8

Enclosure: Inspection Report 05000348/2008202 and 05000364/2008202 (SGI)

cc w/encl: (SAFEGUARDS INFORMATION)

Ms. Lisa Hogg, Security Manager

Southern Nuclear Operating Company Inc.

Joseph M. Farley Nuclear Plant 7388 North State Highway 95

Columbia, AL 36319

cc w/o encl: Mr. James M. Walker, Jr.

Alabama Director of Homeland Security

PO Box 3711

Montgomery, AL 36109-0711

Mr. Kirksey E. Whatley, Director Office of Radiation Control

Alabama Department of Public Health

The RSA Tower Suite 700 PO Box 303017-3017

Montgomery, AL 36130-3017

## SAFEGUARDS INFORMATION

J. Johnson -2-

accessible from the NRC Web site at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a> (The Public Electronic Reading Room). However, because of the security-related concerns contained in the enclosure, and in accordance with 10 CFR 2.390, a copy of this letter's enclosures will not be available for public inspection. Should you have any questions concerning this letter, please contact us. Your cooperation is appreciated.

Sincerely,

Ronald J. Albert, Chief Security Performance Evaluation Branch Security Oversight Division of Security Operations Office of Nuclear Security and Incident Response

Docket Nos.: 50-348, 50-364 License Nos.: NPF-2, NPF-8

Enclosure: Inspection Report No. 05000348/2008202 and 05000364/2008202 (SGI)

<u>Distribution</u> w/encl: SPEB R/F – C. Grigsby, SPEB D. Riffle, DDSO/DSO E. Crowe, SRI Farley J. Wallo, R-II

<u>Distribution</u> w/o encl: R. Jervey, PM - NRR C. Adkison - PMDA

## ML082880673

□ Publicly Available □ Non-Publicly Available □ Sensitive □ Non-Sensitive

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

OFFICE	SS:DSO/NSIR	TL: DSO/NSIR	SRI:RII/DRS	BC:RII/DRS	BC:DSO/NSIR
NAME	J. Berry	A. Rayland	E. Crowe	M. Ernstes	R. Albert
DATE	10/3/2008	10/8/2008	10/6/2008	10/3/2008	10/10/2008

OFFICIAL RECORD COPY