

October 24, 2008

Vice President, Operations
Entergy Nuclear Operations, Inc.
Pilgrim Nuclear Power Station
600 Rocky Hill Road
Plymouth, MA 02360-5508

SUBJECT: PILGRIM NUCLEAR POWER STATION – CLOSEOUT OF GENERIC LETTER
2007-01 “INACCESSIBLE OR UNDERGROUND POWER CABLE FAILURES
THAT DISABLE ACCIDENT MITIGATION SYSTEMS OR CAUSE PLAT
TRANSIENTS” (TAC NO. MD4364)

Dear Sir or Madam:

On February 7, 2007, the U.S. Nuclear Regulatory Commission (NRC) issued Generic Letter (GL) 2007-01 “Inaccessible or Underground Power Cable Failures That Disable Accident Mitigation Systems or Cause Plant Transients” (Agencywide Documents Access and Management System (ADAMS) Accession No. ML070360665). GL 2007-01 requested that licensees provide the following information within 90 days of the date of the GL:

- (1) A history of inaccessible or underground power cable failures for all cables that are within the scope of 10 CFR 50.65 (the Maintenance Rule) and for all voltage levels including the cable type, cable manufacturer, date of failure, type of service, voltage class, years of service, and the root causes for the failure; and,
- (2) A description of all inspection, testing, and monitoring programs to detect the degradation of inaccessible or underground power cables that support emergency diesel generators (EDGs), offsite power, emergency service water (ESW), service water, component cooling water and other systems that are within the scope of 10 CFR 50.65 (the Maintenance Rule).

In your letter dated May 3, 2007, (ADAMS Accession No. ML071300361), you provided the information requested in GL 2007-01 including: (1) a history of inaccessible or underground power cable failures for all cables that are within the scope of 10 CFR 50.65 (the Maintenance Rule) and for all voltage levels including the cable type, cable manufacturer, date of failure, type of service, voltage class, years of service, and the root causes for the failure; and, (2) a description of all inspection, testing, and monitoring programs to detect the degradation of inaccessible or underground power cables that support EDGs, offsite power, ESW, service water, component cooling water and other systems that are within the scope of 10 CFR 50.65 (the Maintenance Rule).

The NRC staff has reviewed the submitted information and has concluded that for Pilgrim Nuclear Power Station, your response to GL 2007-01 is adequate. Based on this review, your response to GL 2007-01 is considered closed and no further action is requested of you at this time.

- 2 -

If you have any questions regarding this letter, please feel free to contact James Kim at (301) 415-4125.

Sincerely,

/RA/

James S. Kim, Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-293

cc w/encl: Distribution via ListServ

- 2 -

If you have any questions regarding this letter, please feel free to contact James Kim at (301) 415-4125.

Sincerely,

/RA/

James Kim, Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-293

cc w/encl: Distribution via ListServ

DISTRIBUTION:

PUBLIC	RidsOgcRp
LPL1-1R/F	RidsAcrsAcnw&mMailCenter
RidsNrrDoriLpl1-1	RidsRgn1MailCenter
RidsNrrLASLittle	RidsNrrDeEeeb (GWilson)
RidsNrrPMJKim	
RidsNrrDoriIDPR	

ADAMS Accession Number: ML082900100

OFFICE	LPL1-1/PM	LPL1-1/LA	EEEB/BC	LPL1-1/BC
NAME	JKim	SLittle	GWilson	MKowal
DATE	10/21/08	10/22/08	10/22/08	10/24/08

OFFICIAL RECORD COPY