

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 612 EAST LAMAR BLVD, SUITE 400 ARLINGTON, TEXAS 76011-4125

October 17, 2008

Global X-Ray & Testing Corp.
ATTN: William M. Johnston
Radiation Safety Officer
P.O. Box 1536
Morgan City, LA 70381

SUBJECT:

DEFICIENCIES REGARDING NRC LICENSE APPLICATION

Mr. Johnston:

The staff has reviewed your NRC license application dated August 15, 2008. We have identified the following deficiencies. Please provide a response to these deficiencies within 15 business days from the date of this letter, so we can complete our review of your application.

Your response may be provided by email to rachel.browder@nrc.gov or by fax to 817-860-8263. Please include the license, docket and mail control numbers, located at the bottom of this page in your response. If you have any questions regarding this request, please contact me at (817) 276-6552.

- 1. The NRC can not issue a license for physical facilities in areas of Agreement State locations. Please clarify that the locations of use will be temporary jobsites only.
- 2. Please submit operating and emergency procedures for notifying management of equipment malfunction or defects as required by 10 CFR Part 21.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html.

Thank you for your cooperation.

Sincerely,

Rachel S. Browder, Health Physicist Nuclear Materials Safety Branch B

Docket: 030-37816 License: 17-29308-01 Control: 471910