

October 30, 2008

Vice President, Operations
Entergy Nuclear Operations, Inc.
Indian Point Energy Center
450 Broadway, GSB
P.O. Box 249
Buchanan, NY 10511-0249

SUBJECT: INDIAN POINT NUCLEAR GENERATING UNIT NOS. 2 AND 3 – CLOSEOUT OF GENERIC LETTER 2007-01, "INACCESSIBLE OR UNDERGROUND POWER CABLE FAILURES THAT DISABLE ACCIDENT MITIGATION SYSTEMS OR CAUSE PLANT TRANSIENTS" (TAC NOS. MD4337 AND MD4338)

Dear Sir or Madam:

On February 7, 2007, the U.S. Nuclear Regulatory Commission (NRC) issued Generic Letter (GL) 2007-01 "Inaccessible or Underground Power Cable Failures That Disable Accident Mitigation Systems or Cause Plant Transients" (Agencywide Documents Access and Management System (ADAMS) Accession No. ML070360665). GL 2007-01 requested that licensees provide the following information within 90 days of the date of the GL:

- (1) A history of inaccessible or underground power cable failures for all cables that are within the scope of 10 CFR 50.65 (the Maintenance Rule) and for all voltage levels including the cable type, cable manufacturer, date of failure, type of service, voltage class, years of service, and the root causes for the failure; and,
- (2) A description of all inspection, testing, and monitoring programs to detect the degradation of inaccessible or underground power cables that support emergency diesel generators (EDGs), offsite power, emergency service water (ESW), service water, component cooling water and other systems that are within the scope of 10 CFR 50.65 (the Maintenance Rule).

In your letter dated May 7, 2007 (ADAMS Accession No. ML071350410), you provided the information requested in GL 2007-01 including: (1) a history of inaccessible or underground power cable failures for all cables that are within the scope of 10 CFR 50.65 (the Maintenance Rule) and for all voltage levels including the cable type, cable manufacturer, date of failure, type of service, voltage class, years of service, and the root causes for the failure; and, (2) a description of all inspection, testing, and monitoring programs to detect the degradation of inaccessible or underground power cables that support EDGs, offsite power, ESW, service water, component cooling water and other systems that are within the scope of 10 CFR 50.65.

- 2 -

The NRC staff has reviewed the submitted information and has concluded that for Indian Point Nuclear Generating Unit Nos. 2 and 3 your response to GL 2007-01 is adequate. Based on this review, your response to GL 2007-01 is considered closed and no further action is requested of you at this time.

If you have any questions regarding this letter, please feel free to contact me at (301) 415-2901.

Sincerely,

/RA/

John P. Boska, Senior Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. 50-247 and 50-286

cc: Distribution via ListServ

The NRC staff has reviewed the submitted information and has concluded that for Indian Point Nuclear Generating Unit Nos. 2 and 3 your response to GL 2007-01 is adequate. Based on this review, your response to GL 2007-01 is considered closed and no further action is requested of you at this time.

If you have any questions regarding this letter, please feel free to contact me at (301) 415-2901.

Sincerely,

/RA/

John P. Boska, Senior Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket Nos. 50-247 and 50-286

cc: Distribution via ListServ

DISTRIBUTION:

PUBLIC	RidsOgcRp
LPLI-1 R/F	RidsAcrcAcnw&mMailCenter
RidsNrrDorlLpl I-1	RidsRgn1MailCenter
RidsNrrLASLittle	RidsNrrDeEeeb (GWilson)
RidsNrrPMJBoska	RidsNrrDorlDpr

ADAMS Accession Number: ML082950391

OFFICE	LPLI-1:GE	LPLI-1:PM	LPLI-1:LA	EEEB:BC	LPLI-1:BC
NAME	JGall	JBoska	SLittle	GWilson	MKowal
DATE	10/24/08	10/21/08	10/28/08	10/30/08	10/30/08

OFFICIAL RECORD COPY