

Central New Jersey Cardiology, P.A.
1511 Park Avenue, Suite #2
South Plainfield, New Jersey 07080

October 30, 2008

Br.2

Licensing Assistance Section
Nuclear Medicine Safety Branch
Division of Radiation Safety and Safeguards
U.S. Nuclear Regulatory Commission, Region I
475 Allendale Road
King of Prussia, PA 19406-1415

RECEIVED
REGION 1
2008 NOV 10 PM 12:27

RE: License Number: 29-28186-01
Central New Jersey Cardiology, PA
Notification Letter
Updated Nuclear Cardiology Diagram

03030506


Dear License Reviewer:

Please find attached to this cover letter, an updated diagram of our nuclear cardiology department. Since our last submission, two locked sealed source storage cabinets have been added to the nuclear cardiology department.

Please place this document within our licensing file for future review.

If you require additional information, please contact Michael W. Lairmore or myself. Mr. Lairmore may be reached at (201) 693-2277.

Sincerely,




Robert Lauer, M.D.
Radiation Safety Officer
Administrative Representative

Attachment A

**Central New Jersey Cardiology, PA
1511 Park Avenue, Suite 2
South Plainfield, New Jersey 07080**

**Updated Diagram
Nuclear Cardiology Department**



Legend:

- A. Locked Cobalt-57 Storage Cabinet (1/4" lead lining)
- B. Crash Cart
- C. Locked Sealed Source Storage Cabinet - Instrument Calibration Sources (1/4" lead shielding)
- D. Sink
- E. L-Shield & Preparation Area (1/4" lead shielding)
- F. Dose Calibrator
- G. Package Receipt/Return Area - Under Counter
- H. Waste Storage Area (1/8" lead shielding)
- I. NMIS Computer Station
- J. Patient Injection Area
- K. Waiting Area
- L. Ludlum SCA & Scintillation Probe Area
- ** Locked Door and/or Cabinet

This is to acknowledge the receipt of your letter/application dated

10/30/08, and to inform you that the initial processing which includes an administrative review has been performed.

☒ **Notification (29-28186-01)** There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

☐ Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 142992.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.