1.0 Introduction and General Description of the Plant

Figure 1.1-1—{50 mi (80 km) Surrounding Area}	1-22
Figure 1.1-2—{10 mi (16 km) Surrounding Area}	1-23
Figure 1.1-3— {Site Area Map}	1-24
Figure 1.2-1—{Callaway Plant Unit 2 Nuclear and Turbine Building Island Layout}	1-28

2.0 Site Characteristics

Figure 2.1-1—{Site Area Map}2-36
Figure 2.1-2—{50 Mile (80 km) Surrounding Area}
Figure 2.1-3—{10 Mile (16 km) Surrounding Area}
Figure 2.1-4—{Site Boundaries}2-39
Figure 2.1-5— {Exclusion Area Boundaries} 2-40
Figure 2.1-6—{Enlarged Site Area Map} 2-41
Figure 2.1-7—{Callaway Plant Unit 2 Enlargement}
Figure 2.1-8—Exclusion Area and Plant Site Area} 2-43
Figure 2.1-9— {10 Mile (16 km) Radius Map}2-44
Figure 2.1-10—{10 Mile (16 km) 2000 Population Distribution}
Figure 2.1-11—{10 Mile (16 km) 2010 Population Distribution}
Figure 2.1-12—{10 Mile (16 km) 2020 Population Distribution}
Figure 2.1-13— {10 Mile (16 km) 2030 Population Distribution}2-48
Figure 2.1-14— {10 Mile (16 km) 2040 Population Distribution} 2-49
Figure 2.1-15— {10 Mile (16 km) 2050 Population Distribution}2-50
Figure 2.1-16—{10 Mile (16 km) 2050 Population Distribution}
Figure 2.1-17—{50 Mile (80 km) 2000 Vicinity}2-52
Figure 2.1-18— {50 Mile (80 km) 2000 Population Distribution} 2-53
Figure 2.1-19— {50 Mile (80 km) 2010 Population Distribution}2-54
Figure 2.1-20—{50 Mile (80 km) 2020 Population Distribution}
Figure 2.1-21— {50 Mile (80 km) 2030 Population Distribution}
Figure 2.1-22—{50 Mile (80 km) 2040 Population Distribution}
Figure 2.1-23— {50 Mile (80 km) 2000 Population Distribution} 2-58
Figure 2.1-24—{50 Mile (80 km) 2060 Population Distribution}
Figure 2.1-25—{Protected Area, Exclusion Area, Restricted Area, and Low Population Zone}2-60
Figure 2.1-26— {LPZ and Emergency Planning Evacuation Routes}
Figure 2.1-27— {10 Mile (16 km) 2057 Population Distribution} 2-62
Figure 2.1-28— {10 Mile (16 km) 2017 Population Distribution}2-63
Figure 2.1-29— {50 Mile (80 km) 2057 Population Distribution} 2-64
Figure 2.1-30—{50 Mile (80 km) 2017 Population Distribution}
Figure 2.1-31— {Cumulative Populations}2-66
Figure 2.2-1—{Location Map, Facilities, Land, and Water Transportation Routes}2-110
Figure 2.2-2—{Low Altitude Air Routes and Airports}

Figure 2.2-3—{IFR Enroute High Altitude Air Routes}
Figure 2.2-4—{Location of Nearest Pipeline}2-113
Figure 2.3-1—Annual Average Number of Tornadoes 1950-19952-443
Figure 2.3-2—Average Number of Strong Violent (F2-F5) Tornadoes, 1950-19952-444
Figure 2.3-3—Date of Maximum Tornado Threat2-445
Figure 2.3-4—Five-Year Lighting Flash Density Map2-446
Figure 2.3-5—{Callaway Plant Wind Rose - 2004-2006, 10 m}2-447
Figure 2.3-6—{Callaway Plant Wind Rose - 2004-2006, 60 m}2-448
Figure 2.3-7—{Callaway Plant Wind Rose - 2004, 10 m}2-449
Figure 2.3-8—{Callaway Plant Wind Rose - 2004, 60 m}2-450
Figure 2.3-9—{Callaway Plant Wind Rose - 2005, 10 m}2-451
Figure 2.3-10—{Callaway Plant Wind Rose - 2005, 60 m}2-452
Figure 2.3-11—{Callaway Plant Wind Rose - 2006, 10 m}2-453
Figure 2.3-12—{Callaway Plant Wind Rose - 2006, 60 m}2-454
Figure 2.3-13—{Callaway Plant Wind Rose - January - 2004-2006, 10 m}2-455
Figure 2.3-14—{Callaway Plant Wind Rose - February - 2004-2006, 10 m}2-456
Figure 2.3-15—{Callaway Plant Wind Rose - March - 2004-2006, 10 m}2-457
Figure 2.3-16—{Callaway Plant Wind Rose - April - 2004-2006, 10 m}2-458
Figure 2.3-17—{Callaway Plant Wind Rose - May - 2004-2006, 10 m}2-459
Figure 2.3-18—{Callaway Plant Wind Rose - June - 2004-2006, 10 m}2-460
Figure 2.3-19—{Callaway Plant Wind Rose - July - 2004-2006, 10 m}2-461
Figure 2.3-20—{Callaway Plant Wind Rose - August - 2004-2006, 10 m}2-462
Figure 2.3-21—{Callaway Plant Wind Rose - September - 2004-2006, 10 m}2-463
Figure 2.3-22—{Callaway Plant Wind Rose - October - 2004-2006, 10 m}2-464
Figure 2.3-23—{Callaway Plant Wind Rose - November - 2004-2006, 10 m}2-465
Figure 2.3-24—{Callaway Plant Wind Rose - December - 2004-2006, 10 m}2-466
Figure 2.3-25—{Callaway Plant Wind Rose - January - 2004-2006, 60 m}2-467
Figure 2.3-26—{Callaway Plant Wind Rose - February - 2004-2006, 60 m}2-468
Figure 2.3-27—{Callaway Plant Wind Rose - March - 2004-2006, 60 m}2-469
Figure 2.3-28—{Callaway Plant Wind Rose - April - 2004-2006, 60 m}2-470
Figure 2.3-29—{Callaway Plant Wind Rose - May - 2004-2006, 60 m}2-471
Figure 2.3-30—{Callaway Plant Wind Rose - June - 2004-2006, 60 m}2-472
Figure 2.3-31—{Callaway Plant Wind Rose - July - 2004-2006, 60 m}2-473
Figure 2.3-32—{Callaway Plant Wind Rose - August - 2004-2006, 60 m}2-474
Figure 2.3-33—{Callaway Plant Wind Rose - September - 2004-2006, 60 m}2-475
Figure 2.3-34—{Callaway Plant Wind Rose - October - 2004-2006, 60 m}2-476
Figure 2.3-35—{Callaway Plant Wind Rose - November - 2004-2006, 60 m}
Figure 2.3-36—{Callaway Plant Wind Rose - December - 2004-2006, 60 m}
Figure 2.3-37—{Columbia, MO Wind Rose - 2004-2006}2-479
Figure 2.3-38—{St. Louis, MO Wind Rose - 2004-2006}2-480
Figure 2.3-39—{Kansas City, MO Wind Rose - 2004-2006}2-481

Figure 2.3-40–	–{Jefferson City, MO Wind Rose - 2004-2006}2-482
Figure 2.3-41-	-{Vichy Rolla, MO Wind Rose - 2004-2006}
Figure 2.3-42-	–{Callaway Plant Precipitation Wind Rose - 2004, 10 m}
Figure 2.3-43-	–{Callaway Plant Precipitation Wind Rose - 2004, 60 m}
Figure 2.3-44–	–{Callaway Plant Precipitation Wind Rose - 2005, 10 m}
Figure 2.3-45–	-{Callaway Plant Precipitation Wind Rose - 2005, 60 m}
Figure 2.3-46-	–{Callaway Plant Precipitation Wind Rose - 2006, 10 m}
Figure 2.3-47–	–{Callaway Plant Precipitation Wind Rose - 2006, 60 m}
Figure 2.3-48–	-{Callaway Plant Precipitation Wind Rose - 2004-2006, 10 m, All Precipitation Hours} 2-490
Figure 2.3-49–	-{Callaway Plant Precipitation Wind Rose - 2004-2006, 60 m, All Precipitation Hours} 2-491
Figure 2.3-50–	–{Callaway Plant Precipitation Wind Rose - January 2004-2006, 10 m, All Precipitation Hours}
Figure 2.3-51–	–{Callaway Plant Precipitation Wind Rose - February 2004-2006, 10 m, All Precipitation Hours}
Figure 2.3-52–	-{Callaway Plant Precipitation Wind Rose - March 2004-2006, 10 m, All Precipitation Hours}
Figure 2.3-53–	-{Callaway Plant Precipitation Wind Rose - April 2004-2006, 10 m, All Precipitation Hours} 2-495
Figure 2.3-54–	-{Callaway Plant Precipitation Wind Rose - May 2004-2006, 10 m, All Precipitation Hours} 2-496
Figure 2.3-55–	-{Callaway Plant Precipitation Wind Rose - June 2004-2006, 10 m, All Precipitation Hours} 2-497
Figure 2.3-56–	-{Callaway Plant Precipitation Wind Rose - July 2004-2006, 10 m, All Precipitation Hours} 2-498
Figure 2.3-57–	–{Callaway Plant Precipitation Wind Rose - August 2004-2006, 10 m, All Precipitation Hours}
Figure 2.3-58–	-{Callaway Plant Precipitation Wind Rose - September 2004-2006, 10 m, All Precipitation Hours}
Figure 2.3-59–	–{Callaway Plant Precipitation Wind Rose - October 2004-2006, 10 m, All Precipitation Hours}
Figure 2.3-60–	–{Callaway Plant Precipitation Wind Rose - November 2004-2006, 10 m, All Precipitation Hours}
Figure 2.3-61–	–{Callaway Plant Precipitation Wind Rose - December 2004-2006, 10 m, All Precipitation Hours}
Figure 2.3-62–	–{Callaway Plant Precipitation Wind Rose - January 2004-2006, 60 m, All Precipitation Hours}
Figure 2.3-63–	–{Callaway Plant Precipitation Wind Rose - February 2004-2006, 60 m, All Precipitation Hours}
Figure 2.3-64–	–{Callaway Plant Precipitation Wind Rose - March 2004-2006, 60 m, All Precipitation Hours}
Figure 2.3-65–	-{Callaway Plant Precipitation Wind Rose - April 2004-2006, 60 m, All Precipitation Hours} 2-507

Figure 2.3-66—{Callaway Plant Precipitation Wind Rose - May 2004-2006, 60 m, All Precipitation Hours} 2-508
Figure 2.3-67—{Callaway Plant Precipitation Wind Rose - June 2004-2006, 60 m, All Precipitation Hours} 2-509
Figure 2.3-68—{Callaway Plant Precipitation Wind Rose - July 2004-2006, 60 m, All Precipitation Hours} 2-510
Figure 2.3-69—{Callaway Plant Precipitation Wind Rose - August 2004-2006, 60 m, All Precipitation Hours}
Figure 2.3-70—{Callaway Plant Precipitation Wind Rose - September 2004-2006, 60 m, All Precipitation Hours}2-512
Figure 2.3-71—{Callaway Plant Precipitation Wind Rose - October 2004-2006, 60 m, All Precipitation Hours}2-513
Figure 2.3-72—{Callaway Plant Precipitation Wind Rose - November 2004-2006, 60 m, All Precipitation Hours}2-514
Figure 2.3-73—{Callaway Plant Precipitation Wind Rose - December 2004-2006, 60 m, All Precipitation Hours}2-515
Figure 2.3-74—Monthly Average Mixing Height Values (Springfield, MO)2-516
Figure 2.3-75—{Topography Within 1 Mile of the Callaway Plant Site}2-517
Figure 2.3-76—{Topography Within 5 Miles of the Callaway Plant Site}2-518
Figure 2.3-77—{Topography Within 50 Miles of the Callaway Plant Site}2-519
Figure 2.3-78—{Maximum Elevation Versus Distance Within 50 Miles of the Callaway Plant Site}2-520
Figure 2.3-79—{Callaway Site Map with Meteorological Tower Location}2-521
Figure 2.3-80—{Detailed Topography within 8 km (5 mi)}2-522
Figure 2.3-81—{Callaway Site Plan and Control Room Location}
Figure 2.4-1—{Plant Site Topography}
Figure 2.4-2— {Site Utilization Plant Layout}2-755
Figure 2.4-3— {Missouri River Basin and Auxvasse Creek Watershed}2-756
Figure 2.4-4— {Mean, Maximum and Minimum Streamflows for the Hermann, MO USGS 06934500, 1957 through 2006}
Figure 2.4-5—{Mean, Maximum and Minimum Streamflows for the Boonville, MO USGS 06909000, 1957through 2007}
Figure 2.4-6—{Tributaries and Streams within the Auxvasse Creek Watershed}2-759
Figure 2.4-7—{USGS Gauges Near Callaway Plant Unit 2 Site}2-760
Figure 2.4-8—{Missouri River Main Stem and Osage River Dam System}2-761
Figure 2.4-9—{Callaway County Surface Water Use}
Figure 2.4-10—{Surface Water Intakes 50 Mile (80 Km) Radius}2-763
Figure 2.4-11—{Dams Within Auxvasse Creek Watershed}2-764
Figure 2.4-12—{Peak Streamflow at Boonville and Hermann}2-765
Figure 2.4-13—{Site Layout}2-766
Figure 2.4-14—{Site Grading Plan}2-767
Figure 2.4-15—{Sub-Basin Site Drainage Delineation}
Figure 2.4-16—{HEC-HMS Hydrologic Diagram}2-769
Figure 2.4-17—{Location of Stormwater Runoff Ponds}2-770

List of Figures

Figure 2.4-18—{Auxvasse Creek Watershed Sub-Basins Delineation}	-771
Figure 2.4-19—{HEC-HMS Model Set Up}2-	-772
Figure 2.4-20—{Sub-Basin 80004 Logan Ck2 Hydrograph}2-	-773
Figure 2.4-21—{Sub-Basin 80004 Auxvasse Ck1 Hydrograph}2-	-774
Figure 2.4-22—{Sub-Basin 80004 Auxvasse Ck3 Hydrograph}2-	-775
Figure 2.4-23—{Sub-Basin 80004 Auxvasse Ck2 Hydrograph}2-	-776
Figure 2.4-24—{Sub-Basin 80003 Auxvasse Ck5 Hydrograph}2-	-777
Figure 2.4-25—{Sub-Basin 80003 Auxvasse Ck4 Hydrograph}2-	-778
Figure 2.4-26—{Storage Inflow & Outflow Thunderbird Lake Lower}2-	-779
Figure 2.4-27—{HEC-RAS Cross Section Cut Lines}2-	-780
Figure 2.4-28—{Specific HEC-RAS Cross Section Cut Lines }2-	-781
Figure 2.4-29—{Auxvasse Creek Surface Water Profile} 2-	-782
Figure 2.4-30—{Streams and Lake Near Site}2-	-783
Figure 2.4-31—{Dams Within a 5 Mile (8 km) Radius}2-	-784
Figure 2.4-32—{Missouri River Mainstem and Osage River Dam}2-	-785
Figure 2.4-33—{Dams Within Auxvasse Creek Watershed}2-	-786
Figure 2.4-34—{Schematic Layout of Callaway Plant Unit 2 Site}	-787
Figure 2.4-35—{Digital Tectonic Activity Map of the Earth}2-	-788
Figure 2.4-36—{Site Location}2-	-789
Figure 2.4-37—{Low Flow Stage-Discharge Curve for Boonville Station}2-	-790
Figure 2.4-38—{Low Flow Stage-Discharge Curve for Hermann Station}2-	-791
Figure 2.4-39—{Low Water Level Data of Boonville Station and Curve Fitting}2-	-792
Figure 2.4-40—{Low Water Level Data of Hermann Station and Curve Fitting}2-	-793
Figure 2.4-41—{Regional Physiographic Provinces}2-	-794
Figure 2.4-42—{Regional Extent of Glaciation and Alluvium}2-	-795
Figure 2.4-43—{Regional Vertical Sequence of Aquifers}2-	-796
Figure 2.4-44—{Aquifer Systems of Missouri}2-	-797
Figure 2.4-45—{Aquifer Systems of Northern, Western, and Southern Missouri}2-	-798
Figure 2.4-46—{MDNR Central Missouri Area and Groundwater Transition Zone}2-	-799
Figure 2.4-47—{Missouri River and Alluvial Aquifer Section}2-	-800
Figure 2.4-48—{Hydrogeological Units}2-	-801
Figure 2.4-49—{Hydrogeologic Study Area with Site Investigation Locations}2-	-802
Figure 2.4-50—{Hydrogeologic Site Investigation Locations - Inset}2-	-803
Figure 2.4-51—{Hydrogeologic Study Area Public and Private Wells}2-	-804
Figure 2.4-52—{Missouri Drought Susceptibility}2-	-805
Figure 2.4-53—{Groundwater Monitoring Hydrographs, Audrain and Boone Counties}2-	-806
Figure 2.4-54—{Groundwater Monitoring Hydrographs, Callaway and Gasconade Counties}2-	-807
Figure 2.4-55—{Groundwater Monitoring Hydrographs, Montgomery and Osage Counties}2-	-808
Figure 2.4-56—{Groundwater Elevation versus Time, Graydon Chert Aquifer Wells}2-	-809
Figure 2.4-57—{Precipitation versus Time, Columbia Regional Airport Station}2-	-810
Figure 2.4-58—{Surface Water Elevation versus Time, Plateau Ponds}2-	-811

Figure 2.4-59–	-{Groundwater Elevation and Precipitation versus Time}	2
Figure 2.4-60-	-{Potentiometric Surface Map, Graydon Chert Aquifer, May 2007}2-81	3
Figure 2.4-61-	-{Potentiometric Surface Map, Graydon Chert Aquifer, August 2007}2-81	4
Figure 2.4-62-	-{Potentiometric Surface Map, Graydon Chert Aquifer, November 2007}2-81	5
Figure 2.4-63-	-{Potentiometric Surface Map, Graydon Chert Aquifer, January 2008}2-81	6
Figure 2.4-64-	-{Groundwater Elevation versus Time, Aquitard}	7
Figure 2.4-65–	-{Groundwater Elevation versus Time, Cotter-Jefferson City	
	Aquifer Well}2-81	8
Figure 2.4-66–	-{Surface Water Elevation versus Time, Lakes and Auxvasse Creek}	9
Figure 2.4-67–	-{Surface Water Elevation versus Time, Mud and Logan Creeks}	20
Figure 2.4-68–	-{Potentiometric Surface Map, Cotter-Jefferson City Aquifer,	
F : 0 4 40	May 2007}	21
Figure 2.4-69–	-{Potentiometric Surface Map, Cotter-Jefferson City Aquifer,) 7
Figure 2.4.70	(Detentiometric Surface Man Cetter Jefferson City Aquifer	<u>.</u>
Figure 2.4-70-	November 2007}	23
Figure 2.4-71-	-{Potentiometric Surface Map. Cotter-Jefferson City Aquifer.	
rigure 211 / 1	January 2008}	24
Figure 2.4-72–	-{Groundwater Elevation versus Time, Missouri River Alluvial	
-	Aquifer Wells}	25
Figure 2.4-73-	-{Potentiometric Surface Map, Missouri River Alluvial Aquifer, August 2007}2-82	26
Figure 2.4-74–	-{Potentiometric Surface Map, Missouri River Alluvial Aquifer, November 2007} 2-827	•
Figure 2.4-75–	-{Potentiometric Surface Map, Missouri River Alluvial Aquifer, January 2008}2-82	28
Figure 2.4-76–	-{Layer 1 Boundary Conditions}2-82	29
Figure 2.4-77–	-{Layer 2 Boundary Conditions}2-83	30
Figure 2.4-78–	-{Layer 3 Boundary Conditions}2-83	31
Figure 2.4-79–	-{Layer 4 Boundary Conditions}	32
Figure 2.4-80-	-{South-North Cross-Section}	33
Figure 2.4-81–	-{East-West Cross-Section}	34
Figure 2.4-82-	-{Layer 1 Calibrated Groundwater Elevations}2-83	35
Figure 2.4-83-	-{Layer 2 Calibrated Groundwater Elevations}2-83	36
Figure 2.4-84—	-{Layer 3 Calibrated Groundwater Elevations}	37
Figure 2.4-85–	-{Layer 4 Calibrated Groundwater Elevations}	38
Figure 2.4-86-	-{Calibration Graph}2-83	39
Figure 2.4-87–	-{Alluvial Aquifer Pre-Pumping Groundwater Elevations}	10
Figure 2.4-88–	-{CJC Aquifer Pre-Pumping Groundwater Elevations}	11
Figure 2.4-89–	-{Alluvial Aquifer Drawdown}2-84	12
Figure 2.4-90-	-{CJC Aquifer Drawdown}2-84	13
Figure 2.4-91–	-{Alluvial Aquifer Groundwater Elevations and Zone Budget Analysis}	14
Figure 2.4-92-	-{Conceptual Groundwater Flow and Transport Pathways}	1 5
Figure 2.5.1-1-	–{Site Area Topographic Map}2-97	′ 5

Figure 2.5.1-2—{Site Topographic Map}2-976
Figure 2.5.1-3—{Map of Physiographic Provinces}
Figure 2.5.1-4—{Limits of Glaciation}2-978
Figure 2.5.1-5—{Central Stable Region}2-979
Figure 2.5.1-6—Missouri Surficial Deposits}2-980
Figure 2.5.1-7—{Regional Domes and Basins}2-981
Figure 2.5.1-8—{Precambrian Geologic Provinces}
Figure 2.5.1-9—{General Stratographic Column of the Region}2-983
Figure 2.5.1-10—{Quaternary Class "A" features in the CEUS}2-984
Figure 2.5.1-11—{Structural Features and Seismicity of the Central US}2-985
Figure 2.5.1-12—{Regional Gravity Anomaly Map}
Figure 2.5.1-13—{Regional Magnetic Anomaly Map}2-987
Figure 2.5.1-14—{Regional Gravity Anomaly Map with Earthquake Overlays}2-988
Figure 2.5.1-15—{Cryptoexplosive Structures}
Figure 2.5.1-16—{Tectonic Interpretation by Weston Geophysical Corporation}2-990
Figure 2.5.1-17—{Seismic Source Zones Interpretation by Weston Geophysical Corporation}2-991
Figure 2.5.1-18—{Tectonic Interpretation by Dames & Moore}2-992
Figure 2.5.1-19—{Seismic Source Zones Interpretation by Dames & Moore}2-993
Figure 2.5.1-20—{Tectonic Interpretation by Law Engineering Testing Company}2-994
Figure 2.5.1-21—{Seismic Source Zones Interpretation by Law Engineering Testing Company}2-995
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants}
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996 Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996 Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.} Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996 Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.} Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.} Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996 Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.} Pigure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.} Pigure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.} Pigure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.} Pigure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996 Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.} Seismic Source Zones Interpretation by Bechtel Group, Inc.} Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.} Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.} Pigure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.} 2-909 Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.} 2-1000 Figure 2.5.1-27—{Springs and Sinkholes of Missouri}
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996 Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.} Pigure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.} Pigure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.} Pigure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.} Pigure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.} Pigure 2.5.1-27—{Springs and Sinkholes of Missouri} Pigure 2.5.1-28—{Cave Density of Missouri}
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}.2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}.2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-27—{Springs and Sinkholes of Missouri}.2-1001Figure 2.5.1-28—{Cave Density of Missouri}.2-1002Figure 2.5.1-29—{Site Area Geologic Map}.2-1003
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}.2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}.2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-27—{Springs and Sinkholes of Missouri}.2-1001Figure 2.5.1-28—{Cave Density of Missouri}.2-1002Figure 2.5.1-29—{Site Area Geologic Map}.2-1003Figure 2.5.1-30—{Site Area Soils Map}.2-1004
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}.2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}.2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-27—{Springs and Sinkholes of Missouri}.2-1001Figure 2.5.1-28—{Cave Density of Missouri}.2-1002Figure 2.5.1-29—{Site Area Geologic Map}.2-1003Figure 2.5.1-30—{Site Area Soils Map}.2-1004Figure 2.5.1-31—{Site Area Soils Map Legend}.2-1005
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}.2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}.2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-900Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-27—{Springs and Sinkholes of Missouri}.2-1001Figure 2.5.1-28—{Cave Density of Missouri}.2-1002Figure 2.5.1-29—{Site Area Geologic Map}.2-1003Figure 2.5.1-30—{Site Area Soils Map}.2-1004Figure 2.5.1-31—{Site Area Soils Map Legend}.2-1005Figure 2.5.1-32—{Site Soils Map}.2-1006
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}.2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}.2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-27—{Springs and Sinkholes of Missouri}2-1001Figure 2.5.1-28—{Cave Density of Missouri}2-1002Figure 2.5.1-29—{Site Area Geologic Map}2-1003Figure 2.5.1-30—{Site Area Soils Map}2-1004Figure 2.5.1-32—{Site Soils Map}2-1005Figure 2.5.1-33—{Depth to Graydon Chert Conglomerate}2-1007
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}.2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}.2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-28—{Cave Density of Missouri}.2-1002Figure 2.5.1-29—{Site Area Geologic Map}.2-1003Figure 2.5.1-30—{Site Area Soils Map}.2-1004Figure 2.5.1-31—{Site Area Soils Map Legend}.2-1005Figure 2.5.1-32—{Site Soils Map}.2-1007Figure 2.5.1-33—{Depth to Graydon Chert Conglomerate}.2-1007Figure 2.5.1-34—{Graydon Chert Conglomerate (Elevation of Top Surface)}.2-1008
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}.2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}.2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-27—{Springs and Sinkholes of Missouri}.2-1001Figure 2.5.1-28—{Cave Density of Missouri}.2-1002Figure 2.5.1-29—{Site Area Geologic Map}.2-1003Figure 2.5.1-30—{Site Area Soils Map}.2-1004Figure 2.5.1-31—{Site Area Soils Map}.2-1005Figure 2.5.1-33—{Depth to Graydon Chert Conglomerate}.2-1007Figure 2.5.1-34—{Graydon Chert Conglomerate (Thickness)}2-1009
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}.2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}.2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-27—{Springs and Sinkholes of Missouri}.2-1001Figure 2.5.1-28—{Cave Density of Missouri}.2-1002Figure 2.5.1-29—{Site Area Geologic Map}.2-1003Figure 2.5.1-30—{Site Area Soils Map}.2-1004Figure 2.5.1-31—{Site Area Soils Map Legend}.2-1005Figure 2.5.1-33—{Depth to Graydon Chert Conglomerate}.2-1007Figure 2.5.1-34—{Graydon Chert Conglomerate (Elevation of Top Surface)}.2-1009Figure 2.5.1-36—{Depth to Bottom of Graydon Chert}.2-1000
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}2-1000Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}2-1000Figure 2.5.1-27—{Springs and Sinkholes of Missouri}2-1001Figure 2.5.1-28—{Cave Density of Missouri}2-1002Figure 2.5.1-29—{Site Area Geologic Map}2-1003Figure 2.5.1-30—{Site Area Soils Map}2-1003Figure 2.5.1-31—{Site Area Soils Map}2-1005Figure 2.5.1-33—{Depth to Graydon Chert Conglomerate}2-1007Figure 2.5.1-33—{Graydon Chert Conglomerate (Elevation of Top Surface)}2-1009Figure 2.5.1-36—{Depth to Bottom of Graydon Chert}2-1000Figure 2.5.1-37—{Burlington Formation (Thickness)}2-1011
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}.2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}.2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-27—{Springs and Sinkholes of Missouri}.2-1001Figure 2.5.1-28—{Cave Density of Missouri}.2-1002Figure 2.5.1-29—{Site Area Geologic Map}.2-1003Figure 2.5.1-30—{Site Area Soils Map}.2-1004Figure 2.5.1-31—{Site Area Soils Map}.2-1006Figure 2.5.1-33—{Depth to Graydon Chert Conglomerate}.2-1007Figure 2.5.1-34—{Graydon Chert Conglomerate (Elevation of Top Surface)}.2-1009Figure 2.5.1-35—{Graydon Chert Conglomerate (Thickness)}.2-1001Figure 2.5.1-33—{Depth to Bottom of Graydon Chert}.2-1001Figure 2.5.1-33—{Burlington Formation (Thickness)}.2-1011Figure 2.5.1-33—{Burlington Formation (Thickness)}.2-1012
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}.2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}.2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-27—{Springs and Sinkholes of Missouri}.2-1000Figure 2.5.1-28—{Cave Density of Missouri}.2-1002Figure 2.5.1-29—{Site Area Geologic Map}.2-1003Figure 2.5.1-30—{Site Area Soils Map}.2-1003Figure 2.5.1-31—{Site Area Soils Map}.2-1004Figure 2.5.1-32—{Site Soils Map}.2-1005Figure 2.5.1-33—{Depth to Graydon Chert Conglomerate}.2-1007Figure 2.5.1-34—{Graydon Chert Conglomerate (Elevation of Top Surface)}.2-1009Figure 2.5.1-35—{Graydon Chert Conglomerate (Thickness)}.2-1001Figure 2.5.1-33—{Burlington Formation (Thickness)}.2-1011Figure 2.5.1-33—{Burlington Formation (Thickness)}.2-1012Figure 2.5.1-39—{Bushberg Formation (Depth to Top Surface)}.2-1013
Figure 2.5.1-22—{Tectonic and Seismic Source Zones Interpretation by Woodward-Clyde Consultants} 2-996Figure 2.5.1-23—{Tectonic Interpretation by Bechtel Group, Inc.}.2-997Figure 2.5.1-24—{Seismic Source Zones Interpretation by Bechtel Group, Inc.}.2-998Figure 2.5.1-25—{Tectonic Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-999Figure 2.5.1-26—{Seismic Source Zones Interpretation by Rondout Associates, Inc.}.2-1000Figure 2.5.1-27—{Springs and Sinkholes of Missouri}.2-1001Figure 2.5.1-28—{Cave Density of Missouri}.2-1002Figure 2.5.1-29—{Site Area Geologic Map}.2-1003Figure 2.5.1-30—{Site Area Soils Map}.2-1004Figure 2.5.1-31—{Site Area Soils Map Legend}.2-1005Figure 2.5.1-32—{Site Soils Map}.2-1006Figure 2.5.1-33—{Depth to Graydon Chert Conglomerate}.2-1007Figure 2.5.1-34—{Graydon Chert Conglomerate (Elevation of Top Surface)}.2-1009Figure 2.5.1-36—{Burlington Formation (Thickness)}.2-1010Figure 2.5.1-37—{Burlington Formation (Thickness)}.2-1012Figure 2.5.1-39—{Bushberg Formation (Depth to Top Surface)}.2-1013Figure 2.5.1-39—{Bushberg Formation (Depth to Top Surface)}.2-1014

Figure 2.5.1-42—{Mineral Resources in Missouri}	2-1020
Figure 2.5.1-43—{Mineral Industries in Missouri}	2-1021
Figure 2.5.2-1—{Earthquake Catalog and Bechtel Group EPRI Source Zones}	2-1152
Figure 2.5.2-2—{Earthquake Catalog and Dames & Moore Group EPRI Source Zones}	2-1154
Figure 2.5.2-3—{Earthquake Catalog and Law Engineering Group EPRI Source Zones}	2-1156
Figure 2.5.2-4—{Earthquake Catalog and Rondout Group EPRI Source Zones}	2-1158
Figure 2.5.2-5—{Earthquake Catalog and Weston Group EPRI Source Zones}	2-1160
Figure 2.5.2-6—{Earthquake Catalog and Woodward-Clyde EPRI Source Zones}	2-1162
Figure 2.5.2-7—{Seismic Activity at the New Madrid Fault System}	2-1164
Figure 2.5.2-8—{Logic Tree for the New Madrid Fault System}	2-1165
Figure 2.5.2-9—{Location of the Arms of the New Madrid Fault System}	2-1166
Figure 2.5.2-10—{Logic Tree for the Ground Motion Models for General Area Sources}	2-1167
Figure 2.5.2-11—{Logic Tree for the Ground Motion Models for Non-General Area Sources} 2	2-1168
Figure 2.5.2-12—{Mean and Fractile Rock Hazard Curves } 2	2-1169
Figure 2.5.2-13—{Mean and Fractile Rock Hazard Curves }	2-1170
Figure 2.5.2-14—{Uniform Hazard Response Spectra for Hard Rock}	2-1171
Figure 2.5.2-15—{Mean De-aggregation for 1E-4, 1E-5 and 1E-6}	2-1172
Figure 2.5.2-16—{Comparison of G-R Parameters, Bechtel EST Zones (USGS data through 2001 ar 2007)}	nd 2-1173
Figure 2.5.2-17—{Comparison of UHRS at Hard Rock for Callaway Plant Unit 2 Site (USGS data thr 2001 and 2007)}	ough 2-1174
Figure 2.5.2-18—{Sensitivity Analysis of Postulated Events Near St. Louis}	2-1175
Figure 2.5.2-19—{Best Estimate of Shear Wave Velocity at the Callaway Plant Unit 2 Site} 2	2-1176
Figure 2.5.2-20—{Randomization of Low Strain Shear Wave Velocity Profiles}	2-1177
Figure 2.5.2-21—{Mean +/- Standard deviation for Shear Wave Velocity}	2-1178
Figure 2.5.2-22—{Strain Dependent Properties and Randomization for Graydon Chert Conglome 2-1179	erate}.
Figure 2.5.2-23—{Smooth Uniform Response Spectra for Hard Rock}	2-1180
Figure 2.5.2-24—{Smooth Reference Spectra for Hard Rock Conditions}	2-1181
Figure 2.5.2-25—{Response Spectra for Controlling Events at the Callaway Plant Unit 2 Site} 2	2-1182
Figure 2.5.2-26—{Response Spectra of Selected Time Histories for 1E-4 Controlling Event LF, DEL DEH after Spectral Matching}	and 2-1183
Figure 2.5.2-27—{Mean Site Amplification Factors and Coefficient of variation at 37.5 ft (11.4 m) I for 1E-4, 1E-5, LF and HF. DEM Input Motion}	Depth 2-1184
Figure 2.5.2-28—{Maximum Strains Vs. Depth for 1E-4, 1E-5, LF and HF. DEM Input Motion}2	2-1185
Figure 2.5.2-29—{HF and LF Spectra and Envelopes for 1E-4 and 1E-5}	2-1186
Figure 2.5.2-30—{Recommended Horizontal and Vertical SSE Spectra}	2-1187
Figure 2.5.2-31—{Recommended V/H Ratios}	2-1188
Figure 2.5.4-1—{Generic Soil Profile}	2-1301
Figure 2.5.4-2—{Boring Layout Plan}	2-1302
Figure 2.5.4-3—{Geophysical Exploration Locations}	2-1303
Figure 2.5.4-4—{Surface Elevation Contours}. 2	2-1304

Figure 2.5.4-5—{Depth to Graydon Chert Conglomerate}	05
Figure 2.5.4-6—{Graydon Chert Conglomerate (Elevation of Top Surface)}	06
Figure 2.5.4-7—{Graydon Chert Conglomerate (Thickness)}	07
Figure 2.5.4-8—{Depth to Bottom of Graydon Chert Conglomerate}	08
Figure 2.5.4-9—{Burlington Formation (Thickness)}	09
Figure 2.5.4-10—{Bushberg Formation (Depth to Top Surface)}	10
Figure 2.5.4-11—{Bushberg Formation (Thickness)} 2-13	11
Figure 2.5.4-12—{Snyder Creek Formation (Depth to Top Surface)}	12
Figure 2.5.4-13—{SPT Variability}	13
Figure 2.5.4-14—{Pressuremeter Test Results}	14
Figure 2.5.4-15—{Pressuremeter Test Results} 2-13	15
Figure 2.5.4-16—{Geophysical Testing (Cross-Hole)} 2-13	16
Figure 2.5.4-17—{Geophysical Testing at CH-2}	17
Figure 2.5.4-18—{Geophysical Testing at R1}	18
Figure 2.5.4-19—{Geophysical Testing at R1-B}	19
Figure 2.5.4-20—{Geophysical Testing at R-25} 2-13	20
Figure 2.5.4-21—{Geophysical Testing at R-28}	21
Figure 2.5.4-22—{Reflection Survey (1 of 3)}	22
Figure 2.5.4-23—{Reflection Survey (2 of 3)}	23
Figure 2.5.4-24—{Reflection Survey (3 of 3)}	24
Figure 2.5.4-25—{Atterberg Limits and Moisture Content}	25
Figure 2.5.4-26—{Casagrande Plasticity Chart}	26
Figure 2.5.4-27—{Resonant Column Test, UTA-56-A (1E) Loess / Acretion Gley} 2-13	27
Figure 2.5.4-28—{Resonant Column Test, UTA-56-B (2C) Glacial Till}	28
Figure 2.5.4-29—{Resonant Column Test, UTA-56-C (3C) Graydon Chert Conglomerate} 2-13	29
Figure 2.5.4-30—{Resonant Column Test, UTA-56-D (4C) Graydon Chert Conglomerate (FWC)} 2-13	30
Figure 2.5.4-31—{Resonant Column Test, UTA-56-E (5C) Graydon Chert Conglomerate (CB)} 2-13	31
Figure 2.5.4-32—{Resonant Column Test, UTA-56-B (2G) Glacial Till} 2-13	32
Figure 2.5.4-33—{Seismic Wave Velocity Profiles Soil Velocity Profile} 2-13	33
Figure 2.5.4-34—{Strain Dependent Properties for the Overburden Soils}	34
Figure 2.5.4-35—{Recommended Strain Dependent Properties for the Graydon Chert Conglomerate 2-1335	}.
Figure 2.5.4-36—{Foundation Interface Profiles}	36
Figure 2.5.4-37—{Foundation Interface Cross Section 1-1'}	37
Figure 2.5.4-38—{Foundation Interface Cross Section 2-2'}	38
Figure 2.5.4-39—{Foundation Interface Cross Section 3-3'} 2-13	39
Figure 2.5.4-40—{Foundation Interface Cross Section 4-4'}	40
Figure 2.5.4-41—{Excavation Plan}	41
Figure 2.5.4-42—{Excavation Cross Sections}	42
Figure 2.5.4-43—{Liquefaction Potential} 2-13	43
Figure 2.5.4-44—{NI Settlement Analysis Service Loads}	44

Figure 2.5.4-45—{NI Settlement Analysis East West Section}
Figure 2.5.4-46—{NI Settlement Analysis North South Section}
Figure 2.5.4-47—{Examples of Earth Pressure Diagrams}
Figure 2.5.5-1—{Site Topographic Map 5 Mile (8 km) Radius}
Figure 2.5.5-2—{Site Area Topographic Map 0.6 Mile (1 km) Radius}
Figure 2.5.5-3—{Generic Soil Profile}
Figure 2.5.5-4—{Excavation Cross Sections}
Figure 2.5.5-5—{Permanent Slope Cross Sections and Failure Surfaces}
Figure 2.5.5-6—{Temporary Slope Cross Sections and Failure Surfaces}
Figure 2.5.5-7—{ESWEMS Pond Plan View}
Figure 2.5L-1—{Site Region Relief Map}
Figure 2.5L-2—{Site Vicinity Topographic Map}
Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build
Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings}
Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings}
 Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings}
 Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings}
 Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings}
 Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings}
 Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings}
Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings} 2-137: Figure 2.5L-4—{Regional Geologic Map} 2-137: Figure 2.5L-5—{Regional Faulting and Earthquake Epicenters} 2-137: Figure 2.5L-6—{Regional Folding} 2-137: Figure 2.5L-7—{Regional Loess Isopach Map} 2-137: Figure 2.5L-8—{Site Vicinity Geologic Map} 2-137: Figure 2.5L-9—{Site Area Geologic Cross Sections} 2-137: Figure 2.5L-10—{Site Geologic Cross Section} 2-137:
Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings}
Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings}
Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings}
Figure 2.5L-3—{Site Map With Existing Callaway Plant Unit 1 and Proposed Callaway Plant Unit 2 Build ings}

3.0 Design of Structures, Components, Equipment and Systems

Figure 3.7-1—{Comparison of EPR (Standard Plant) and Callaway Plant Unit 2 Ground Design Spectra Horizontal Direction, 5% Damping}3-59
Figure 3.7-2—{Comparison of EPR (Standard Plant) and Callaway Plant Unit 2 Ground Design Spectra Vertical Direction, 5% Damping}
Figure 3.7-3—{Comparison of EPR (Standard Plant) and Callaway Plant Unit 2 Ground Design Spectra Horizontal Direction, Low Frequencies, 5% Damping}3-61
Figure 3.7-4—{Comparison of EPR (Standard Plant) and Callaway Plant Unit 2 Ground Design Spectra Vertical Direction, Low Frequencies, 5% Damping}
Figure 3.7-5—{Comparison of EPGB FIRS (Callaway Plant Unit 2) and CSDRS Horizontal Direction, 5% Damping}
Figure 3.7-6—{Comparison of EPGB FIRS (Callaway Plant Unit 2) and CSDRS Vertical Direction, 5% Damping}
Figure 3.7-7—{Comparison of ESWB FIRS (Callaway Plant Unit 2) and CSDRS Horizontal Direction, 5% Damping}

Figure 3.7-8—{Comparison of ESWB FIRS (Callaway Plant Unit 2) and CSDRS Vertical Direction, 5% Damping}
Figure 3.7-9—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of NI Basemat, X(E-W) Direction, 5% Damping}
Figure 3.7-10—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of NI Basemat, Y(N-S) Direction, 5% Damping}3-68
Figure 3.7-11—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of NI Basemat, Z(Vertical) Direction, 5% Damping}3-69
Figure 3.7-12—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of EPGB 1&2 Basemat, X(E-W) Direction, 5% Damping}3-70
Figure 3.7-13—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of EPGB 1&2 Basemat, Y(N-S) Direction, 5% Damping}3-71
Figure 3.7-14—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of EPGB 1&2 Basemat, Z(Vertical) Direction, 5% Damping}3-72
Figure 3.7-15—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of EPGB 3&4 Basemat, X(E-W) Direction, 5% Damping}3-73
Figure 3.7-16—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of EPGB 3&4 Basemat, Y(N-S) Direction, 5% Damping}
Figure 3.7-17—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of EPGB 3&4 Basemat, Z(Vertical) Direction, 5% Damping}3-75
Figure 3.7-18—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 1 Basemat, X(E-W) Direction, 5% Damping}3-76
Figure 3.7-19—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 1 Basemat, Y(N-S) Direction, 5% Damping}
Figure 3.7-20—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 1 Basemat, Z(Vertical) Direction, 5% Damping}3-78
Figure 3.7-21—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 2 Basemat, X(E-W) Direction, 5% Damping}3-79
Figure 3.7-22—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 2 Basemat, Y(N-S) Direction, 5% Damping}
Figure 3.7-23—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 2 Basemat, Z(Vertical) Direction, 5% Damping}
Figure 3.7-24—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 3 Basemat, X(E-W) Direction, 5% Damping}3-82
Figure 3.7-25—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 3 Basemat, Y(N-S) Direction, 5% Damping}
Figure 3.7-26—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 3 Basemat, Z(Vertical) Direction, 5% Damping}
Figure 3.7-27—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 4 Basemat, X(E-W) Direction, 5% Damping}3-85
Figure 3.7-28—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 4 Basemat, Y(N-S) Direction, 5% Damping}
Figure 3.7-29—{Comparison of Callaway Plant Unit 2 versus US EPR Standard In-structure Response Spectra, Center of ESWB 4 Basemat, Z(Vertical) Direction, 5% Damping}
Figure 3.7-30—{Isometric View of FEM for EPGB}

Figure 3.7-31—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Reactor Building Internals, Elev. 5.15m, ±15% Peak-Broadended, X(E-W) Direction, 5% Damping}3-89
Figure 3.7-32—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Reactor Building Internals, Elev. 5.15m, ±15% Peak-Broadended, Y(N-S) Direction, 5% Damping}3-90
Figure 3.7-33—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Reactor Building Internals, Elev. 5.15m, ±15% Peak-Broadended, Z(Vertical) Direction, 5% Damping}
Figure 3.7-34—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Reactor Building Internals, Elev. 19.50m, ±15% Peak-Broadended, X(E-W) Direction, 5% Damping}
Figure 3.7-35—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Reactor Building Internals, Elev. 19.50m, ±15% Peak-Broadended, Y(N-S) Direction, 5% Damping}
Figure 3.7-36—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Reactor Building Internals, Elev. 19.50m, ±15% Peak-Broadended, Z(Vertical) Direction, 5% Damping}
Figure 3.7-37—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 1, 8.1m, ±15% Peak-Broadended, X(E-W) Direction, 5% Damping}
Figure 3.7-38—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 1, 8.1m, ±15% Peak-Broadended, Y(N-S) Direction, 5% Damping}3-96
Figure 3.7-39—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 1, 8.1m, ±15% Peak-Broadended, Z(Vertical) Direction, 5% Damping}
Figure 3.7-40—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 1, 21.0m, ±15% Peak-Broadended, X(E-W) Direction, 5% Damping}
Figure 3.7-41—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 1, 21.0m, ±15% Peak-Broadended, Y(N-S) Direction, 5% Damping}3-99
Figure 3.7-42—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 1, 21.0m, ±15% Peak-Broadended, Z(Vertical) Direction, 5% Damping}
Figure 3.7-43—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 2/3, 8.1m, ±15% Peak-Broadended, X(E-W) Direction, 5% Damping}3-101
Figure 3.7-44—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building $2/3$, $8.1m$, $\pm 15\%$ Peak-Broadended, Y(N-S) Direction, 5% Damping}
Figure 3.7-45—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 2/3, 8.1m, ±15% Peak-Broadended, Z(Vertical) Direction, 5% Damping}3-103

Figure 3.7-46—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 2/3, 15.4m, ±15% Peak-Broadended, X(E-W) Direction, 5% Damping}
Figure 3.7-47—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 2/3, 15.4m, ±15% Peak-Broadended, Y(N-S) Direction, 5% Damping}
Figure 3.7-48—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 2/3, 15.4m, ±15% Peak-Broadended, Z(Vertical) Direction, 5% Damping}
Figure 3.7-49—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 4, 21.0m, ±15% Peak-Broadended, X(E-W) Direction, 5% Damping}3-107
Figure 3.7-50—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 4, 21.0m, ±15% Peak-Broadended, Y(N-S) Direction, 5% Damping}3-108
Figure 3.7-51—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Safeguard Building 4, 21.0m, ±15% Peak-Broadended, Z(Vertical) Direction, 5% Damping}
Figure 3.7-52—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Containment Building, Elev. 37.60m, ±15% Peak-Broadended, X(E-W) Direction, 5% Damping}
Figure 3.7-53—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Containment Building, Elev. 37.60m, ±15% Peak-Broadended, Y(N-S) Direction, 5% Damping}
Figure 3.7-54—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Containment Building, Elev. 37.60m, ±15% Peak-Broadended, Z(Vertical) Direction, 5% Damping}
Figure 3.7-55—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Containment Building, Elev. 58.00m, ±15% Peak-Broadended, X(E-W) Direction, 5% Damping}
Figure 3.7-56—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Containment Building, Elev. 58.00m, ±15% Peak-Broadended, Y(N-S) Direction, 5% Damping}
Figure 3.7-57—	-{Comparison of Callaway Plant Unit 2 (bold, dark blue) versus US EPR Standard In-structure Response Spectra, Containment Building, Elev. 58.00m, ±15% Peak-Broadended, Z(Vertical) Direction, 5% Damping}
Figure 3.7-58—	-{Callaway EPGB, Elev. 0.0m, X(E-W) Direction, 5% Damping}
Figure 3.7-59—	-{Callaway EPGB, Elev. 0.0m, Y(N-S) Direction, 5% Damping}
Figure 3.7-60—	-{Callaway EPGB, Elev. 0.0m, Z(Vertical) Direction, 5% Damping}
Figure 3.7-61—	-{Callaway ESWB, Elev. 19.20m, X(E-W) Direction, 5% Damping}
Figure 3.7-62—	-{Callaway ESWB, Elev. 19.20m, Y(N-S) Direction, 5% Damping}3-120
Figure 3.7-63—	-Callaway ESWB, Elev. 19.20m, Z(Vertical) Direction, 5% Damping
Figure 3.7-64—	-Callaway ESWB, Elev. 4.27m, X(E-W) Direction, 5% Damping
Figure 3.7-65—	-Callaway ESWB, Elev. 4.27m, Y(N-S) Direction, 5% Damping
Figure 3.7-66—	-Callaway ESWB, Elev. 4.27m, Z(Vertical) Direction, 5% Damping

Figure 3.7-67—	-US EPR Callaway Plant Unit 2 In-structure Response Spectra, Reactor Building Internals, Elev. 5.15m, ±15% Peak-Broadened, Z(Vertical) Direction, 2%, 3%, 4%, 5%, 7%, and 10% Damping
Figure 3.7-68—	-Callaway Spectrum Envelope of EPGB, Elev. 0.0m, X(E-W) Direction, 2%, 3%, 4%, 5%, 7%, and 10% Damping
Figure 3.7-69—	-Callaway Spectrum Envelope of EPGB, Elev. 0.0m, Y(N-S) Direction, 2%, 3%, 4%, 5%, 7%, and 10% Damping
Figure 3.7-70—	-Callaway Spectrum Envelope of EPGB, Elev. 0.0m, Z(Vertical) Direction, 2%, 3%, 4%, 5%, 7%, and 10% Damping3-128
Figure 3.7-71—	-Callaway Spectrum Envelope of ESWB, Elev. 19.20m, X(E-W) Direction, 2%, 3%, 4%, 5%, 7%, and 10% Damping3-129
Figure 3.7-72—	-Callaway Spectrum Envelope of ESWB, Elev. 19.20m, Y(N-S) Direction, 2%, 3%, 4%, 5%, 7%, and 10% Damping3-130
Figure 3.7-73—	-Callaway Spectrum Envelope of ESWB, Elev. 19.20m, Z(Vertical) Direction, 2%, 3%, 4%, 5%, 7%, and 10% Damping3-131
Figure 3.7-74—	-Callaway Spectrum Envelope of ESWB, Elev. 4.27m, X(E-W) Direction, 2%, 3%, 4%, 5%, 7%, and 10% Damping3-132
Figure 3.7-75—	-Callaway Spectrum Envelope of ESWB, Elev. 4.27m, Y(N-S) Direction, 2%, 3%, 4%, 5%, 7%, and 10% Damping
Figure 3.7-76—	-{Comparison of Callaway Plant Unit 2 GMRS and CSDRS at 0.1g PGA (Horizontal)}.3-134
Figure 3.7-77—	-FIRS at ESWEMS Pump House Foundation Level
Figure 3.7-78—	-North-South Time Histories Matching ESWEMS Foundation Level FIRS
Figure 3.7-79—	-East-West Time Histories Matching ESWEMS Foundation Level FIRS
Figure 3.7-80—	-Vertical Time Histories Matching ESWEMS Foundation Level FIRS
Figure 3.7-81—	-Callaway Plant Unit 2 North-South FIRS at Elev. 835ft
Figure 3.7-82—	-Callaway Plant Unit 2 East-West FIRS at Elev. 835ft
Figure 3.7-83—	-Callaway Plant Unit 2 Vertical FIRS at Elev. 835ft
Figure 3.7-84—	-Callaway Plant Unit 2 Strain-Compatible Site Profile
Figure 3.7-85—	-Callaway Plant Unit 2 Vs EPR DC Soil Cases
Figure 3.7-86—	-Callaway Plant Unit 2 Vs EPR DC Soil Cases
Figure 3.7-87—	-Response Spectra at NI Common Basemat Bottom Node 417 - 5% Damping X-Direction 3-145
Figure 3.7-88—	-Response Spectra at NI Common Basemat Bottom Node 417 - 5% Damping Y-Direction 3-146
Figure 3.7-89—	-Response Spectra at NI Common Basemat Bottom Node 417 - 5% Damping Z-Direction 3-147
Figure 3.7-90—	-Soil Model Surface Response Spectra at Centers of Footprints of EPGB & ESWB - 5% Damping X-Direction
Figure 3.7-91—	-Soil Model Surface Response Spectra at Centers of Footprints of EPGB & ESWB - 5% Damping Y-Direction
Figure 3.7-92—	-Soil Model Surface Response Spectra at Centers of Footprints of EPGB & ESWB - 5% Damping Z-Direction
Figure 3.7-93—	-Horizontal Spectrum for Response Spectrum Analysis
Figure 3.7-94—	- Vertical Spectrum for Response Spectrum Analysis

Figure 3.7-95—ESWEMS Pumphouse Horizontal Response Spectrum with 5% Damping3-153
Figure 3.7-96—ESWEMS Pumphouse Vertical Response Spectrum with 5% Damping
Figure 3.7-97—Legend of Joints/Nodes in ESWEMS Pumphouse at Locations of High Demand Stresses 3-155
Figure 3.7-98—Legend of Internal Joints/Nodes at Locations of High Demand Stress
Figure 3.7-99—Finite Element Model of ESWEMS Pump House
Figure 3.7-100—Assumed Shear Wave Velocities in Structural Fill Under ESWEMS Pump House3-158
Figure 3.7-101—Strain Compatible Shear Wave Velocities in Subgrade Profile Used in SSI Analysis 3-159
Figure 3.7-102—In-structure Floor Response Spectra in E-W Direction at First Floor Level of the ESWEMS Pump House
Figure 3.7-103—In-structure Floor Response Spectra in N-S Direction at First Floor Level of the ESWEMS Pump House
Figure 3.7-104—In-structure Floor Response Spectra in Vertical Direction at First Floor Level of the ESWEMS Pump House
Figure 3.7-105—In-structure Floor Response Spectra in E-W Direction at Mezzanine Level of the ESWEMS Pump House
Figure 3.7-106—In-Structure Floor Response Spectra in N-S Direction at Mezzanine Level of the ESWEMS Pump House
Figure 3.7-107—In-structure Floor Response Spectra in Vertical Direction at Mezzanine Level of the ESWEMS Pump House
Figure 3.7-108—In-structure Floor Response Spectra in E-W Direction at Roof Level of the ESWEMS Pump House
Figure 3.7-109—In-structure Floor Response Spectra in N-S Direction at Roof Level of the ESWEMS Pump House
Figure 3.7-110—In-structure Floor Response Spectra in Vertical Direction at Roof Level of the ESWEMS Pump House
Figure 3.7-111—{Spectrum Envelope of ESWB Elev. 4.27 m, Z(Vert) Direction, 2%, 3%, 4%, 5%, 7%, and 10% Damping}
Figure 3.8-1— {Schematic Site Plan of Seismic Category I Buried Utilities at the NI (Electrical Duct Banks) 3-189
Figure 3.8-2—{Schematic Site Plan of Seismic Category I Buried Utilities at the NI (Underground Piping) 3-190
Figure 3.8-3—{Isometric View of the GTStrudl Finite Element Model for the ESWEMS Pumphouse Structure (Partial View of Basemat, Exterior Walls and Interior Divider Walls)}3-19
Figure 3.8-4—{Isometric View of the GTStrudI Finite Element Model for the ESWEMS Pumphouse Structure (Partial View of Pump Wells, Wing Walls and Apron)}
Figure 3E.4-1—{Isometric View of ESWEMS Pumphouse Main Basemat & Pump Well Base - Finite Element Mesh}
Figure 3E.4-2—{Isometric View of the ESWEMS Pumphouse GTStrudI Finite Element Model-Exterior Wall, Roof, and Apron}
Figure 3E.4-3—{GT Strudl Finite Element Planar Reference System}
Figure 3E.4-4—{Plant Arrangement - ESWEMS Pumphouse Excavation Cut and Backfill}
Figure 3E.4-5—{Plant Arrangement - ESWEMS Pond and Pumphouse Location Plan}

Figure 3E.4-6—{Plant Arrangement - ESWEMS Pond Typical Riprap Detail}	3-244
Figure 3E.4-7—{Plant Arrangement -ESWEMS Pond Spillway Plan}	3-245
Figure 3E.4-8—{Plant Arrangement -ESWEMS Pond Spillway Section}	3-246
Figure 3E.4-9—{Plant Arrangement - ESWEMS Pond Section at Embankment}	3-247
Figure 3E.4-10—{Plant Arrangement -ESWEMS Pond Section at Embankment}	3-248
Figure 3E.4-11—{Plant Arrangement -ESWEMS Pond Section at Embankment}	3-249
Figure 3E.4-12—{Plant Arrangement -ESWEMS Pumphouse Rebar}	3-250

4.0 Reactor

5.0 Reactor Coolant System and Connected Systems

6.0 Engineered Safety Features

7.0 Instrumentation and Controls

8.0 Electric Power

Figure 8.1-1—{Callaway Plant 345 kV Circuit Corridors}	8-10
Figure 8.2-1—{Callaway Plant Layout}	8-26
Figure 8.2-2—{Callaway Switchyard Single Line Diagram}	8-27
Figure 8.3-1—{Emergency Power Supply System Single Line Drawing - Sheet 1 of 3}	8-34
Figure 8.3-2—{Emergency Power Supply System Single Line Drawing - Sheet 2 of 3}	8-35
Figure 8.3-3—{Emergency Power Supply System Single Line Drawing - Sheet 3 of 3}	8-36
Figure 8.3-4—{Normal Power Supply System Single Line Drawing - Sheet 1 of 4}	8-37
Figure 8.3-5—{Normal Power Supply System Single Line Drawing - Sheet 2 of 4}	8-38
Figure 8.3-6—{Normal Power Supply System Single Line Drawing - Sheet 3 of 4}	8-39
Figure 8.3-7—{Normal Power Supply System Single Line Drawing - Sheet 4 of 4}	8-40
Figure 8.3-8—{Callaway Site Grounding}	8-41

9.0 Auxiliary Systems

Callaway Plant Unit 2

Figure 9.2-1—{Potable Water System}	
Figure 9.2-2—{Sanitary Waste Water System}	9-27
Figure 9.2-3—{Essential Service Water Emergency Makeup System}	9-28
Figure 9.2-4—{Schematic of Raw Water/Treated Water Supply}	9-29
Figure 9.2-5—{Collector Well River Intake System}	9-30
Figure 9.2-6—{Collector Well River Intake System Pump Structure-Plan View}	9-31
Figure 9.2-7—{Collector Well River Intake System Pump Structure - Section View}	9-32

-igure 9.2-8—{Plant Arrangement - ESWEMS Pumphouse Floor Plan}	9-33
-igure 9.2-9—{Plant Arrangement - ESWEMS Pumphouse Section}	9-34
-igure 9.2-10—{Plant Arrangement - ESWEMS Pumphouse Section}	9-35
-igure 9.2-11—{Plant Arrangement - ESWEMS Pumphouse Section}	9-36
-igure 9.2-12—{Plant Arrangement - ESWEMS Pumphouse Pump Well Plan}	9-37
-igure 9.2-13—{Plant Arrangement - ESWEMS Pumphouse Mezzanine Plan}	9-38
-igure 9.2-14—{Plant Arrangement - ESWEMS Pumphouse Roof Plant}	9-39
Figure 9.4-1—{ESWEMS Pumphouse Ventilation System}	9-47
Figure 9.5-1—{Fire Protection Organization}	9-65

9B Fire Protection Analysis - Plant Specific Supplement

Figure 9B-1—{Callaway Unit 2 Fire Barrier Location, Turbine Building Plan at Elevation (-)23 Feet}.9B-36
Figure 9B-2—{Callaway Unit 2 Fire Barrier Location, Turbine Building Plan at Elevation +/- 0 Feet}.9B-37
Figure 9B-3—{Callaway Unit 2 Fire Barrier Location, Turbine Building Plan at Elevation +38 Feet} .9B-38
Figure 9B-4—{Callaway Unit 2 Fire Barrier Location, Turbine Building Plan at Elevation +65 Feet} .9B-39
Figure 9B-5—{Callaway Unit 2 Fire Barrier Location, Turbine Building Plan at Elevation (-)43 Feet}.9B-40
Figure 9B-6—{Callaway Unit 2 Fire Barrier Location, Turbine Building Roof Plan}9B-41
Figure 9B-7—{Callaway Unit 2 Fire Barrier Location, Turbine Building Section A-A}9B-42
Figure 9B-8—{Callaway Unit 2 Fire Barrier Location, Turbine Building Section B-B}9B-43
Figure 9B-9—{Callaway Unit 2 Fire Barrier Location, Turbine Building Section C-C}9B-44
Figure 9B-10—{Callaway Unit 2 Fire Barrier Location, SWGR/SBO Buildings Plan View at Elevation (-)13'-0"}
Figure 9B-11—{Callaway Unit 2 Fire Barrier Location, SWGR/SBO/AUX BLR Buildings Plan View at Elevation 0'-0"}
Figure 9B-12—{Callaway Unit 2 Fire Barrier Location, SWGR/SBO/AUX BLR Buildings Plan View at Elevation 13'-0"}
Figure 9B-13—{Callaway Unit 2 Fire Barrier Location, SWGR/SBO/AUX BLR Buildings Plan View at Elevation 24'-6"}
Figure 9B-14—{Callaway Unit 2 Fire Barrier Location, SWGR/SBO/AUX BLR Buildings, Plan View Section A-A}
Figure 9B-15—{Callaway Unit 2 Fire Barrier Location, Transformer Area Plan View at Elevation 0'-0" } 9B-50
Figure 9B-16—{Callaway Unit 2 Fire Barrier Location, Security Access Facility Plan View}
Figure 9B-17—{Callaway Unit 2 Fire Barrier Location, Central Gas Supply Building Plan View}9B-52
Figure 9B-18—{Callaway Unit 2 Fire Barrier Location, Switchyard Control House Plan View}9B-53
Figure 9B-19—{Callaway Unit 2 Fire Barrier Location, Fire Protection Building Plan View}
Figure 9B-20—{Callaway Unit 2 Fire Barrier Location, Circulating Water Pump Building, Plan View and Section A-A (Typical)}
Figure 9B-21—{Callaway Unit 2 Fire Barrier Location, ESWEMS Pumphouse, Fire Protection Layout} 9B-56

10.0 Steam and Power Conversion System

Figure 10.4-1—{Circulating Water System P & ID (Circulating Water Pump Building)}	10-17
Figure 10.4-2—{Circulating Water System P & ID (Turbine Building)}	10-18
Figure 10.4-3—{Circulating Water System Pump Intake Structure (Plan View)}	10-19
Figure 10.4-4—{Circulating Water System Pump Intake Structure (Section View)}	10-20
Figure 10.4-5—{Circulating Water System P & ID Cooling Towers}	10-21
Figure 10.4-6—{Circulating Water System P & ID Blowdown Flowpath}	10-22
Figure 10.4-7—{Circulating Water System Plant Discharge}	10-23

11.0 Radioactive Waste Management

12.0 Radiation Protection

Figure 12.3-1—{Site Layout of Callaway	Plant Unit 2		
rigule 12.5-1—(Sile Layout of Callawa)	y Flaint Offit Z	[

13.0 Conduct of Operations

Figure 13.1-1—{Organization Chart}		-25
------------------------------------	--	-----

14.0 Verification Programs

15.0 Transient and Accident Analysis

16.0 Introduction

17.0 Quality Assurance and Reliability Assurance

18.0 Human Factors Engineering

19.0 Probabilistic Risk Assessment and Severe Accident Evaluation