NRC FORM 591M PART 1 (10-2003)			U.S. NUCLEAR REGULATORY COMMISSION			
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION						
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE			
Insight Diagnostic Imaging 806 Clearwater Loop, Suite N Post Falls, Idaho 83854			USNRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005			
Location: 750 N. Syringa Street, REPORT NUMBER 2009-001		Post Falls, ID	0			
3. DOCKET NUMBER 030-37735		4. LICENSEE NUMBER 11-29290	-01	5. DATE OF INSPECTION February (
LICENSEE:						
2. Previous violatio 3. The violation(s), identified, non-repe 1600, to exercise d Nor	RC) rules and regulative records, interview spection findings, no on(s) closed. , specifically describe titive, and corrective liscretion, were satist n-Cited Violation(s) w	ions and the conditions of vs with personnel, and obs violations were identified. ed to you by the inspector action was or is being tak fied. vas/were discussed involvi	your license. The inspecti ervations by the inspector.	on consisted of selective The inspection findings not being cited because ria in the NRC Enforcern nt(s) and Corrective Acti	e examinations of s are as follows: they were self- tent Policy, NUREG- on(s):	
	d Corrective Actions)					
corrective actions is made	30 days, the actions in accordance with th ce will be achieved). I	e described by me to the in ne requirements of 10 CFR I understand that no furthe ted Name	r written response to NRC	rect the violations identif	teps which will be taken,	
			4-4	x /v/mg_		
NRC FORM 591M PART 1 (10-	~2003)			X		