

(10-2003)
10 CFR 2.201

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Hurley Medical Center REPORT NUMBER(S) 2009-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-01993	4. LICENSE NUMBER(S) 21-00338-02	5. DATE(S) OF INSPECTION 1/13/09	
6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS 03.01-03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 2240	2. PRIORITY 2	3. LICENSEE CONTACT Appa Rao Makkam	4. TELEPHONE NUMBER 810/257-9000
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: <u>7/2010</u>	
<input type="checkbox"/> Field			
<input type="checkbox"/> Temporary Job Site			

PROGRAM SCOPE

Licensee is a medical facility located in Flint, Michigan. This licensee is a large general hospital with a complete line of services. This inspection is a follow-up to escalated enforcement involving the failure to remove individuals no longer at the facility or who no longer need access to radioactive materials in quantities of concern from the access list.

Performance Observations

The inspector reviewed the list of personnel given unescorted access to the blood irradiator and determined that the list had been pared to remove individuals who no longer needed access to the irradiator and that their key cards had been deactivated. Only four individuals at present have access to the device. Each has undergone a proper security check and are properly listed on the access list.

During the course of the inspection, no abnormalities were noted.



