

**Open Generic Communication TACs (PA No. 101122CA/B)
Summary Report (AS OF 02/28/2009)**

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
MD5448	RIS 'Consideration of Risk of Fire & Other External Events in 50.65(a)(4) Risk Assess & Mgmt'	O	21.8	5/4/2007	DRA
MD9330	RIS 'Communications Between NRC and Reactor Licensees During Emergencies and Significant Incidents'	O	6.9	7/30/2008	NSIR
MD9331	RIS 'Use of Multiple Dosimetry and Compartment Factors for EDE'	O	6.9	7/30/2008	DIRS
MD9346	RIS 'Delay in the Resolution of In-Vessel Downstream Effects Issues Related to GL 2004-02'	O	6.9	7/31/2008	DSS
MD9983	RIS 'Steam Generator Tube Inspections'	O	4.0	10/27/2008	DCI
ME0240	RIS 'RIS 2007-16, Rev. 1, Implementation of the Requirements of 10 CFR 54.34(b) and the Backfit Rule'	O	2.4	12/16/2008	RPOB
ME0366	RIS 'RIS 2005-02, Rev. 1 Clarifying the Process for Making Emergency Plan Changes'	O	1.6	01/08/2009	NSIR
ME0371	RIS 'Physical Protection of Chemical Hazards at NRC Licensees'	O	1.5	01/12/2009	NSIR
ME0655	RIS 'Implementation of New Final Rule, Protection of Safeguards Information'	O	0.3	02/17/2009	NSIR
MD9738	IN 'Spurious Safety Injection and Reactor Trip at North Anna Unit 2	O	4.9	9/30/2008	DE
ME0392	IN 'Transformer Failures – Recent Operating Experience'	O	1.4	01/15/2009	IOEB
ME0460	IN 'Turbine Driven Auxiliary Feedwater Pump Inoperable Due to Mispositioned Valve'	O	0.8	02/02/2009	DIRS
ME0465	IN 'Operational Considerations for Engagement Simulation Systems'	O	0.8	02/04/2009	NSIR
ME0470	IN 'Construction Related Experience with Internal Flooding Protection Systems'	O	0.7	02/04/2009	NRO
ME0471	IN 'Construction Related Experience with Cables, Connectors, and Junction Boxes'	O	0.7	02/04/2009	NRO
ME0472	IN 'Withholding of Proprietary Information from Public Disclosure'	O	0.7	02/04/2009	NMSS
ME0622	IN 'High Pressure Coolant Injection Control Loop Oscillation'	O	0.5	02/10/2009	EICB

**Open Generic Communication TACs (PA No. 101122CA/B)
Summary Report (AS OF 02/28/2009)**

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
ME0679	IN 'Underestimate Of Dam Failure Frequency Used In Probabilistic Risk Assessments'	O	0.2	02/20/2009	DRA
ME0707	IN 'Unplanned Control Rod Withdrawal'	O	0.1	02/24/2009	RIII
ME0725	IN 'Painting Activities Result in Inoperability of EDGs and Other Plant Equipment'	O	0.0	02/26/2009	DIRS
MD7897	GL 'Generic Letter 2008-01, Generic Technical Review'	O	13.6	01/17/2008	DE
