

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: Cardiology & Arrhythmia Consultants 400 Gresham Drive, Medical Tower, Suite 507 Norfolk, Virginia 23507  REPORT Nos                      03036962/2009-001	2. NRC/REGIONAL OFFICE  <b>U.S. Nuclear Regulatory Commission                  Region I, 475 Allendale Road                  King of Prussia, Pennsylvania 19406-1415</b>
---	---

3. DOCKET NUMBER(S) 03036962	4. LICENSE NUMBER(S) 45-31057-01	5. DATE(S) OF INSPECTION 2/12/2009
---------------------------------	-------------------------------------	---------------------------------------

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified,
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

*10 CFR 20.1924(a) requires, in part, that each licensee ensure that each container of licensed material bears a durable, clearly visible label bearing the radiation symbol and the words "Caution - Radioactive Materials" or "Danger - Radioactive Materials." Contrary to the above, on February 11, 2009, the licensee placed waste contaminated with <sup>125</sup>I in a biohazard container not labeled with a label as described above. This is a severity level IV violation (Supplement IV). The licensee indicated they would obtain a leaded box for the biohazard container and label the container and the box as described above. Until the container is labeled, the radioactive waste storage container would be used for any biohazardous waste that is contaminated.*

**Licensee's Statement of Corrective Actions for Item 4, above.**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	SOPHIE PARKER		2/18/09
NRC INSPECTOR	Steven R. Courtemanche		2/12/09