

Exelon Generation Company, LLC
Byron Station
4450 North German Church Road
Byron, IL 61010-9794

www.exeloncorp.com

April 8, 2009

LTR; BYRON 2009-0041
File: 1.10.0101

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555-0001

Byron Station, Unions 1 and 2
Facility Operating License Nos. NPF-37 and NPF-66
NRC Docket Nos. STN 50-454 and STN 50-455

Subject: 2008 Regulatory Commitment Change Summary Report

Enclosed please find the "Regulatory Commitment Change Summary Report" for Byron Station. This report contains summary information from January 1, 2008, through December 31, 2008. Revisions to docketed regulatory commitments were processed using the current revision of Nuclear Energy Institutes' document NEI 99-04 "Guidelines for Managing Nuclear Regulatory Commission (NRC) Commitment Changes."

If you have any questions concerning this report, please contact D. Gudger, Regulatory Assurance Manager at (815) 406-2800.

Respectfully,



Daniel J. Enright
Site Vice President
Byron Station

DJE /TLH/ cy

Enclosure

ATTACHMENT

BYRON STATION

REGULATORY COMMITMENT CHANGE SUMMARY REPORT FOR 2008

Original Document:

Commitment ARs 10323 – 10336, 10338 – NRC Notice of Violation October 11, 1988

Subject of Deletion's

AR 10313 – 0 BVS.5-1.WO1
AR 10323 - 1/2 BVS.5-3.CC.1-1
AR 10324 - 1/2 BVS.5-3.CC.1-2
AR 10325 - 1/2 BVS.5-2.F.3-1
AR 10326 - 1/2 BVS.5-2.F.3-2
AR 10327 - 1/2 BVS.5-2.F.2-1
AR 10328 - 1/2 BVS.5-2.F.2-2
AR 10329 - 1/2 BVS.6.2.1.B-1
AR 10330 - 1/2 BVS.6.2.1.B-2
AR 10331 - 1/2 BVS.1.2.3.1-1
AR 10332 - 1/2 BVS.1.2.3.1-1
AR 10333 - 1/2 BVS.1.2.3.1-2
AR 10334 – 0 BVS.5.3.SX.1-2
AR 10335 – 0 BVS.5.3.SX.1-1
AR 10336 - 1/2 BVS.5.3.SX.1-1
AR 10338 - 1/2 BVS.5.3.SX.1-2

These procedures have been revised to add steps to assure the repeatability of the position of vibration measurements on those pumps included in the current IST program. This is to assure compliance with section XI of the ASME code, subsection IWP-4160.

Basis:

This has been standard practice for 20+ years and has also been incorporated into the fleetwide IST Program.

Status:

These commitments were deleted under Commitment Change Numbers 08-013 through 08-027.

ATTACHMENT

BYRON STATION

REGULATORY COMMITMENT CHANGE SUMMARY REPORT FOR 2008

Original Document:

Commitment AR 577295-07 & 10 - May 16, 2007 B.5.b Fleetwide Response to NRC

Subject of Change::

"Attachment 1b, Table A.6-1: ID#32 External spray of the containment building. High confidence release reduction strategy. ID #23 vent containment via the emergency access hatch.

Attachment 1b, Table A.2-4: ID #5 SFP makeup from Aux Bldg and FHB hose stations. This strategy may provide 1250 gpm through five 2.5 fire hoses."

Basis:

Table A.6-1 - It was erroneously indicated in the May 16, 2007 B.5.b Fleetwide Response that a modification was going to be installed; when it was not. IR 806752 was written after the identifying NRC inspector indicated he did not want a separate letter issued to correct this and to utilize this Annual NRC Commitment Change / Deletion Notification Process.

Table A.2-4 will correct wording from 'hoses' to 'hydrants'.

Status:

The commitment was being changed under Commitment Change Number 08-031.