HLWYM HEmails

From: Tae Ahn

Sent: Monday, February 26, 2007 8:37 AM **To:** Yi-Ming Pan; Sheena Whaley

Cc: Xihua He

Subject: Re: ENG1 review strategy section A

Comments:

(1) "1. General corrosion of drip shield" needs to be added as the last part of "2. General corrosion of waste package outer layer." Early DS failure is expected mainly from mechanical failure. By the time DS failure by corrosion, temperature will be low enough to avoid WP localized corrosion. DS is fully assessed in Risk Insight Progress Report (second one), and has never been graded as a risk significant issue. We simply need to know proper data base.

(2) In Risk Insights in "1. Peristency of a passive film on Alloy 22" - add words to the end " ---, and others related to the evidence of sustaining passive film."

>>> Yiming Pan <<u>ypan@cnwra.swri.edu</u>> 02/23/2007 7:02 PM >>> Sheena and Tae.

A copy of the ENG1 review strategy section A is placed at the share drive X: or N:\ENG 1. I will be on travel next week. Please call my cellular phone at (210)522-5194 if you have any questions.

Thanks, Yiming Hearing Identifier: HLW_YuccaMountain_Hold_EX

Email Number: 1624

Mail Envelope Properties (s5e29c44.052)

Subject: Re: ENG1 review strategy section A

Sent Date: 2/26/2007 8:37:15 AM **Received Date:** 2/26/2007 8:37:57 AM

From: Tae Ahn

Created By: Tae.Ahn@nrc.gov

Recipients:

"Xihua He" <xhe@cnwra.swri.edu>

Tracking Status: None

"Yi-Ming Pan" <ypan@cnwra.swri.edu>

Tracking Status: None

"Sheena Whaley" <Sheena.Whaley@nrc.gov>

Tracking Status: None

Post Office: NRNWMS05.NRC.GOV

Files Size Date & Time

MESSAGE 978 2/26/2007 8:37:57 AM

Options

Priority:StandardReturn Notification:NoReply Requested:NoSensitivity:Normal

Expiration Date: Recipients Received: