

NRC FORM 591M PART 1 **U.S. NUCLEAR REGULATORY COMMISSION**
10-2003
 10 CFR 2.201

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: St. Vincent's Medical Center 2800 Main Street Bridgeport, CT 06606 REPORT Nos 2008-001	2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415
--	---

3. DOCKET NUMBER(S) 030-01245	4. LICENSE NUMBER(S) 06-00843-03	5. DATE(S) OF INSPECTION 8/15/2008 - 4/27/2009
---	--	--

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the Inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 40.51(b)(5) authorizes transfers of devices or products containing depleted uranium only to persons authorized to receive such sources or byproduct material under the terms of a general or specific license. Contrary to the above, the licensee transferred depleted uranium shielding to a general licensee and the terms of the general license were not met. Specifically, the depleted uranium shielding was not labeled properly. On February 12, 2009, the licensee provided the required label to the general licensee and verified that the proper labeling had occurred.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Physicist VAS KRITHIVAS, Ph.D.		4/28/09
NRC INSPECTOR	Tara L. Weidner		4/27/2009