

~~Non-Sensitive - Not For Public Disclosure~~

DAILY STAFF NOTES

REGION I

January 22, 2009

- On January 21, Region I issued inspection report 50-219/2008007 for the Oyster Creek (OC) license renewal follow-up inspection. The inspection was performed using IP 71003 "Post-Approval Site Inspection for License Renewal," as a prudent measure, absent a final NRC decision on license renewal. The inspection observed OC license renewal activities during the last refueling outage prior to April 9, 2009, when the plant would enter the period of extended operation under the timely renewal provision of 10 CFR Part 54.31. Based on the inspection results, the NRC did not identify any safety significant conditions affecting current operations.

~~Non-Sensitive - Not For Public Disclosure~~