

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Perspectives Imaging 91 West 1750 North Centerville, Utah 84014 Location: 777 Hospital Way Portneuf Medial Center Pocatello, Idaho 83201 REPORT No: 2009-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125	
3. DOCKET NUMBER 150-00043	4. LICENSE NUMBER UT-0600514	5. DATE OF INSPECTION April 16 through May 01, 2009	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.



10 CFR 35.61(a) requires, in part, that a licensee calibrate the survey instruments used to show compliance with this part and 10 CFR Part 20 before first use, annually, and following a repair that affects the calibration.

Contrary to the above, as of February 18, 2009, the licensee was using a Ludlum Model 14-C, serial number 247097 survey instrument to show compliance with this part and 10 CFR Part 20. The survey instrument was last calibrated February 2008, and had not been calibrated from February 19, 2009 through April 14, 2009.

The licensee committed to taking prompt corrective action by removing the affected equipment out of service and having it calibrated by an individual authorized for such services. In the mean time a loaner survey instrument that is fully operational and calibrated shall be used by Perspectives Imaging to show compliance with 10 CFR Part 35 and Part 20.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Lisa Bosworth, M.S		May 1, 2009
NRC INSPECTOR	R. Rick Muñoz		May 1, 2009