

Figure 3E.1-14—Reinforcement Pattern for Section 3-3 of the Equipment Hatch Area





Figure 3E.1-15—Elevation View of the Entire RCB



UJA029 T2

Figure 3E.1-16—Section Cut Through Entire RCB





Figure 3E.1-17—Elevation View of Critical Section



UJA031 T2

Figure 3E.1-18—Section View Cut Through Critical Section




Figure 3E.1-19—Plan View Cut Through Critical Section





Figure 3E.1-20—Elevation View of Buttress 3



UJA034 T2

[Next File](#)