



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555-0001

June 24, 2009

Mr. Jeffrey B. Archie
Vice President, Nuclear Plant Operations
South Carolina Electric & Gas Company
Virgil C. Summer Nuclear Station
Post Office Box 88
Jenkinsville, SC 29065

SUBJECT: VIRGIL C. SUMMER NUCLEAR STATION, UNIT NO. 1 – DAM SAFETY AND
OPERATION INSPECTION REPORT

Dear Mr. Archie:

Enclosed is a copy of the Dam Safety Inspection Report prepared by the Federal Energy Regulatory Commission (FERC) for the U.S. Nuclear Regulatory Commission. The enclosure contains the results of an inspection on April 22, 2009, of the service water pond dams at the Virgil C. Summer Nuclear Station, Unit No. 1. During this inspection there were no conditions found that should adversely affect the immediate safety and permanence of the structures or the operational reliability of the reservoir.

At FERC's request, the enclosure is not being made publicly available since it contains critical energy infrastructure information.

Sincerely,

A handwritten signature in cursive script that reads "Robert E. Martin".

Robert E. Martin, Senior Project Manager
Plant Licensing Branch II-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-395

Enclosure:
Dam Safety and Operation Inspection Report

The enclosure transmitted herewith
contains Security-Related information.
When separated from enclosure, this
document is decontrolled.

Mr. Jeffrey B. Archie
Vice President, Nuclear Plant Operations
South Carolina Electric & Gas Company
Virgil C. Summer Nuclear Station
Post Office Box 88
Jenkinsville, SC 29065

SUBJECT: VIRGIL C. SUMMER NUCLEAR STATION, UNIT NO. 1 – DAM SAFETY AND
OPERATION INSPECTION REPORT

Dear Mr. Archie:

Enclosed is a copy of the Dam Safety Inspection Report prepared by the Federal Energy Regulatory Commission (FERC) for the U.S. Nuclear Regulatory Commission. The enclosure contains the results of an inspection on April 22, 2009, of the service water pond dams at the Virgil C. Summer Nuclear Station, Unit No. 1. During this inspection there were no conditions found that should adversely affect the immediate safety and permanence of the structures or the operational reliability of the reservoir.

At FERC's request, the enclosure is not being made publicly available since it contains critical energy infrastructure information.

Sincerely,

/RA/

Robert E. Martin, Senior Project Manager
Plant Licensing Branch II-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-395

Enclosure:
Dam Safety and Operation Inspection Report

**The enclosure transmitted herewith
contains Security-Related information.
When separated from enclosure, this
document is decontrolled.**

DISTRIBUTION:

Public (ML09170671)
LPL2-1 R/F
RidsNrrDorLpl2-1
RidsNrrDorDpr

RidsNrrPMSummer
RidsNrrLASRorher
RidsRgn2MailCenter
RMartin

RidsOgcRp
RidsAcrcAcnwMailCenter
GWilson

ADAMS Accession No.: PKG: ML091730617
PUBLIC LTR: ML091730671

NON-Public LTR: ML091730668,

NRR-106

OFFICE	NRR/LPL2-/PM	NRR/LPL2-1/LA	NRR/EEEB/BC	NRR/LPL2-1/BC
NAME	RMartin	SRohrer	GWilson	MWong
DATE	06/ 21/09	06/ 23/09	06/ 24/09	06/24/09

OFFICIAL RECORD COPY