

FEB 03 1983

RIV Official File Copy

License: SMB-911

040-7580

Fansteel, Inc.
ATTN: James A. Pierret
Manager
Number Ten Tantalum Place
Muskogee, OK 74401

Gentlemen:

This refers to the telephone conversation between Mr. Jerry Everett of this office and Mr. James A. Pierret on January 14, 1983, regarding the actions you would take regarding the problem of a leaking liner in your number 3 retention pond.

Regarding this matter, we understand that you will undertake the following actions:

1. Immediately initiate the installation of three additional monitoring wells; one located west of the pond near the railroad tracks, one northeast of the french drain, and one due east near the perimeter fence line.
2. Start pumping from the longitudinal drain to determine the location of the leak.
3. Locate and mend the leak.
4. Provide this office with a monthly progress report until the issue has been resolved.

If this is not your understanding of your course of action and commitment, please contact us immediately.

Sincerely,

J. T. Collins
Regional Administrator

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

bcc: c/o DMB (IE07) bcc: RIV bcc: Dale Smith, URFO
AEOD/NR J. Collins
IE/DFFMS/FFMB01 R. Bangart
IE/RSB Inspector
NMSS RIV File
NRC PDR

MRPS
JEverett:jd
1/10/83

TPB
GBrown
1/10/83

DDY&TP
RBangart
1/21/83

RA/RIV
JCollins
1/11/83

A-22