



ENERGY NORTHWEST

Dale K. Atkinson
Vice President, Operational Support
P.O. Box 968, PE03
Richland, WA 99352-0968
Ph. 509.377.4302 | F. 509.377.4098
dkatkinson@energy-northwest.com

August 10, 2009
GO2-09-110

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555-0001

Subject: **COLUMBIA GENERATING STATION, DOCKET NO. 50-397
LICENSEE EVENT REPORT NO. 2009-S01-00**

Dear Sir or Madam:

Transmitted herewith is 60-Day Follow-up Report No. 2009-S01-00 for Columbia Generating Station. This report is submitted in consideration of anticipated interest in Energy Northwest's investigation of the event reported in Event Report 45131 on June 13, 2009. The enclosed report contains security related information and is requested to be withheld from public disclosure under 10 CFR 2.390.

There are no commitments being made to the NRC by this letter. If you have any questions or require additional information, please contact Mr. GV Cullen at (509) 377-6105.

Respectfully,

DK Atkinson
Vice President, Operational Support

Enclosure: Licensee Event Report 2009-S01-00

cc: EE Collins, Jr. – NRC RIV
NJ DiFrancesco – NRC NRR
INPO Records Center (w/o)
NRC Sr. Resident Inspector – 988C (2)
RN Sherman – BPA/1399 (w/o)
WA Horin – Winston & Strawn (w/o)
WC Walker – NRC RIV

IE74
NRR