

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: <i>Michigan Cardiology, P.C. Wayne, MI Southfield, MI Clinic (location inspected)</i> REPORT NUMBER(S) <i>2009-001</i>		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351	
3. DOCKET NUMBER(S) <i>1030-36384</i>	4. LICENSEE NUMBER(S) <i>21-32468-01</i>	5. DATE(S) OF INSPECTION <i>August 18, 2009</i>	

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

License Cond. 15.A specifies that the licensee will conduct its program in accordance with the statements in Application dated 8/14/03. Item 10. b. states that the licensee will provide dosimetry per the criteria and discussion paragraphs in NUREG-1556, Volume 9, Section 8.22. The licensee's radiation protection program, No. 11 "Personal Monitoring Program," states in part that extremity personnel dosimeters must be worn (with the label facing radior source. Contrary to the requirements of License Condition 15.A, the licensee did not provide an extremity dosimeter to a nuclear medicine technologist. Licensee personnel immediately ordered a dosimeter for this NMT.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	<i>M. P. Mansoor</i>	<i>MANSOOR NAIMI</i>	<i>8/18/09</i>
NRC INSPECTOR	Deborah A. Piskura	<i>Deborah A. Piskura</i>	<i>8/18/09</i>

RP

