



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
612 EAST LAMAR BLVD, SUITE 400
ARLINGTON, TEXAS 76011-4125

September 1, 2009

Ross T. Ridenoure,
Senior Vice President and
Chief Nuclear Officer
Southern California Edison Company
San Onofre Nuclear Generating Station
P.O. Box 128
San Clemente, CA 92674-0128

SUBJECT: MIDCYCLE PERFORMANCE REVIEW AND INSPECTION PLAN –
SAN ONOFRE NUCLEAR GENERATING STATION

Dear Mr. Ridenoure:

On August 4, 2009, the NRC staff completed its performance review of San Onofre Nuclear Generating Station (SONGS), Units 2 and 3 for the first half of the calendar year 2009 assessment cycle. Our technical staff reviewed performance indicators (PIs) for the most recent quarter and inspection results over the previous 12 months. The purpose of this letter is to inform you of our assessment of your safety performance during this period and our plans for future inspections at your facility.

This performance review and enclosed inspection plan do not include security information. A separate letter designated and marked as "Official Use Only – Security-Related Information" will include the security cornerstone review and resultant inspection plan.

Although SONGS Units 2 and 3 operated in a manner that preserved public health and safety and fully met all cornerstone objectives, the NRC continues to identify performance problems in human performance and problem identification and resolution. This is the fourth consecutive assessment cycle where substantive crosscutting issues were identified in human performance and problem identification and resolution. We conducted public meetings in May and June of 2009 following the End-of-Cycle Assessment to discuss your improvement initiatives. While we acknowledge that you are seeing some early indications of performance improvements, based on your performance monitoring activities, the NRC will leave open the substantive crosscutting issues until our inspections and observations indicate your corrective actions have been effective. The NRC will continue to conduct periodic public meetings and perform additional inspection activities to closely monitor your effectiveness in addressing these performance deficiencies. The NRC will consider additional actions, if needed, in the event performance improvements are not reflected in inspection and assessment results.

Unit 2 Plant performance for the most recent quarter was within the Regulatory Response column of the NRC's Action Matrix, based on one White finding in the Mitigating Systems cornerstone. The finding involved the failure to establish appropriate instructions for replacement of a safety-related battery output breaker resulting in the battery being inoperable between March 2004 and March 2008. Unit 3 Plant performance was within the Licensee Response Column of the NRC's Action Matrix, based on all inspection findings being classified as having very low safety significance (Green) and all PI's indicating performance at a level requiring no additional NRC oversight (Green).

During this assessment period, the NRC identified 20 Green findings and one White finding with crosscutting aspects in the human performance area. In our annual assessment letter dated March 4, 2009, we advised you of substantive crosscutting issues associated with the components of resources and work practices involving the themes of failing to provide adequate procedures or work instructions and ineffective use of human error prevention techniques. Our current assessment identified six Green findings involving ineffective use of human error prevention techniques and three findings involving inadequate procedures. The inadequate procedure findings included two Green findings with one in the most recent quarter and one White finding. We determined that your corrective actions have not demonstrated adequate improved performance to close the substantive crosscutting issues.

Additionally, during this assessment period the staff identified an additional human performance theme in the component of decision-making associated with failing to use conservative assumptions. Four findings were identified during the assessment period affecting the Mitigating Systems and Initiating Events cornerstones. Examples of these human performance findings include: failure to implement timely corrective actions to preclude repetition of a significant condition adverse to quality associated with safety related 480 volt breakers, failure to adequately evaluate a degraded relay that affected operability of an emergency diesel generator, failure to adequately evaluate the impact of boric acid leakage effects on the reactor coolant system, and a failure to adequately evaluate degraded conditions to support an operability assessment associated with a degraded component cooling water heat exchanger.

These human performance substantive crosscutting issues will remain open until we determine that corrective actions have been effective.

During this assessment period, the NRC identified eight Green findings and one Severity Level IV finding with crosscutting aspects in the problem identification and resolution area. In our annual assessment letter dated March 4, 2009, we advised you of a crosscutting theme in the component of the corrective action program involving instances of failing to thoroughly evaluate problems such that the resolutions effectively address causes and extent of conditions. During this assessment period seven Green findings were related to this theme. Your staff has taken corrective actions to address these issues; however, these corrective actions have not resulted in adequate performance improvement as evidenced by the continued high number of findings. Therefore, this problem identification and resolution substantive crosscutting issue will remain open until we determine that corrective actions have been effective.

On January 11, 2008, the NRC issued SCE Confirmatory Order EA 07-232. The Order was issued in response to the identification of several instances of willful violations. The Order specified specific actions that SCE committed to perform to address potential safety culture issues. In October 2008, the NRC performed a team inspection that reviewed your corrective actions associated with the Order. Based on this inspection, the team determined you

demonstrated sufficient progress to close eight of the Order items. However, for a significant number of items the team was unable to determine that your staff had taken sufficient actions, therefore these items remained open. On January 14, 2009, the NRC received your letter providing a status report regarding your schedule for completion of the open Order items. The NRC performed a follow-up Confirmatory Order inspection in June 2009. Based on the results of that inspection the NRC closed an additional four Order items. Currently two Confirmatory Order items remain open that involve the completion of training activities scheduled through December 2009 and submittal of a letter to the NRC that discusses your basis for concluding that each Order item has been satisfied. The NRC plans to perform additional inspections following completion of these items.

Your continuing performance problems are of concern to the NRC. This concern is based, in part, on a White finding moving Unit 2 to the Regulatory Response column of the NRC's Action Matrix; four consecutive assessment cycles with substantive crosscutting issues not being effectively addressed in the areas of human performance and problem identification and resolution; and the identification of an additional substantive crosscutting issue theme during this assessment period in the human performance area related to the failure to use conservative assumptions for decision making activities. On the basis of this concern the NRC is requesting the following:

- 1) We request you provide a written response to this letter updating the status of your corrective actions planned to address the human performance and the problem identification and resolution crosscutting issues, including schedules, milestones, and performance monitoring metrics.
- 2) We request you support periodic public meetings to discuss your improvement initiatives for the areas discussed in this letter until sustained improvement is noted.
- 3) In our last assessment letter dated March 4, 2009 we requested that you perform an independent assessment of the safety culture at SONGS. We request you provide us a letter discussing the results of this assessment and any associated planned actions and projected completion dates.
- 4) We request that you provide written notification to the NRC of your readiness for NRC to conduct a 95001 supplemental inspection for the White finding associated with the loose battery connection on Unit 2.

The enclosed inspection plan details the inspections, less those related to security scheduled through December 31, 2010. This inspection plan includes an infrequently performed inspection due to the steam generator replacement outages scheduled to occur during this period. The inspection plan is provided to allow for the resolution of any scheduling conflicts and personnel availability issues well in advance of inspector arrival onsite. Routine resident inspections are not listed due to their ongoing and continuous nature. The inspections in the last nine months of the inspection plan are tentative and may be revised at the end-of-cycle review.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document

system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

If circumstances arise which cause us to change this inspection plan, we will contact you to discuss the change as soon as possible. Please contact Michael Hay at (817) 860-8173 with any questions you may have regarding this letter or the inspection plan.

Sincerely,



Elmo Collins
Regional Administrator

Dockets: 50-361
50-362

Licenses: NPF-10
NPF-15

cc w/enclosure: San Onofre Nuclear Generating Station Inspection/ Activity Plan

Chairman, Board of Supervisors
County of San Diego
1600 Pacific Highway, Room 335
San Diego, CA 92101

Gary L. Nolff
Assistant Director-Resources
City of Riverside
3900 Main Street
Riverside, CA 92522

Mark L. Parsons
Deputy City Attorney
City of Riverside
3900 Main Street
Riverside, CA 92522

Gary H. Yamamoto, P.E., Chief
Division of Drinking Water and
Environmental Management
1616 Capitol Avenue, MS 7400
P.O. Box 997377
Sacramento, CA 95899-7377

Michael J. DeMarco
San Onofre Liaison
San Diego Gas & Electric Company
8315 Century Park Ct. CP21G
San Diego, CA 92123-1548

Director, Radiological Health Branch
State Department of Health Services
P.O. Box 997414 (MS 7610)
Sacramento, CA 95899-7414

Mayor
City of San Clemente
100 Avenida Presidio
San Clemente, CA 92672

James D. Boyd, Commissioner
California Energy Commission
1516 Ninth Street (MS 34)
Sacramento, CA 95814

Douglas K. Porter, Esq.
Southern California Edison Company
2244 Walnut Grove Avenue
Rosemead, CA 91770

Albert R. Hochevar
Southern California Edison Company
San Onofre Nuclear Generating Station
P.O. Box 128
San Clemente, CA 92675

A. Edward Scherer
Southern California Edison Company
San Onofre Nuclear Generating Station
P.O. Box 128
San Clemente, CA 92674-0128

Mr. Steve Hsu
Department of Health Services
Radiologic Health Branch
MS 7610, P.O. Box 997414
Sacramento, CA 95899-7414

Mr. Mike Short
Southern California Edison Company
San Onofre Nuclear Generating Station
P.O. Box 128
San Clemente, CA 92674-0128

Chief, Technological Hazards Branch
FEMA Region IX
1111 Broadway, Suite 1200
Oakland, CA 94607-4052

Electronic distribution by RIV:

- Regional Administrator (Elmo.Collins@nrc.gov)
- Deputy Regional Administrator (Chuck.Casto@nrc.gov)
- DRP Director (Dwight.Chamberlain@nrc.gov)
- DRP Deputy Director (Anton.Vegel@nrc.gov)
- DRS Director (Roy.Caniano@nrc.gov)
- DRS Deputy Director (Troy.Pruett@nrc.gov)
- Branch Chief, DRP/D (Michael.Hay@nrc.gov)
- Senior Project Engineer, DRP/D (Don.Allen@nrc.gov)
- Senior Resident Inspector (Greg.Warnick@nrc.gov)
- Resident Inspector (John.Reynoso@nrc.gov)
- Team Leader, DRP/TSS (Chuck.Paulk@nrc.gov)
- RITS Coordinator (Marisa.Herrera@nrc.gov)
- Public Affairs Officer (Victor.Dricks@nrc.gov)
- Regional State Liaison Officer (Bill.Maier@nrc.gov)
- RA Secretary (Lucy.Owen@nrc.gov)
- DRA Secretary (Judy.Kilcrease@nrc.gov)
- Branch Chief, DRS/EB1 (Thomas.Farnholtz@nrc.gov)
- Branch Chief, DRS/EB2 (Neil.Keefe@nrc.gov)
- Branch Chief, DRS/PSB1 (Michael.Shannon@nrc.gov)
- Branch Chief, DRS/PSB2 (Greg.Werner@nrc.gov)
- Branch Chief, DRS/OB (Ryan.Lantz@nrc.gov)
- OEDO RIV Coordinator, Primary (Leigh.Trocine@nrc.gov)
- OEDO, TRPS (Tamara.Bloomer@nrc.gov)
- Deputy Director, DIRS, NRR (Frederick.Brown@nrc.gov)
- Director, DORL, NRR (Joseph.Giitter@nrc.gov)
- Deputy Director, DORL, NRR (Robert.Nelson@nrc.gov)
- Chief, PLB IV, DORL, NRR (Michael.Markley@nrc.gov)
- NRR Project Manager (Kaly.Kalyanam@nrc.gov)
- RidsNrrDirslpab Resource@nrc.gov
- Congressional Affairs Officer (Jenny.Weil@nrc.gov)
- mortensengk@INPO.org

SUNSI Review Completed: MCH ADAMS: Yes No Initials: MCH
 Publicly Available Non-Publicly Available Sensitive Non-Sensitive
 R:\ EOC and Midcycle\Midcycle Assessment Letters\Songs.doc

RIV C-DRP/D	D-DRS	D-DRP	DRA	RA
MCHay	RCaniano	DChamberlain	CCasto	ECollins
8/18/2009	8/19/2009	8/20/2009	8/1/2009	8/1/2009

OFFICIAL RECORD COPY T-TELEPHONE E=EMAIL F=FAX

San Onofre
Inspection / Activity Plan
09/01/2009 - 12/31/2010

Unit Number	Planned Dates Start End	Inspection Activity	Title	No. of Staff on Site
2	09/27/2009 12/31/2009	SGR-J2 IP 50001	- STEAM GENERATOR REPLACEMENT - UNIT 2 Steam Generator Replacement Inspection	1
2,3	08/24/2009 09/04/2009	EB1-17T IP 7111117T	- 50.59 & MODS Evaluations of Changes, Tests, or Experiments and Permanent Plant Modifications	3
2,3	09/21/2009 09/25/2009	EP1 IP 2515/175	- EP EXERCISE Emergency Response Organization, Drill/Exercise Performance Indicator, Program Review	4
2,3	09/21/2009 09/25/2009	IP 7111401	Exercise Evaluation	
2,3	09/21/2009 09/25/2009	IP 7111404	Emergency Action Level and Emergency Plan Changes	
2,3	09/21/2009 09/25/2009	IP 71151-EP01	Drill/Exercise Performance	
3	10/19/2009 11/27/2009	EB1-08P IP 2515/172	- U2 INSERVICE INSPECTION Reactor Coolant System Dissimilar Metal Butt Welds	1
3	10/19/2009 11/27/2009	IP 7111108P	Inservice Inspection Activities - PWR	
2	10/19/2009 10/30/2009	EXAM X02416	- INITIAL EXAM INITIAL EXAM UNIT 2-SANO (10/2009)	6
3	10/19/2009 10/30/2009	X02417	INITIAL EXAM UNIT 3-SANO (10/2009)	
2,3	10/26/2009 10/30/2009	RP-ORSS IP 7112101	- OCCUPATIONAL RADIATION SAFETY - ALARA Access Control to Radiologically Significant Areas	1
2,3	10/26/2009 10/30/2009	IP 7112102	ALARA Planning and Controls	
2,3	10/26/2009 10/30/2009	IP 71151	Performance Indicator Verification	
2,3	02/08/2010 02/12/2010	PSB2-52B IP 71152B	- BIENNIAL PI&R Identification and Resolution of Problems	5
2,3	02/22/2010 02/26/2010	IP 71152B	Identification and Resolution of Problems	
2,3	05/10/2010 05/14/2010	RP-ORS1 IP 7112101	- OCCUPATIONAL RADIATION SAFETY - ALARA Access Control to Radiologically Significant Areas	1
2,3	05/10/2010 05/14/2010	IP 7112102	ALARA Planning and Controls	
2	05/10/2010 05/14/2010	IP 71151-OR01	Occupational Exposure Control Effectiveness	
3	05/10/2010 05/14/2010	IP 71151-PR01	RETS/ODCM Radiological Effluent	
2,3	06/14/2010 06/18/2010	EB2-05T IP 7111105T	- TRIENNIAL FIRE PROTECTION Fire Protection [Triennial]	4
2,3	06/28/2010 07/02/2010	IP 7111105T	Fire Protection [Triennial]	
2,3	08/16/2010 08/20/2010	RP TEAM IP 2515/173	- RADIATION SAFETY TEAM INSPECTION Review of the Implementation of the Industry Ground Water Protection Voluntary Initiative	4
2,3	08/16/2010 08/20/2010	IP 7112103	Radiation Monitoring Instrumentation and Protective Equipment	
2,3	08/16/2010 08/20/2010	IP 7112201	Radioactive Gaseous and Liquid Effluent Treatment and Monitoring Systems	
2,3	08/16/2010 08/20/2010	IP 7112202	Radioactive Material Processing and Transportation	

This report does not include INPO and OUTAGE activities.
This report shows only on-site and announced inspection procedures.

San Onofre
 Inspection / Activity Plan
 09/01/2009 - 12/31/2010

Unit Number	Planned Dates Start End	Inspection Activity	Title	No. of Staff on Site
RP TEAM - RADIATION SAFETY TEAM INSPECTION				
2, 3	08/16/2010 08/20/2010	IP 7112203	Radiological Environmental Monitoring Program (REMP) And Radioactive Material Control Program	4
2, 3	08/16/2010 08/20/2010	IP 7113011	Material Control and Accounting (MC&A)	
EXAM - INITIAL EXAM				
2	09/20/2010 09/25/2010	X02445	INITIAL EXAM-SONGS (10/2010)	6
3	09/20/2010 09/25/2010	X02446	INITIAL EXAM UNIT 3-SONGS (10/2010)	
2	10/18/2010 10/29/2010	X02445	INITIAL EXAM-SONGS (10/2010)	
3	10/18/2010 10/29/2010	X02446	INITIAL EXAM UNIT 3-SONGS (10/2010)	
RP-ORS1 - OCCUPATIONAL RADIATION SAFETY				
2, 3	09/27/2010 10/01/2010	IP 7112101	Access Control to Radiologically Significant Areas	1
2, 3	09/27/2010 10/01/2010	IP 7112102	ALARA Planning and Controls	
2, 3	09/27/2010 10/01/2010	IP 71151-OR01	Occupational Exposure Control Effectiveness	
2, 3	09/27/2010 10/01/2010	IP 71151-PR01	RETS/ODCM Radiological Effluent	
EB1-08P - INSERVICE INSPECTION - U3				
3	10/12/2010 10/22/2010	IP 2515172	Reactor Coolant System Dissimilar Metal Butt Welds	3
3	10/12/2010 10/22/2010	IP 7111108P	Inservice Inspection Activities - PWR	
EP-1 - BIENNIAL EP PROGRAM INSPECTION				
2, 3	11/15/2010 11/19/2010	IP 7111402	Alert and Notification System Testing	1
2, 3	11/15/2010 11/19/2010	IP 7111403	Emergency Response Organization Augmentation Testing	
2, 3	11/15/2010 11/19/2010	IP 7111404	Emergency Action Level and Emergency Plan Changes	
2, 3	11/15/2010 11/19/2010	IP 7111405	Correction of Emergency Preparedness Weaknesses and Deficiencies	
2, 3	11/15/2010 11/19/2010	IP 71151-EP01	Drill/Exercise Performance	
2, 3	11/15/2010 11/19/2010	IP 71151-EP02	ERO Drill Participation	
2, 3	11/15/2010 11/19/2010	IP 71151-EP03	Alert & Notification System	
BRQ - OPERATOR REQUAL INSPECTION				
2, 3	11/01/2010 11/05/2010	IP 7111111B	Licensed Operator Requalification Program	3

This report does not include INPO and OUTAGE activities.
 This report shows only on-site and announced inspection procedures.