

September 3, 2009 USNRC Document Control Desk Washing ton DC 20555-0001

REPLY TO A NOTICE OF VIOLATION

Docket No. 030-32304 License No. 43-27362 -01

To whom it may concern:

Following is the answer to NOV dated July 23, 2009:

1. Reason for the violation;

Failure by the responsible Radiographer to record the physical survey of the restricted area.

The area was roped and the proper signs were in place and the survey was completed by the Assistant Radiographer but was not recorded.

This and other discrepancies were a pattern for this Radiographer. He was only with us for about three months.

2. Action to prevent recurrence;

Additional emphasis on the importance of following **ALL** the radiation safety rules including the records, This emphasis has been ongoing in our safety meetings.

3.Full compliance was achieved in May of 2008 with the termination of the above referenced Radiographer with an occasional unintentional omission due to human error.

Sincerely.

glas R. Johnston

HSO des la contra e la contra ménina a contra ménina de la contra por contra de la contra de la contra a contra Suest

Failure by the responsible fladlographer to record the planted survey of the reservice.

F(S)

The action we are related to

化二乙基苯基乙基苯基磺基乙基基乙基乙基乙基乙基乙基乙基

Nondestructive Testing Laboratories & Training Center 369 West Gregson Avenue; Salt Lake City, Utah 84115; (801)487-0801; Fax (801)466-8790