



(a)




(b)




(c)


Figure 2-9. Examples of lack of salt deposit in the manifold after running at 105°C. Salt deposits were not observed. Time of failure was indicated by ball drop for all failed specimens.



(a)



(b)



(c)

Figure 2-10. Fracture morphology for Alloy 22. (a) tensile test in 125°C air, (b) and (c) Keno specimen (overload) failures from Keno Run 1. No indication of SCC was observed. Note that magnification of image in (a) is larger than (b).