



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
612 EAST LAMAR BOULEVARD, SUITE 400  
ARLINGTON, TEXAS 76011-4125

September 28, 2009

Cardiovascular Institute, PC  
ATTN: Romeo A. Pavlic, M.D.  
10 N. Post Street #642  
Spokane, Washington 99219

SUBJECT: APPLICATION FOR A NEW LICENSE

The U.S. Nuclear Regulatory Commission (NRC) received by facsimile your application for a new medical use license on September 17, 2009 followed by the original application received by regular mail on September 21, 2009. NRC performed a cursory review of the application to determine if it met minimum acceptable criteria for docketing. The application was not submitted in accordance with NRC's guidance document NUREG-1556, Volume 9, revision 2, and contained several deficiencies. These deficiencies impede the docketing, review and processing of your license application. Your legal counselor, Brent Stanyer, was notified by electronic mail on September 17, 2009 of these deficiencies and an explanation was provided on how to correct them. You were also notified of these deficiencies by electronic mail on September 21, 2009. On September 25, 2009, the NRC received by facsimile a re-submittal of your license application that still did not address the deficiencies originally identified in electronic mails dated September 17 and 21, 2009.

Please complete the following steps to allow NRC to docket your new license application.

1. Submit to this office the required license application fee of \$2,300. For your convenience, I have enclosed NRC Form 629 (credit card payment authorization form). An alternative is to make payment by check and mail it to this office.
2. Complete Appendix C of NUREG-1556, Volume 9, revision 2, to provide the additional information needed for items 5 through 11 of NRC Form 313 dated August 27, 2009 that was submitted with the license application. NUREG-1556, Volume 9, revision 2 can be found at the following website address:  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1556/v9/r2/>
3. Contact Insight Diagnostic Imaging and request that they submit to this office a license termination request for NRC License Number 11-29290-01 using the enclosed NRC Form 314.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>.

Cardiovascular Institute, PC

-2-

You can contact me at 817-860-8189 if you have any questions about the license application process.

Thank you for your cooperation.

Sincerely,

**/RA/**

Roberto J. Torres, Senior Health Physicist  
Nuclear Materials Safety Branch B

Enclosures: As stated