



REGION I  
475 ALLENDALE ROAD  
KING OF PRUSSIA, PENNSYLVANIA 19406-1415

September 28, 2009

Docket No. 03012498

License No. 47-17282-01

Yong K. Park, Ph.D.  
Radiation Safety Officer/Authorized Medical Physicist  
Ohio Valley Medical Center  
2000 Eoff Street  
Wheeling, WV 26003-3870

SUBJECT: NRC INSPECTION REPORT NO. 03012498/2009001, OHIO VALLEY MEDICAL CENTER

Dear Dr. Park:

This letter refers to your September 3, 2009, correspondence indicating that you identified an error in NRC Inspection Report No. 03012498/2009001. You stated that you performed timer linearity checks over a range of five minutes contrary to the statement made in the inspection report that linearity was performed to two minutes. Thank you for this additional information. We will add it to the docket for Ohio Valley Medical Center. Please note that this information does not change the results of the inspection since 10 CFR 35.633(b)(5) requires that full calibration measurements of a remote afterloader unit for medical use include determination of timer accuracy and linearity over the typical range of use, which in the case of your facility is ten minutes.

Your cooperation with us is appreciated.

Sincerely,

***Original signed by Pamela Henderson***

Pamela Henderson, Chief  
Medical Branch  
Division of Nuclear Materials Safety

cc:  
Bernie Albertini, Assistant Administrator  
State of West Virginia

September 28, 2009

Docket No. 03012498

License No. 47-17282-01

Yong K. Park, Ph.D.  
Radiation Safety Officer/Authorized Medical Physicist  
Ohio Valley Medical Center  
2000 Eoff Street  
Wheeling, WV 26003-3870

SUBJECT: NRC INSPECTION REPORT NO. 03012498/2009001, OHIO VALLEY MEDICAL CENTER

Dear Dr. Park:

This letter refers to your September 3, 2009, correspondence indicating that you identified an error in NRC Inspection Report No. 03012498/2009001. You stated that you performed timer linearity checks over a range of five minutes contrary to the statement made in the inspection report that linearity was performed to two minutes. Thank you for this additional information. We will add it to the docket for Ohio Valley Medical Center. Please note that this information does not change the results of the inspection since 10 CFR 35.633(b)(5) requires that full calibration measurements of a remote afterloader unit for medical use include determination of timer accuracy and linearity over the typical range of use, which in the case of your facility is ten minutes.

Your cooperation with us is appreciated.

Sincerely,

***Original signed by Pamela Henderson***

Pamela Henderson, Chief  
Medical Branch  
Division of Nuclear Materials Safety

cc:  
Bernie Albertini, Assistant Administrator  
State of West Virginia

DOCUMENT NAME: G:\WordDocs\Current\Insp Letter\L47-17282-01.2009001.doc

**SUNSI Review Complete: JNguyen**

After declaring this document "An Official Agency Record" it will be released to the Public.

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy ML092720134

OFFICE	DNMS/RI	N	DNMS/RI	N	DNMS/RI			
NAME	JNguyen/JN		PHenderson/PJH					
DATE	9/28/09		9/28/09					

OFFICIAL RECORD COPY