

NRC FORM 591M PART 1
(4-2008)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Colby & Thielmeier Testing Company, Inc. 10625 Liberty Avenue St. Louis, MO REPORT NUMBER(S) 2009-001		2. NRC/REGIONAL OFFICE REGION III US NUCLEAR REGULATORY COMMISSION 2443 WARRENVILLE ROAD STE 210 LISLE IL 60532-4352	
3. DOCKET NUMBER(S) 03005159	4. LICENSE NUMBER(S) 24-13737-01	5. DATE(S) OF INSPECTION 9/21-23/2009	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Condition 12 of NRC License No. 24-13737-01 named an individual as the Radiation Safety Officer (RSO). However, from December 16, 2008, to August 25, 2009, an individual other than the individual named in Condition 12 of the license served as the licensee's RSO.

As corrective action, the licensee committed to ensure that it promptly requests future license amendment requests to change the individual named as the RSO on the license to ensure that new RSOs are authorized on the license before they begin to serve as the RSO. The licensee also committed to ensure that, if its authorized RSO leaves the licensee's employ on short notice, it will promptly notify the NRC of the situation and promptly request a license amendment to authorize the new RSO on the license.

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE	Stephen Thielmeier	<i>Stephen Thielmeier</i>	9/24/09
NRC INSPECTOR	Robert G. Gattone, Jr.	<i>Robert G. Gattone, Jr.</i>	9/24/09

Part 4 Jm