

Eastern Connecticut Cardiology Group
481 Gold Star Highway, Suite 101
Groton, CT 06340
(860) 437-6785
(860) 446-2535 (Fax)

Br 2

November 9, 2009

Licensing Assistance Section
Nuclear Medicine Safety Branch
Division of Radiation Safety and Safeguards
U.S. Nuclear Regulatory Commission, Region I
475 Allendale Road
King of Prussia, PA 19406-1415

RECEIVED
REGION 1
2009 NOV 16 PM 12: 23

RE: License Number: 06-30826-01
Amendment Application
Eastern Connecticut Cardiology Group

03036292

Dear License Reviewer:

We request our radioactive material license be amended to reflect the following changes:

1. We request our radioactive material license be amended to add an additional "Location of Use". The address of the new facility is provided below:

Eastern Connecticut Cardiology Group
196 Parkway South, Suite 103
Waterford, CT 06385

A diagram of the nuclear cardiology department is provided within Attachment A. Please refer to the Attachment Section for details. In addition, Attachment A includes an "Equipment List" for the hot lab and imaging area.

2. Please amend our radioactive material license to change the administrative mailing address to:

Eastern Connecticut Cardiology Group
196 Parkway South, Suite 103
Waterford, CT 06385
(860) 437-6748
(860) 443-3980 (Fax)


144295
NRC REGIONAL MATERIALS-002

This imaging center is a new location. Radioactive materials have never been used at this imaging center.

If you have additional questions, please contact Michael W. Lairmore, M.S. or myself. Mr. Lairmore may be contacted at (201) 693-2277.

We thank you in advance for your assistance with this licensing action.


Sincerely,

A handwritten signature in black ink, reading "Tracey Gomes-Johnson". The signature is fluid and cursive, with the first name "Tracey" and last name "Johnson" clearly legible.

Tracey Gomes-Johnson
Practice Administrator

Attachment A

Eastern Connecticut Cardiology Group
196 Parway South, Suite 103
Waterford, CT 06385



Legend:

1. NMIS Computer
2. L-Shield/Preparation Area/ E-Vial Storage (1/4" lead lining)
3. Dose Calibrator
4. Flood Disk Storage
5. Well Counter
6. Package Receipt/Return Area
7. Waste Storage Area (1/8" lead lining)
- *** Locked Door

Areas Surrounding the Nuclear Cardiology Department:

- A. To the south of the imaging center resides the main office area.
- B. To the west and east of the nuclear cardiology department resides professional office suites
- C. To the north of the nuclear cardiology department lies the parking lot.
- D. Professional office suite reside above the department.
- E. Below the nuclear cardiology department is the building foundation.

Equipment List

1. Philips Cardio MD Imaging System
2. Capintec CAPRAC Wipe Test Counter
3. Capintec CRC-15R dose calibrator
4. Ludlum 14C survey meter with pancake probe (x2)

This is to acknowledge the receipt of your letter/application dated

11/9/09, and to inform you that the initial processing which includes an administrative review has been performed.

☒ Amendment (06-30826-01)
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

☐ Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 144295.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.