

**The date for this document is December 1, 2009**



Flow Control

David E. Tuttle  
QA Manager

Tyco Flow Control  
Anderson Greenwood Crosby  
43 Kendrick Street  
Wrentham, MA 02093 U.S.A.

Tele: 508-384-4640  
Fax: 508-384-7984

e-mail: dtuttle@tycovalves.com

REPLY TO A NOTICE OF NONCONFORMANCE

October 16, 2009

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

Subject: Reply to Notice of Nonconformance  
NRC Inspection Report No. 99900293/2009-201  
Nonconformance 99900293/2009-201-02, -03 and -04

Dear Sir:

The notice of violation and notice of nonconformances (letter dated September 16, 2009) as a result of Inspection Report No. 99900293/2009-201, requires a written statement or explanation within 30 days of the date of the letter. AG Crosby responded to the notice of violation on October 13, 2009. However, we do not have time to also respond to the notice of nonconformances within the specified time frame, and request an extension of the response time.

We request the extension based on the amount of work involved. There are 3 nonconformances, and 2 to 3 issues within each nonconformance to respond to. We request an additional 30 days to complete our analysis of the root cause and decide on the proper corrective steps to be taken for the identified nonconformances.

We expect to complete our analysis, and respond accordingly, well within the next 30 days.

Sincerely,

David E. Tuttle  
Quality Assurance Manager  
Anderson Greenwood Crosby

cc: Juan Peralta, Chief  
Quality and Vendor Branch 1  
Division of Construction Inspection  
& Operational Programs  
Office of New Reactors