

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Acuren USA Prudhoe Bay, Alaska, Drop Point P-70, and temporary job sites, Prudhoe Bay, Alaska		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 612 East Lamar Blvd, Suite 400 Arlington, Texas 76011-4125	
REPORT NO: 2009-002			
3. DOCKET NUMBER 030-36217	4. LICENSE NUMBER 42-32443-01	5. DATES OF INSPECTION 9/23/09 – 12/7/09	

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.


3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Jason M. Razo		12/7/09

TRANSMISSION VERIFICATION REPORT

TIME : 12/07/2009 10:05
NAME : NRC RIV
FAX : 8178608188
TEL : 8178608100
SER.# : BRDJ4J117485

DATE, TIME	12/07 10:05
FAX NO./NAME	712818423370
DURATION	00:00:40
PAGE(S)	02
RESULT	COVERPAGE
MODE	OK
	STANDARD
	ECM



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
612 EAST LAMAR BLVD, SUITE 400
ARLINGTON, TEXAS 76011-4125

F A C S I M I L E

Name:	Gayle Staton	License No.:	42-32443-01
Licensee:	Acuren USA	Docket No.:	030-36217
Fax No.:	281-842-3370		
Phone No.:	281-228-0000		
From:	Jason Razo		
Date:	12/7/09		
Subject:	Clear Inspection Report, NRC Form 591M Part1		
Pages:	1 + transmittal sheet		

Miss Staton,

I am faxing you an NRC Form 591M inspection report which documents the inspection performed by myself, conducted at your facilities in Prudhoe Bay, Alaska. No response or signature on your part is required. Please maintain the report for your records. If you have any questions about the inspection or the 591M please call me at 817-276-6589.

Jason M. Razo
Materials Inspector
Nuclear Materials Safety Branch A