

POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE NEW YORK, N. Y. 10019

(212) 397-6200

TRUSTEES

FREDERICK R. CLARK
CHAIRMAN

GEORGE L. INGALLS
VICE CHAIRMAN

RICHARD M. FLYNN

ROBERT I. MILLONZI

WILLIAM F. LUDDY



April 24, 1979
IPN-79-19

GEORGE T. BERRY
EXECUTIVE DIRECTOR
LEWIS R. BENNETT
GENERAL COUNSEL AND
ASSISTANT EXECUTIVE
DIRECTOR
JOSEPH R. SCHMIEDER
CHIEF ENGINEER
JOHN W. BOSTON
DIRECTOR OF
POWER OPERATIONS
THOMAS F. McCRANN, JR.
CONTROLLER

Director, Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. Albert Schwencer, Chief
Operating Reactor Branch No. 1
Division of Operating Reactors


Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286

Dear Sir:

On November 21, 1978 (IPO-173), the Authority transmitted to you forty (40) copies of a report prepared by the Westinghouse Electric Corporation on the subject facility concerning fracture toughness and the potential for lamellar tearing of steam generator and reactor coolant pump support materials.

Enclosed is a letter NS-RAW-093, dated April 10, 1979 from Westinghouse requesting that the document previously submitted to you be withheld from public disclosure as it contains Westinghouse proprietary information.

Very truly yours,


Paul J. Early
Assistant Chief Engineer-
Projects

ADD:
H. SMITH
w/ENCL

7904270 342