

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



November 14, 1979
IP-KRC-6176

Docket No. 50-286
License No. DPR-64

Boyce H. Grier, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Tube Plugging of Indian Point
Unit No. Three Steam Generators

Dear Mr. Grier:

This report is submitted in accordance with the requirement of Technical Specification 4.9.C relating to Steam Generator Tube Plugging.

As a result of our inservice inspection of the steam generators during the second refueling outage, and based on the recommendations from Westinghouse, the following number of tubes were plugged:

Steam Generator No. 31
97 Tubes


Steam Generator No. 32
111 Tubes

Steam Generator No. 33
113 Tubes

Steam Generator No. 34
114 Tubes

Complete details of the tube plugging program will be contained in the annual steam generator tube inservice inspections report.

Very truly yours,


J. P. Bayne
Resident Manager

App
11/10

KRC/bam

cc: Director, Office of Inspection and Enforcement
c/o Distribution Services Branch, DDC, ADM
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

7911200520