

POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE NEW YORK, N. Y. 10019

(212) 397-6200

TRUSTEES

JOHN S. DYSON
CHAIRMAN

GEORGE L. INGALLS
VICE CHAIRMAN

RICHARD M. FLYNN

ROBERT I. MILLONZI

FREDERICK R. CLARK



January 22, 1980

IPN-80-7

GEORGE T. BERRY
PRESIDENT & CHIEF
OPERATING OFFICER

JOHN W. BOSTON
EXECUTIVE VICE
PRESIDENT & DIRECTOR
OF POWER OPERATIONS

JOSEPH R. SCHMIEDER
EXECUTIVE VICE
PRESIDENT & CHIEF
ENGINEER

LEROY W. SINCLAIR
SENIOR VICE PRESIDENT
& CHIEF FINANCIAL
OFFICER

THOMAS R. FREY
SENIOR VICE PRESIDENT
& GENERAL COUNSEL

Director of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. Albert Schwencer, Chief
Operating Reactors Branch No. 1
Division of Operating Reactors

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
Fire Protection Program Review

- References: (1) IPO-125, Early to Stello, dated June 29, 1978
(2) IPN-79-2, Early to Schwencer, dated
February 6, 1979
(3) IPN-79-84, Early to Schwencer, dated
November 26, 1979

Dear Sir:

In Reference (1), in response to Question 7 of your April 26, 1978 request for additional information on the subject item, the Authority provided a list of ventilation ducts/louvers that were to be provided with fire dampers (see pages 7-1 through 7-3). In Reference (2), in response to Question 3 of your November 28, 1978 request for additional information on the subject item, the Authority provided a revised page 7-3 of Reference (1) and a listing of six ducts/louvers that were included on that page that did not require fire dampers. In order to eliminate any confusion as to what the Authority's commitment is with respect to these ducts/louvers, we are herewith providing as Attachment 1 and 2 respectively, a revised response to Question 7 of Reference (1) and Question 3 of Reference (2).


In Reference (3), the Authority provided a revised response to Question 11 of Enclosure 1 of your September 29, 1978 letter request for information on the subject item. The Authority is

A006
S
1/1

F 8001280 375

herewith providing as Attachment 3 a revised response to this question to include a fire damper in section 11.g that was specifically identified in Amendment No. 24 to the Indian Point 3 facility Operating License, but was inadvertently omitted from this listing. This omission was discovered by the Office of Inspection and Enforcement Inspection 50-286/79-12 conducted at the facility on August 20-22, 1979 (Unresolved Item 79-12-06). This information should permit the item 79-12-06 to be closed.

Very truly yours,



Paul J. Early
Assistant Chief Engineer-Projects

cc: Mr. Theodore A. Rebelowski
Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, New York 10511

ATTACHMENT 1

REVISED RESPONSE TO QUESTION 1
OF NRC'S REQUEST OF APRIL 26, 1978
FOR ADDITIONAL INFORMATION ON FIRE PROTECTION
PROGRAM REVIEW

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT 3 NUCLEAR POWER PLANT
DOCKET NO. 50-286
JANUARY 11, 1980