

POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE

NEW YORK, N.Y. 10019

(212) 397-6200

TRUSTEES

JOHN S. DYSON  
CHAIRMAN

GEORGE L. INGALLS  
VICE CHAIRMAN

RICHARD M. FLYNN

JAMES L. LAROCCA

ROLLAND E. KIDDER



LEROY W. SINCLAIR  
PRESIDENT & CHIEF  
OPERATING OFFICER

WALTER T. KICINSKI  
FIRST EXECUTIVE  
VICE PRESIDENT &  
CHIEF ADMINISTRATIVE  
OFFICER

JOSEPH R. SCHMIEDER  
EXECUTIVE VICE  
PRESIDENT & CHIEF  
ENGINEER

STEPHEN L. BAUM  
SENIOR VICE PRESIDENT  
& GENERAL COUNSEL

May 16, 1983  
IPN-83-40

Director of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Attention: Mr. Steven A. Varga, Chief  
Operating Reactors Branch No. 1  
Division of Licensing


Subject: Indian Point.3 Nuclear Power Plant  
Docket No. 50-286  
Fracture Mechanics Analysis

Dear Sir:

The attachment to our letter of April 28, 1983 (IPN-83-30) served to place the second revision of a report entitled, "Fracture Mechanics Analysis of the Indian Point Unit 3 Nuclear Generating Station Steam Generator Girth Weld Cracks Under Pressurized Thermal Shock Conditions" (Non-Proprietary) onto our docket. This letter serves to place the third revision of this report, attached, onto our docket. The revisions appear on pages 4-6, 4-6a, 4-6b, 4-8, 4-8a, and are indicated by a bar in the right hand margin.

Should you or your staff have any questions regarding this matter, please contact Mr. P. Kokolakis of my staff.

Very truly yours,

  
J. P. Bayne  
Executive Vice President  
Nuclear Generation

JPB/PK/sg

cc: Resident Inspector's Office  
Indian Point Unit 3  
U. S. Nuclear Regulatory Commission  
P. O. Box 66  
Buchanan, New York 10511

A001

8305200405 830516  
PDR ADDCK 05000286  
P PDR