

UNITED STATES GOVERNMENT

Memorandum

TO : Eber R. Price, Assistant Director
Division of Licensing and Regulation
Headquarters

DATE: December 11, 1962

FROM : Eugene J. Moretto, Radiation Specialist (Review)
Region III, Division of Compliance, Chicago

SUBJECT: INSPECTION REPORT - GENERAL STEEL INDUSTRIES,
GRANITE CITY, ILLINOIS : LICENSE NO. 12-8271-1

CO:III:EJO

Enclosed is inspection report for General Steel Industries of Granite City, Illinois, License No. 12-8271-1.

Based on the information obtained and by observation at the time of the inspection, the AEC representative found four items of noncompliance. The licensee was in violation against Section 20.201(b) for failure to make an adequate survey of radiography facility; against Section 31.104 for failure to calibrate his survey meters at intervals of three months; against 31.105 for failure to leak test his two Cobalt-60 sealed sources at intervals of six months; and against 31.106 for failure to maintain inventories on a quarterly basis.


These violations were brought to the attention of Mr. Robert Ripley, Assistant Metallurgist and the individual responsible for the radiography program. He advised the AEC representative that immediate action would be taken to correct all violation noted.

In evaluating this radiography program, there does not appear to be any serious deficiencies which would warrant a follow-up inspection. Therefore, a follow-up inspection is not planned. The items of noncompliance will be reviewed at the next scheduled re-inspection.

All correspondence regarding the existing violations should be addressed to Mr. Robert Ripley.

Enclosure:
Inspection Report (1 cy.)

cc: Division of Compliance HQ - w/encl. (orig.)



A/G